

# AX5043 ERRATA

---

## Errata Silicon Errata for AX5043

2015–December–10



**ON Semiconductor®**

[www.onsemi.com](http://www.onsemi.com)

---

### Introduction

This document lists silicon erratas, as well as features of the AX5043 that may be unexpected to the user.

The issues listed in this document are for the silicon revisions listed in the table below.

**Table 1.**

Revision	REVISION Register
V1	0x51

### Issues

#### *Radio Controller may not Properly Release FIFO Read or Write Port*

When the AX5043 is directly switched from receive to transmit without powering down, the radio controller may under some circumstances not properly release the FIFO write port, thereby preventing SPI writes to the FIFO. When switching from transmit to receive without powering down, the radio controller may under some circumstances not properly release the FIFO read port, thereby preventing SPI reads from the FIFO.

Workaround: Write a second time a different value to the PWRMODE register. For example, when changing from receive to transmit mode, do the following:

1. Write 0x05 to PWRMODE to turn off the receiver
2. Write 0x07 to PWRMODE to release FIFO ports and to make sure the FIFO is enabled
3. Fill FIFO
4. Write 0x0D to PWRMODE to start transmission

Affected Revisions: V1

#### *Zero Length Payload Packets with Hardware Address Matching and CRC*

Packets where the hardware matched address is immediately followed by the hardware checked CRC are dropped, even if the CRC is correct.

Workarounds:

1. The transmitter may insert a padding byte between address and CRC
2. Shorten the AX5043 hardware matched address by one byte, and check the last byte in software
3. Check the CRC in software

Affected Revisions: V1

#### *Gaussian Frequency Shift Keying (GFSK)*

GFSK works as expected between AX5043 devices with both settings (BT = 0.3 and BT = 0.5). Both settings comply with transmission regulations. However, the AX5043 uses a slightly different shaping function than many non-ON Semiconductor chips, that may cause these chips to have difficulties receiving AX5043 transmissions. In this case, it is recommended to use the BT = 0.3 setting for the AX5043 and a BT = 0.5 setting for the non-ON Semiconductor chip.

Affected Revisions: V1

# AX5043 ERRATA

ON Semiconductor and the  are registered trademarks of Semiconductor Components Industries, LLC (SCILLC) or its subsidiaries in the United States and/or other countries. SCILLC owns the rights to a number of patents, trademarks, copyrights, trade secrets, and other intellectual property. A listing of SCILLC's product/patent coverage may be accessed at [www.onsemi.com/site/pdf/Patent-Marking.pdf](http://www.onsemi.com/site/pdf/Patent-Marking.pdf). SCILLC reserves the right to make changes without further notice to any products herein. SCILLC makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does SCILLC assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation special, consequential or incidental damages. "Typical" parameters which may be provided in SCILLC data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. SCILLC does not convey any license under its patent rights nor the rights of others. SCILLC products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the SCILLC product could create a situation where personal injury or death may occur. Should Buyer purchase or use SCILLC products for any such unintended or unauthorized application, Buyer shall indemnify and hold SCILLC and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that SCILLC was negligent regarding the design or manufacture of the part. SCILLC is an Equal Opportunity/Affirmative Action Employer. This literature is subject to all applicable copyright laws and is not for resale in any manner.

## PUBLICATION ORDERING INFORMATION

### LITERATURE FULFILLMENT:

Literature Distribution Center for ON Semiconductor  
19521 E. 32nd Pkwy, Aurora, Colorado 80011 USA  
**Phone:** 303-675-2175 or 800-344-3860 Toll Free USA/Canada  
**Fax:** 303-675-2176 or 800-344-3867 Toll Free USA/Canada  
**Email:** [orderlit@onsemi.com](mailto:orderlit@onsemi.com)

**N. American Technical Support:** 800-282-9855 Toll Free  
USA/Canada  
**Europe, Middle East and Africa Technical Support:**  
Phone: 421 33 790 2910  
**Japan Customer Focus Center**  
Phone: 81-3-5817-1050

**ON Semiconductor Website:** [www.onsemi.com](http://www.onsemi.com)  
**Order Literature:** <http://www.onsemi.com/orderlit>  
For additional information, please contact your local  
Sales Representative