Each Strata platform requires validation before releasing to production. These tests can range from simply installing Strata and ensuring the evaluation board is detectable to using lab equipment to facilitate proper functionality.

| Test | Instructions | | Pass Condition |
|--------------------------------|---|---|---|
| One Time Tests | me Tests These tests only need to be done one time per OPN. | | |
| Strata Version Confirmation | 1) Ensure Strata version is appropriate for validation 2) Open Strata and Login > Click the profile letter "X" > About 3) Version 2.1.0 or later is required a) If version is out of date, install the <u>newest Strata release</u> b) If the newest version not new enough, contact SEC for a Beta release | | U Version 2.1.0 o |
| Strata Platform Selector | Open Strata and Login On "Platform Selection" tab find the STR OPN in this list. a) STR-SENSORS-GEVK Select "Browse Documentation" | | Ensure all OPN At least one do "Platform Doc Datasheets" all |
| Setup | Install "Hello Strata Utils" using the newest Hello Strata installer here a) \\usbserv1\deployment\hello_strata ONLY REQUIRED TO INSTALL THE FOLLOWING!! See picture to right. a) JLink b) Platform Registration Tool c) Serial Console Interface | Hello Strata Setup Select Components Please select the components you want to install. Default Select All Deselect All Hello Strata Application development reposit Docker for Windows GNU Arm Embedded Toolchain Git Bash Hello Strata Build Image JLink Ulink Microsoft Visual Studio Code Hello Strata Uli Gextra Ulis Ecouchbase Browser Zerial Console Interface | Installation co |
| Platform Registration Tool | Ensure "Setup" section was completed. Those instructions only need to be repeated if the "Hello Strata Utils" are not installed. Connect the EVB as shown in the picture to the right Open the "Platform Registration Tool" application Per OPN, download the .bin file from Strata's "Platform Documents" > "Downloads" section Browse to the downloaded .bin file in the "Firmware data file" browse "Select" dialog Click "Begin" Ensure programming was successful Repeat steps 1) through 5) for the remaining boards before continuing to next step. Note: simply unplug JLink and platform and plug into another and the flash will start automatically. | | Flash was succ Programmin To program another du new process with or pr |
| Serial Console Interface | Open the "Serial Console Interface" application and execute the following command {"cmd":"set_platform_id","payload":{"platform_id":"","class_id":"72ddcc10-2d18-4316-8170-52 | 223162e54cf","board_count":0}} | Command stat |
| | 2) Repeat steps 1) through 5) for the remaining boards before continuing to next step | | |

.0 or later is installed

OPN is in the "Platform Selection" list e document is shown on "Platform Content" tab under ocuments" and optionally documents displayed on "Part and "Downloads"

completed

uccessful

ning successful



r device, simply plug it in and will start automatically

r press End.

status is "OK"

| | | 19:04:29.217 ℃ ~ { "cmd": "s "palload" "plat "plat "clas) 19:04:29.458 ~ { 19:04:29.458 ~ { "ack": " |
|------------------|--|---|
| All Board Tests | Tests below this line must be done on every board. | |
| Strata Detection | Make sure to close "Serial Console Interface" Unplug mini USB cable from previous steps (see picture to right for reference to which USB cable). Open Strata and Login, you should see Platform Selection list Plug in board to computer using mini USB cable | Strata detects "Platform Cor The Touch tal |
| Touch Tab | 1) Touch the sensors 0 through 7 | LED on board |
| Proximity Tab | Click Proximity tab Hover finger approximately ½" above A, B, C, and D sensors | LED on board Activation and |
| Light Tab | Use finger to change to Light sensor by touching the "LIGHT" sensor show in the picture to the right Change gain from 8 to 0.25 Set the sensitivity to 140 using the slider | UI changes to In normal offi Aroun Aroun Sensitivity is of increase |
| Temperature Tab | 1) Click Temperature tab | |
| Temperature Tab | 1) Reduce the Remote THERM and Local THERM Limits to 0°C | |
| Temperature Tab | 1) Change the Range from 0-127°C to -64-191°C | |
| LC717A10AR Tab | 1) Click LC717A10AR tab 2) Disable CIN0 and CIN1 using the two Enable On/Off sliding buttons, see picture to right 3) Touch both CIN0 and CIN1 | CINO and CIN Threshold ind |
| LC717A10AR Tab | Click the Export Registers button Type a file name into the "File name" field and click Save Open that file in a text editor | There are two |

| ": "set_platform_id", load": { "platform.id": "", "class_id": "72ddc10-2d18-4316-8170-5223162e54cf", "board_count": 0 |
|---|
| ": "set_platform_id", load": { "return_value": true, "return_string": "command valid" |
| ification": { "value": "set_platform_id", "payload": £ "status": "OK" } |
| |
| ects board and user interface is automatically shown on Controls" tab tab is activated |
| ard next to each sensor is illuminated and Data indicators in Strata are activated per all 8 touches |
| ard next to each sensor is illuminated and Data indicators in Strata are activated per all 8 touches |
| to Light tab office lighting conditions the Lux value should read und 2000-4000 lx for gain of 8 und 100 lx for gain of 0.25 is coerced to 150 when set to 150 and Lux reading should |
| t 15 seconds the Remote Temperature should be around 40°C cal Temperature should be around 32°C and slowly increasing. |
| HRM, and LTHRM indicators in Strata should be lit up red |
| GH, and LHIGH indicators in Strata should be lit up red. Along M, RTHRM, and LTHRM indicators from previous step. |
| CIN1 LEDs on PCB do not illuminate and the Activation and indicators in Strata are not updated |
| wo lines of data exported in this file |