



PRODUCT BULLETIN # 20054

Generic Copy

Issue Date: 05-Apr-2013

TITLE: Announcement of character missing on MPN Label

AFFECTED PERIOD: Products shipped from factory from Feb 5 to Mar 24

AFFECTED CHANGE CATEGORY(S): Shipping - MPN Label

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor sales office or <quality@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

This is the notification regarding about a labeling issue that occurred during the "AFFECTED PERIOD" stated above. After this period, the label became normal (like the "Good MPN Label" example).

In this affected period, the following characters are missing due to the printing failure of MPN Label. There is no problem for other data at all.

The items which have missing characters of MPN Label are as follows;

1. Pb-Free
2. E-Category Value
3. China RoHS
4. ON Semi logo


Also, regarding the product, it complies with RoHS and China RoHS.

Example:

【Good MPN Label】



【Different MPN Label】



- | | | | |
|----------------|-----------------------|----------------------|-------------------|
| 1
Pb – Free | 2
E-Category Value | 3
China RoHS logo | 4
ON Semi logo |
|----------------|-----------------------|----------------------|-------------------|


PRODUCT BULLETIN #20054

Products list printed with the character missing on MPN Label

List of affected Generic Parts:

LA1140-E	LC74732W-9811-E	LC75842EHS-E	LC822973-10B-E
LA4192-E	LC74732WH-9811-E	LC75847T-E	LC823170PRA-4H
LA4422-E	LC74736PT-E	LC75852W-E	LC823416-10R3-H
LA4425A-E	LC74782M-9011-E	LC75857W-E	LC823425-12G1-H
LA4525-E	LC749000AT-8B15H	LC75874W-E	LC823425-13W1-E
LA4525-V-E	LC749880T-E	LC75878W-E	LC823425-14S1-E
LA4600-E	LC75411UES-E	LC75878WS-E	LC823430TA-2H
LA4627HK-E	LC75412EH-E	LC75884W-E	LC823431TAK-2H
LA5693D-N-E	LC75725E-E	LC75886PWH-H	LC82360-YJ2-E
LA6358NLL-E	LC75812PTH-8565-H	LC75890W-2H	LC850541-E
LA6458SL-E	LC75812PTS-8565-H	LC75897PW-E	LC87F2J32AU-QIP-E
LB11988-E	LC75813ES-E	LC78692NW-E	LC87F5JC8AU-QIP-E
LB1205-L-E	LC75813TS-E	LC7935AN-E	LC87F5NC8AVU-QIP-E
LB1423N-E	LC75821E-E	LC7935ANHS-E	LC89075WA-H
LB1641-E	LC75822W-E	LC79401D-E	LC89075W-H
LB1641L-E	LC75827W-E	LC7940KD-E	LE28F4001CTS12-MPB-E
LB1663-E	LC75827WS-E	LC7940ND-E	LV24250LS-MPB-E
LB1667-E	LC75827W-SH-E	LC7942KD-E	LV25400PNW-F-MPB-E
LB1668-A-E	LC75832W-E	LC79430D-E	LV25450PNW-F-MPB-E
LB1668-E	LC75833E-E	LC7981-E	LV4137W-MPB-E
LB1668-H	LC75834E-E	LC7985ND-8733-E	LV8044LP-MPB-H
LB1731-H-E	LC75834W-E	LC821033-E	LV8075LP-E
LC72717PW-H	LC75836W-E	LC821621-E	LV8411GR-E
LC74731W-9818-E	LC75836WH-E	LC82162B-R1000-E	LV8413GP-E
LC74731WS-9818-E	LC75842E-E	LC822973-10BA-E	LV8413GP-H

List of affected Customer Specific Parts:

LC01707LF-CL-MPB-H	LC72323N-9D35-E	LC786922E-01UM-E	LC878396PA-5BB5-E
LC21003B-Z92-E	LC72323Y-9C55N-E	LC786922E-01UY-E	LC878396PA-5BP5-E
LC22010C-YF4-E	LC72336-9C77-E	LC786924NT-US-H	LC878396PA-5BZ2-E
LC22017C-YF3-E	LC7234-8490-E	LC786925NW-US-H	LC8783C8PA-59H7-E
LC22031CT-PH6-E	LC723663-9D54-E	LC786927W-03DA-LR-H	LC8783C8PA-5AF0-E
LC24085BT-XJ5D-E	LC749402PT-UDE-H	LC786927W-03ED-LR-H	LC8783C8PA-5BT9-E
LC24108B-13C-H	LC749492PT-UCE-H	LC786927W-03KR-LR-H	LC8783G0PA-5BZ1-E
LC24108B-VH6-E	LC75031PW-6152-H	LC786950NT-US-H	LC8783M4PA-5BV0-E
LC24232B-YE4-E	LC75806PTS-T-UKP-H	LC786950T-US-H	LC8784P7PB-5BR9-E
LC27355CST-00M-E	LC75809PT-US-H	LC786953W-US-H	LC87F5JC8A-F5BK2-E
LC27356CSQ-00NB-E	LC75810T-8726-E	LC786954W-US-H	LC87F83P7PA-F5BW0-E
LC5872-1M24-E	LC75818PTH-8561-H	LC786960E-13UCSHLR-H	LC98300BT-09Y-E
LC6528N-4F50-E	LC75834JEHS-USL-E	LC786960E-15SM-LR-H	LC98300BT-ZD2-E
LC66404A-4K81-E	LC75857WH-SH-UC-E	LC786960PE-28SM-LR-H	LC98500BQ-07L-E
LC70301W-UIC-H	LC75857WH-UALP-E	LC786961W-16SM-LR-H	LC98500BT-UC5TD-E
LC70301W-UMK-H	LC75878WS-UYNS-E	LC786961W-19DA-LR-H	LC98500DT-04G-E
LC70310KBG-UDS-H	LC75878W-UALP-E	LC786961W-20FY-LR-H	LC98600CQ-01N-E
LC703200AW-8C01-H	LC75879PT-US-H	LC823410-10S4-H	LC98600CQ-05JB-E
LC72321Y-9C01N-E	LC78611W-02ED-E	LC823410-13N-H	LC98600CQ-13B-H
LC72321Y-9C25N-E	LC78613T-UCA-H	LC865612A-52R8-E	LC98700DF-05S-E
LC72322-8995-E	LC78613T-UDA-H	LC875G32A-5BY4-E	LC98800DF-14A-H
LC72322-9271-E	LC786800E-00US-H	LC875J48C-5BZ3-E	LC98800DFA-11L-H
LC72322-9357-E	LC786800E-03US-H	LC877G16A-5BV6-2H	LV25400W-FJT-MPB-E
LC72322N-9390-E	LC786920NE-SHLR-UC-E	LC878396PA-5AA5-E	