

**ON Semiconductor**



Subject: ON Semiconductor UPDATE NOTIFICATION 10147

TITLE: UPDATE NOTIFICATION FOR PCN'S 4813 AND 10041

EFFECTIVE DATE: 09-MAR-00

AFFECTED CHANGE CATEGORIES

AFFECTED PRODUCT DIVISIONS

ANALOG PRODUCTS DIV

ADDITIONAL RELIABILITY DATA: None

Ref:

SAMPLES: No

Ref:

For any questions concerning this notification:

REFERENCE: ALAN GARLINGTON

PHONE: 602-244-3157

DISCLAIMER:

ON SEMICONDUCTOR WILL CONSIDER THIS CHANGE APPROVED UNLESS SPECIFIC CONDITIONS OF ACCEPTANCE ARE PROVIDED IN WRITING WITHIN 30 DAYS OF RECEIPT OF THIS NOTICE. TO DO SO, CONTACT YOUR LOCAL ON SEMICONDUCTOR SALES OFFICE.

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.

\*\*\*\*\*  
UPDATE NOTIFICATION  
\*\*\*\*\*

ISSUE DATE: 08-Mar-2000  
EFFECTIVE DATE: 09-Mar-2000

NOTIFICATION #:10147  
ISSUING DIVISION:ON SEMICONDUCTO

DESCRIPTION AND PURPOSE  
-----

In June 1999 and September 1999, Analog issued two product change notifications regarding products manufactured in BMC/BP4 and their qualification in the Tesla Wafer Fab located in Roznov, Czech Republic. These PCN numbers were 4813 and 10041. The PCN's listed devices to be run at the Tesla wafer fab and dates for which they would have customer samples available. ON has been able to delay indefinitely the transfer of many of the devices listed on these PCN's. Therefore, samples for the re-qualification will not be produced, as they are not necessary at this time. This notification is being issued to clarify, on a per device basis, the status of the parts, and whether they will be processed in Tesla. At the bottom of this notice is a complete listing of all devices listed on the two original PCN's and the specific device information. ON Semiconductor apologizes for any inconvenience that this change has caused you. Since most of these devices will continue to be sourced from the original Wafer Fab, no customer re-qualification should be needed on these parts.

NOTE: DEVICES LISTED AS YES/DUAL MEAN THAT THE INTENT IS TO RUN THE  
DEVICE IN BOTH THE CURRENT FAB(S) AS WELL AS THE TESLA FAB.

DEVICE LISTING FROM PCN4813	CURRENT FAB	MOVING TO TESLA	SAMPLES AVAILABLE	EOL PCN#
FLM2931AD-5.0R2	BMC/Tesla			
FLP2951ACDR2	BMC	No		
FMC33172DR2	BMC	No		
LM201AD	BMC	No		
LM201ADR2	BMC	No		
LM201AN	BMC	No		
LM211D	BP4	Yes	Now	
LM211DR2	BP4	Yes	Now	
LM2931AD2T-5.0	BMC/Tesla			
LM2931AD2T-5.0R4	BMC/Tesla			
LM2931AD-5.0	BMC/Tesla			
LM2931AD-5.0R2	BMC/Tesla			
LM2931ADT-5.0	BMC/Tesla			
LM2931ADT-5.0RK	BMC/Tesla			

Semiconductor Technology Grp

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

LM2931AT-5.0	BMC/Tesla		
LM2931AZ-5.0	BMC/Tesla		
LM2931AZ-5.0RA	BMC/Tesla		
LM2931AZ-5.0RP	BMC/Tesla		
LM2931CD	BMC/Tesla		
LM2931CD2T	BMC/Tesla		
LM2931CD2TR4	BMC/Tesla		
LM2931CDR2	BMC/Tesla		
LM2931CT	BMC/Tesla		
LM2931CTV	BMC/Tesla		
LM2931D2T-5.0	BMC/Tesla		
LM2931D2T-5.0R4	BMC/Tesla		
LM2931D-5.0	BMC/Tesla		
LM2931D-5.0R2	BMC/Tesla		
LM2931DT-5.0	BMC/Tesla		
LM2931T-5.0	BMC/Tesla		
LM2931Z-5.0	BMC/Tesla		
LM2935D2T	BMC	No	
LM2935T	BMC	No	
LM301AD	BMC	No	
LM301ADR2	BMC	No	
LM301AN	BMC	No	
LM311D	BP4	Yes	Now
LM311DR2	BP4	Yes	Now
LM311N	BP4	Yes	Now
LM317MABDT	Tesla		
LM317MABDTRK	Tesla		
LM317MABT	Tesla		
LM317MADTRK	Tesla		
LM317MBDT	Tesla		
LM317MBDTRK	Tesla		
LM317MBT	Tesla		
LM317MDT	Tesla		
LM317MDTRK	Tesla		
LM317MT	Tesla		
LM323AT	BMC	No	
LM323T	BMC	No	
LM337AT	BMC	No	
LM337BD2T	BMC	No	
LM337BD2TR4	BMC	No	
LM337BT	BMC	No	
LM337D2T	BMC	No	
LM337D2TR4	BMC	No	
LM337MT	BMC	No	
LM337T	BMC	No	
LM350BT	BMC	No	
LM350T	BMC	No	
LM833D	BP4/BMC	No	
LM833DR2	BP4/BMC	No	
LM833N	BP4/BMC	No	
LMW301A	BMC		

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000  
EFFECTIVE DATE: 09-Mar-2000

NOTIFICATION #:10147  
ISSUING DIVISION:ON SEMICONDUCTO

LMW311	BP4		10107
LP2950ACDT-3.0	BMC	No	
LP2950ACDT-3.3	BMC	No	
LP2950ACDT-5.0	BMC	No	
LP2950ACDT-5.0RK	BMC	No	
LP2950ACZ-3.3	BMC	No	
LP2950ACZ-3.3RA	BMC	No	
LP2950ACZ-5.0	BMC	No	
LP2950ACZ-5.0RA	BMC	No	
LP2950CDT-3.0	BMC	No	
LP2950CDT-3.3	BMC	No	
LP2950CDT-3.3RK	BMC	No	
LP2950CDT-5.0	BMC	No	
LP2950CDT-5.0RK	BMC	No	
LP2950CP-005	BMC	No	
LP2950CZ-3.0	BMC	No	
LP2950CZ-3.3	BMC	No	
LP2950CZ-3.3RA	BMC	No	
LP2950CZ-5.0	BMC	No	
LP2950CZ-5.0RA	BMC	No	
LP2950CZ-5.0RP	BMC	No	
LP2951ACD	BMC	No	
LP2951ACD-005	BMC	No	
LP2951ACD-3.0	BMC	No	
LP2951ACD-3.0R2	BMC	No	
LP2951ACD-3.3	BMC	No	
LP2951ACD-5R2	BMC	No	
LP2951ACDM-3.0R2	BMC	No	
LP2951ACDM-3.3R2	BMC	No	
LP2951ACDM-5.0R2	BMC	No	
LP2951ACDR2	BMC	No	
LP2951ACN	BMC	No	
LP2951ACN-3.0	BMC	No	
LP2951ACN-3.3	BMC	No	
LP2951CD	BMC	No	
LP2951CD-005	BMC	No	
LP2951CD-3.0	BMC	No	
LP2951CD-3.3	BMC	No	
LP2951CD-3.3R2	BMC	No	
LP2951CD-5R2	BMC	No	
LP2951CDMR2	BMC	No	
LP2951CDR2	BMC	No	
LP2951CN	BMC	No	
LP2951CN-3.0	BMC	No	
LP2951CN-3.3	BMC	No	
MC1403BD	BMC	No	
MC1403BDR2	BMC	No	
MC1403BP1	BMC	No	
MC1403D	BMC	No	
MC1403DR2	BMC	No	
MC1403P1	BMC	No	

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000  
EFFECTIVE DATE: 09-Mar-2000

NOTIFICATION #:10147  
ISSUING DIVISION:ON SEMICONDUCTO

MC1404P5	BMC	No	
MC1436D	BMC	No	
MC1436DR2	BMC	No	
MC1488D	BP4	Yes	Now
MC1488DR2	BP4	Yes	Now
MC1488M	BP4	Yes	Now
MC1488MEL	BP4	Yes	Now
MC1488ML1	BP4	Yes	Now
MC1488MR1	BP4	Yes	Now
MC1488P	BP4	Yes	Now
MC1723BD	BP4		10109
MC1723BDR2	BP4		10109
MC1723CD	BP4		10109
MC1723CDR2	BP4		10109
MC1723CP	BP4		10109
MC1776CD	BMC		10109
MC1776CDR2	BMC		10109
MC1776CP1	BMC		10109
MC33060ADR2	BMC	No	
MC33060AP	BMC	No	
MC33063AD	BMC	No	
MC33063ADR2	BMC	No	
MC33063AP1	BMC	No	
MC33063AVD	BMC	No	
MC33071AD	BMC	No	
MC33071ADR2	BMC	No	
MC33071AP	BMC	No	
MC33071D	BMC	No	
MC33071DR2	BMC	No	
MC33071P	BMC	No	
MC33072AD	BMC/Allegro	No	
MC33072ADR2	BMC/Allegro	No	
MC33072AP	BMC/Allegro	No	
MC33072D	BMC/Allegro	No	
MC33072DR2	BMC/Allegro	No	
MC33072P	BMC/Allegro	No	
MC33077D	BMC	No	
MC33077DR2	BMC	No	
MC33077P	BMC	No	
MC33078D	BP4/BMC	No	
MC33078DR2	BP4/BMC	No	
MC33078M	BP4/BMC	No	
MC33078ML1	BP4/BMC	No	
MC33078P	BP4/BMC	No	
MC33079D	BP4/BMC	No	
MC33079DR2	BP4/BMC	No	
MC33079MR1	BP4/BMC	No	
MC33079P	BP4/BMC	No	
MC33160DW	BMC	No	
MC33160DWR2	BMC	No	
MC33160P	BMC	No	

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000  
EFFECTIVE DATE: 09-Mar-2000

NOTIFICATION #:10147  
ISSUING DIVISION:ON SEMICONDUCTO

MC33163DW	BMC	Yes/Dual	Aug-00
MC33163DWR2	BMC	Yes/Dual	Aug-00
MC33163P	BMC	Yes/Dual	Aug-00
MC33166D2T	BMC	No	
MC33166D2TR4	BMC	No	
MC33166T	BMC	No	
MC33166TH	BMC	No	
MC33166TV	BMC	No	
MC33167D2T	BMC	No	
MC33167T	BMC	No	
MC33167TH	BMC	No	
MC33167TV	BMC	No	
MC33171D	BMC	No	
MC33171DR2	BMC	No	
MC33171P	BMC	No	
MC33172D	BMC	No	
MC33172DR2	BMC	No	
MC33172MEL	BMC	No	
MC33172P	BMC	No	
MC33174D	BMC	No	
MC33174DR2	BMC	No	
MC33174M	BMC	No	
MC33174P	BMC	No	
MC33174VDR2	BMC	No	
MC33174VP	BMC	No	
MC33267D2T	BMC	No	
MC33267D2TR4	BMC	No	
MC33267T	BMC	No	
MC33267TH	BMC	No	
MC33267TV	BMC	No	
MC33272AD	BMC	No	
MC33272ADR2	BMC	No	
MC33272AP	BMC	No	
MC33274AD	BMC	No	
MC33274ADR2	BMC	No	
MC33274AP	BMC	No	
MC3405P	BMC		10109
MC34060AD	BMC	No	
MC34060ADR2	BMC	No	
MC34060AP	BMC	No	
MC34060P	BMC	No	
MC34063AD	BMC	No	
MC34063ADR2	BMC	No	
MC34063AM	BMC	No	
MC34063AMEL	BMC	No	
MC34063AML1	BMC	No	
MC34063AML2	BMC	No	
MC34063AMR1	BMC	No	
MC34063AMR2	BMC	No	
MC34063AP1	BMC	No	
MC34063BD	BMC	No	

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000  
 EFFECTIVE DATE: 09-Mar-2000

NOTIFICATION #:10147  
 ISSUING DIVISION:ON SEMICONDUCTO

MC34063BDR2	BMC	No	
MC34071AD	BMC	No	
MC34071ADR2	BMC	No	
MC34071AP	BMC	No	
MC34071D	BMC	No	
MC34071DR2	BMC	No	
MC34071JOR2	BMC	No	
MC34071P	BMC	No	
MC34072AD	BMC/Allegro	No	
MC34072ADR2	BMC/Allegro	No	
MC34072AP	BMC/Allegro	No	
MC34072D	BMC/Allegro	No	
MC34072DR2	BMC/Allegro	No	
MC34072JOR2	BMC/Allegro	No	
MC34072P	BMC/Allegro	No	
MC34072VD	BMC/Allegro	No	
MC34072VDR2	BMC/Allegro	No	
MC34072VP	BMC/Allegro	No	
MC34160DW	BMC	No	
MC34160DWR2	BMC	No	
MC34160P	BMC	No	
MC34163DW	BMC	Yes/Dual	Aug-00
MC34163DWR2	BMC	Yes/Dual	Aug-00
MC34163P	BMC	Yes/Dual	Aug-00
MC34166D2T	BMC	No	
MC34166D2TR4	BMC	No	
MC34166T	BMC	No	
MC34166TH	BMC	No	
MC34166TV	BMC	No	
MC34167D2T	BMC	No	
MC34167T	BMC	No	
MC34167TH	BMC	No	
MC34167TV	BMC	No	
MC3423D	BP4	Yes	Now
MC3423DR2	BP4	Yes	Now
MC3423P1	BP4	Yes	Now
MC3425P1	BMC	No	
MC3476P1	BMC		4323
MC3488AD	BMC	No	
MC3488ADR2	BMC	No	
MC3488AP1	BMC	No	
MC4558CD	BMC		10109
MC4558CDR2	BMC		10109
MC4558CP1	BMC		10109
MC4558VD	BMC		10109
MC4558VDR2	BMC		10109
MC78T05ABT	BMC	No	
MC78T05ACT	BMC	No	
MC78T05BT	BMC	No	
MC78T05CT	BMC	No	
MC78T08CT	BMC	No	

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC78T12ACT	BMC	No	
MC78T12BT	BMC	No	
MC78T12CT	BMC	No	
MC78T15ABT	BMC	No	
MC78T15ACT	BMC	No	
MC78T15CT	BMC	No	
MC7905.2CT	Tesla		
MC79L05ABD	BP4	Yes	Now
MC79L05ABDR2	BP4	Yes	Now
MC79L05ABP	BP4	Yes	Now
MC79L05ABPRA	BP4	Yes	Now
MC79L05ACD	BP4	Yes	Now
MC79L05ACDR2	BP4	Yes	Now
MC79L05ACP	BP4	Yes	Now
MC79L05ACPRA	BP4	Yes	Now
MC79L05ACPRP	BP4	Yes	Now
MC79L05CP	BP4	Yes	Now
MC79L12ABD	BP4	Yes	Now
MC79L12ABDR2	BP4	Yes	Now
MC79L12ABP	BP4	Yes	Now
MC79L12ABPRA	BP4	Yes	Now
MC79L12ACD	BP4	Yes	Now
MC79L12ACDR2	BP4	Yes	Now
MC79L12ACP	BP4	Yes	Now
MC79L12ACPRA	BP4	Yes	Now
MC79L12ACPRP	BP4	Yes	Now
MC79L15ABD	BP4	Yes	Now
MC79L15ABDR2	BP4	Yes	Now
MC79L15ABP	BP4	Yes	Now
MC79L15ABPRP	BP4	Yes	Now
MC79L15ACD	BP4	Yes	Now
MC79L15ACDR2	BP4	Yes	Now
MC79L15ACP	BP4	Yes	Now
MC79L15ACPRA	BP4	Yes	Now
MC79L15ACPRP	BP4	Yes	Now
MC79L18ACP	BP4	Yes	Now
MC79L24ABP	BP4	Yes	Now
MC79L24ACP	BP4	Yes	Now
MC79L24ACPRM	BP4	Yes	Now
MC79L24ACPRP	BP4	Yes	Now
MC79M05BDT	Tesla		
MC79M05BDTRK	Tesla		
MC79M05BT	Tesla		
MC79M05CDT	Tesla		
MC79M05CDTRK	Tesla		
MC79M05CT	Tesla		
MC79M12BDT	Tesla		
MC79M12BDTRK	Tesla		
MC79M12BT	Tesla		
MC79M12CDT	Tesla		
MC79M12CDTRK	Tesla		



\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC79M12CT	Tesla		
MC79M15BDT	Tesla		
MC79M15BDTRK	Tesla		
MC79M15BT	Tesla		
MC79M15CDT	Tesla		
MC79M15CDTRK	Tesla		
MC79M15CT	Tesla		
MCW1403	BMC		10107
MCW1436C	BMC		10107
MCW1488C	BP4		10107
MCW1723C	BP4		10107
MCW33171	BMC		10107
MCW33172	BMC		10107
MCW33174	BMC		10107
MCW34071	BMC		10107
MCW34072	BMC		10107
MCW79L05AC	BP4		10107
MCW79L05C	BP4		10107
MCW79L12AC	BP4		10107
SA317MDTRK	Tesla		
SG3525AN	BMC	No	
SG3526N	BMC	No	
TL494BDR2	BMC	Yes/Dual	Aug-00
TL494CD	BMC	Yes/Dual	Aug-00
TL494CDR2	BMC	Yes/Dual	Aug-00
TL494CN	BMC	Yes/Dual	Aug-00
TL494IN	BMC	Yes/Dual	Aug-00
TL594CD	BMC	Yes/Dual	Aug-00

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000 NOTIFICATION #:10147  
 EFFECTIVE DATE: 09-Mar-2000 ISSUING DIVISION:ON SEMICONDUCTO

TL594CDR2	BMC	Yes/Dual	Aug-00	
TL594CN	BMC	Yes/Dual	Aug-00	
TLW594C	BMC			10107
TY38403	BP4			10109
TY40422RP	BMC/Tesla			
TYA2803A	BP4			10109
TYA33272ADR2	BMC	No		
UA78S40PC	BMC	No		
UA78S40PV	BMC	No		
UC2842AD	Tesla			
UC2842ADR2	Tesla			
UC2842AN	Tesla			
UC2843AD	Tesla			
UC2843ADR2	Tesla			
UC2843AN	Tesla			
UC2844D	BMC	No		
UC2844DR2	BMC	No		
UC2844N	BMC	No		
UC2845D	BMC	No		
UC2845DR2	BMC	No		
UC2845N	BMC	No		
UC3842AD	Tesla			
UC3842ADR2	Tesla			
UC3842AN	Tesla			
UC3842AN1	Tesla			
UC3842AN2	Tesla			
UC3843AD	Tesla			
UC3843AD2R2	Tesla			
UC3843ADR2	Tesla			
UC3843AN	Tesla			
UC3843AN2	Tesla			
UC3844D	BMC	No		
UC3844DR2	BMC	No		
UC3844N	BMC	No		
UC3845D	BMC	No		
UC3845DR2	BMC	No		
UC3845N	BMC	No		
ULN2803A	BP4			10109
ULN2804A	BMC			10109
ULNW2803	BP4			10109

DEVICE LISTING FROM PCN10041

CA3059	BMC	No		
FMC33064D-5R2	BP4/BMC	Yes/Dual	Mar-00	
FMC33164D-3R2	BP4/BMC	No		
FMC33164D-5R2	BP4/BMC	No		
LM239AD	BP4			10109
LM239ADR2	BP4			10109
LM239AN	BP4			10109
LM285D-1.2	BMC	No		

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

LM285D-1.2R2	BMC	No		
LM285D-2.5	BMC	No		
LM285D-2.5R2	BMC	No		
LM285Z-1.2	BMC	No		
LM285Z-1.2RA	BMC	No		
LM285Z-2.5	BMC	No		
LM285Z-2.5RA	BMC	No		
LM285Z-2.5RP	BMC	No		
LM339AD	BP4			10109
LM339ADR2	BP4			10109
LM339AN	BP4			10109
LM348D	BP4			10109
LM348DR2	BP4			10109
LM385BD-1.2	BMC	No		
LM385BD-1.2R2	BMC	No		
LM385BD-2.5	BMC	No		
LM385BD-2.5R2	BMC	No		
LM385BZ-1.2	BMC	No		
LM385BZ-1.2RA	BMC	No		
LM385BZ-2.5	BMC	No		
LM385BZ-2.5RA	BMC	No		
LM385D-1.2	BMC	No		
LM385D-1.2R2	BMC	No		
LM385D-2.5	BMC	No		
LM385D-2.5R2	BMC	No		
LM385Z-1.2	BMC	No		
LM385Z-1.2RA	BMC	No		
LM385Z-1.2RP	BMC	No		
LM385Z-2.5	BMC	No		
LM385Z-2.5RP	BMC	No		
LM393AN	Tesla			10109
LMW339A	BP4			10107
LMW385-1.2	BMC			10107
LSC1176D	BP4			10109
LSC1176DR2	BP4			10109
MC1455BD	BP4	Yes	Aug-00	
MC1455BDR2	BP4	Yes	Aug-00	
MC1455BP1	BP4	Yes	Aug-00	
MC1455D	BP4	Yes	Aug-00	
MC1455DR2	BP4	Yes	Aug-00	
MC1455P1	BP4	Yes	Aug-00	
MC1458CD	BP4			10109
MC1458CDR2	BP4			10109
MC1458CP1	BP4			10109
MC1458D	BP4			10109
MC1458DR2	BP4			10109
MC1458P1	BP4			10109
MC1494P	BMC	No		
MC1495BP	BMC	No		
MC1495D	BMC	No		
MC1495DR2	BMC	No		

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC1495P	BMC	No	
MC1496BP	BP4	Yes	Jun-00
MC1496D	BP4	Yes	Jun-00
MC1496DR2	BP4	Yes	Jun-00
MC1496P	BP4	Yes	Jun-00
MC1496P1	BP4	Yes	Jun-00
MC14C89ABD	BMC	No	
MC14C89ABDR2	BMC	No	
MC14C89ABP	BMC	No	
MC1741CD	BMC	No	
MC1741CDR2	BMC	No	
MC1741CP1	BMC	No	
MC33030DW	BMC	No	
MC33030DWR2	BMC	No	
MC33030P	BMC	No	
MC33033DW	BP4/BMC	Yes/Dual	Apr-00
MC33033DWR2	BP4/BMC	Yes/Dual	Apr-00
MC33033P	BP4/BMC	Yes/Dual	Apr-00
MC33035DW	BMC	No	
MC33035DWR2	BMC	No	
MC33035P	BMC	No	
MC33039D	BP4	Yes	Jul-00
MC33039DR2	BP4	Yes	Jul-00
MC33039P	BP4	Yes	Jul-00
MC33064D-005	BP4/BMC	Yes/Dual	Mar-00
MC33064D-5R2	BP4/BMC	Yes/Dual	Mar-00
MC33064DM-5R2	BP4/BMC	Yes/Dual	Mar-00
MC33064P-005	BP4/BMC	Yes/Dual	Mar-00
MC33064P-5RA	BP4/BMC	Yes/Dual	Mar-00
MC33064P-5RP	BP4/BMC	Yes/Dual	Mar-00
MC33065DW-H	BMC	No	
MC33065DW-HR2	BMC	No	
MC33065DW-L	BMC	No	
MC33065DW-LR2	BMC	No	
MC33065P-L	BMC	No	
MC33164D-003	BP4/BMC	No	
MC33164D-005	BP4/BMC	No	
MC33164D-3R2	BP4/BMC	No	
MC33164D-5R2	BP4/BMC	No	
MC33164DM-3R2	BP4/BMC	No	
MC33164DM-5R2	BP4/BMC	No	
MC33164P-003	BP4/BMC	No	
MC33164P-005	BP4/BMC	No	
MC33164P-3RA	BP4/BMC	No	
MC33164P-3RP	BP4/BMC	No	
MC33164P-5RA	BP4/BMC	No	
MC33164P-5RP	BP4/BMC	No	
MC3346D	BMC	No	
MC3346DR2	BMC	No	
MC3346P	BMC	No	
MC3358D	BMC	No	

\*\*\*\*\*  
 UPDATE NOTIFICATION

\*\*\*\*\*  
 ISSUE DATE: 08-Mar-2000 NOTIFICATION #:10147  
 EFFECTIVE DATE: 09-Mar-2000 ISSUING DIVISION:ON SEMICONDUCTO

MC3358DR2	BMC	No	
MC3358P1	BMC	No	
MC34064D-005	BP4/BMC	Yes/Dual	Mar-00
MC34064D-5R2	BP4/BMC	Yes/Dual	Mar-00
MC34064DM-5R2	BP4/BMC	Yes/Dual	Mar-00
MC34064P-005	BP4/BMC	Yes/Dual	Mar-00
MC34064P-5RA	BP4/BMC	Yes/Dual	Mar-00
MC34064P-5RM	BP4/BMC	Yes/Dual	Mar-00
MC34064P-5RP	BP4/BMC	Yes/Dual	Mar-00
MC34065DW-H	BMC	No	
MC34065DW-L	BMC	No	
MC34065P-H	BMC	No	
MC34065P-L	BMC	No	
MC34164D-003	BP4/BMC	No	
MC34164D-005	BP4/BMC	No	
MC34164D-3R2	BP4/BMC	No	
MC34164D-5R2	BP4/BMC	No	
MC34164DM-3R2	BP4/BMC	No	
MC34164P-003	BP4/BMC	No	
MC34164P-005	BP4/BMC	No	
MC34164P-3RP	BP4/BMC	No	
MC34164P-5RA	BP4/BMC	No	
MC34164P-5RP	BP4/BMC	No	
MC3456P	BMC	No	
MC3458D	BMC	No	
MC3458DR2	BMC	No	
MC3458P1	BMC	No	
MC3479P	BMC	No	
MC44602P2	BP4		10107
MC4741CD	BP4		10109
MC4741CDR2	BP4		10109
MC4741CP	BP4		10109
MCW1455	BP4		4748
MCW1741C	BMC		10107
MCW33035	BMC	No	
MCW33039	BMC	No	
MCW34064	BP4/BMC		10107
MCW34164-005	BP4/BMC		10107
TDA1085C	BP4	Yes	Aug-00
TY40470R2	BP4/BMC	Yes/Dual	Mar-00
TYA1496DR2	BP4	Yes	Jun-00
TYA33164D-5R2	BP4/BMC	No	
TYA33164P-5RP	BP4/BMC	No	
UAA2016D	BP4	Yes	Apr-00
UAA2016P	BP4	Yes	Apr-00

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

FILE FORMAT: ASCII TEXT

FONT - Courier

SIZE - 12 Point

LINE - 70 characters/line

PAGE - 55 lines/page

PAGEBREAK CHARACTER - ^L (Control L)

AFFECTED DEVICE LIST (WITHOUT SPECIALS)

-----

CA3059	, FLM2931AD-5.0R2	, FLP2951ACDR2	, FMC33064D-5R2
FMC33164D-3R2	, FMC33164D-5R2	, FMC33172DR2	, LM201AD
LM201ADR2	, LM201AN	, LM211D	, LM211DR2
LM239AD	, LM239ADR2	, LM239AN	, LM285D-1.2
LM285D-1.2R2	, LM285D-2.5	, LM285D-2.5R2	, LM285Z-1.2
LM285Z-1.2RA	, LM285Z-2.5	, LM285Z-2.5RA	, LM285Z-2.5RP
LM2931AD-5.0	, LM2931AD-5.0R2	, LM2931AD2T-5.0	, LM2931AD2T-5.0R4
LM2931ADT-5.0	, LM2931ADT-5.0RK	, LM2931AT-5.0	, LM2931AZ-5.0
LM2931AZ-5.0RA	, LM2931AZ-5.0RP	, LM2931CD	, LM2931CD2T
LM2931CD2TR4	, LM2931CDR2	, LM2931CT	, LM2931CTV
LM2931D-5.0	, LM2931D-5.0R2	, LM2931D2T-5.0	, LM2931D2T-5.0R4
LM2931DT-5.0	, LM2931T-5.0	, LM2931Z-5.0	, LM2935D2T
LM2935T	, LM301AD	, LM301ADR2	, LM301AN
LM311D	, LM311DR2	, LM311N	, LM317MABDT
LM317MABDTRK	, LM317MABT	, LM317MADTRK	, LM317MBDT
LM317MBDTRK	, LM317MBT	, LM317MDT	, LM317MDTRK
LM317MT	, LM323AT	, LM323T	, LM337AT
LM337BD2T	, LM337BD2TR4	, LM337BT	, LM337D2T
LM337D2TR4	, LM337MT	, LM337T	, LM339AD
LM339ADR2	, LM339AN	, LM348D	, LM348DR2
LM350BT	, LM350T	, LM385BD-1.2	, LM385BD-1.2R2
LM385BD-2.5	, LM385BD-2.5R2	, LM385BZ-1.2	, LM385BZ-1.2RA
LM385BZ-2.5	, LM385BZ-2.5RA	, LM385D-1.2	, LM385D-1.2R2
LM385D-2.5	, LM385D-2.5R2	, LM385Z-1.2	, LM385Z-1.2RA
LM385Z-1.2RP	, LM385Z-2.5	, LM385Z-2.5RP	, LM393AN
LM833D	, LM833DR2	, LM833N	, LMW301A
LMW311	, LMW339A	, LMW385-1.2	, LP2950ACDT-3.0
LP2950ACDT-3.3	, LP2950ACDT-5.0	, LP2950ACDT-5.0RK	, LP2950ACZ-3.3
LP2950ACZ-3.3RA	, LP2950ACZ-5.0	, LP2950ACZ-5.0RA	, LP2950CDT-3.0
LP2950CDT-3.3	, LP2950CDT-3.3RK	, LP2950CDT-5.0	, LP2950CP-005
LP2950CZ-3.0	, LP2950CZ-3.3	, LP2950CZ-3.3RA	, LP2950CZ-5.0
LP2950CZ-5.0RA	, LP2950CZ-5.0RP	, LP2951ACD	, LP2951ACD-005
LP2951ACD-3.0	, LP2951ACD-3.0R2	, LP2951ACD-3.3	, LP2951ACD-5R2
LP2951ACDM-3.0R2	, LP2951ACDM-3.3R2	, LP2951ACDM-5.0R2	, LP2951ACDR2
LP2951ACN	, LP2951ACN-3.0	, LP2951ACN-3.3	, LP2951CD
LP2951CD-005	, LP2951CD-3.0	, LP2951CD-3.3	, LP2951CD-3.3R2
LP2951CD-5R2	, LP2951CDMR2	, LP2951CDR2	, LP2951CN
LP2951CN-3.0	, LP2951CN-3.3	, MC1403BD	, MC1403BDR2
MC1403BP1	, MC1403D	, MC1403DR2	, MC1403P1
MC1404P5	, MC1436D	, MC1436DR2	, MC1455BD
MC1455BDR2	, MC1455BP1	, MC1455D	, MC1455DR2
MC1455P1	, MC1458CD	, MC1458CDR2	, MC1458CP1
MC1458D	, MC1458DR2	, MC1458P1	, MC1488D
MC1488DR2	, MC1488M	, MC1488MEL	, MC1488ML1
MC1488MR1	, MC1488P	, MC1494P	, MC1495BP
MC1495D	, MC1495DR2	, MC1495P	, MC1496BP
MC1496D	, MC1496DR2	, MC1496P	, MC1496P1
MC14C89ABD	, MC14C89ABDR2	, MC14C89ABP	, MC1723BD
MC1723BDR2	, MC1723CD	, MC1723CDR2	, MC1723CP
MC1741CD	, MC1741CDR2	, MC1741CP1	, MC1776CD
MC1776CDR2	, MC1776CP1	, MC33030DW	, MC33030DWR2
MC33030P	, MC33033DW	, MC33033DWR2	, MC33033P
MC33035DW	, MC33035DWR2	, MC33035P	, MC33039D
MC33039DR2	, MC33039P	, MC33060ADR2	, MC33060AP
MC33063AD	, MC33063ADR2	, MC33063AP1	, MC33063AVD
MC33064D-005	, MC33064D-5R2	, MC33064DM-5R2	, MC33064P-005
MC33064P-5RA	, MC33064P-5RP	, MC33065DW-H	, MC33065DW-HR2
MC33065DW-L	, MC33065DW-LR2	, MC33065P-L	, MC33071AD

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC33071ADR2	, MC33071AP	, MC33071D	, MC33071DR2
MC33071P	, MC33072AD	, MC33072ADR2	, MC33072AP
MC33072D	, MC33072DR2	, MC33072P	, MC33077D
MC33077DR2	, MC33077P	, MC33078D	, MC33078DR2
MC33078M	, MC33078ML1	, MC33078P	, MC33079D
MC33079DR2	, MC33079MR1	, MC33079P	, MC33160DW
MC33160DWR2	, MC33160P	, MC33163DW	, MC33163DWR2
MC33163P	, MC33164D-003	, MC33164D-005	, MC33164D-3R2
MC33164D-5R2	, MC33164DM-3R2	, MC33164DM-5R2	, MC33164P-003
MC33164P-005	, MC33164P-3RA	, MC33164P-3RP	, MC33164P-5RA
MC33164P-5RP	, MC33166D2T	, MC33166D2TR4	, MC33166T
MC33166TH	, MC33166TV	, MC33167D2T	, MC33167T
MC33167TH	, MC33167TV	, MC33171D	, MC33171DR2
MC33171P	, MC33172D	, MC33172DR2	, MC33172MEL
MC33172P	, MC33174D	, MC33174DR2	, MC33174M
MC33174P	, MC33174VDR2	, MC33174VP	, MC33267D2T
MC33267D2TR4	, MC33267T	, MC33267TH	, MC33267TV
MC33272AD	, MC33272ADR2	, MC33272AP	, MC33274AD
MC33274ADR2	, MC33274AP	, MC3346D	, MC3346DR2
MC3346P	, MC3358D	, MC3358DR2	, MC3358P1
MC3405P	, MC34060AD	, MC34060ADR2	, MC34060AP
MC34060P	, MC34063AD	, MC34063ADR2	, MC34063AM
MC34063AMEL	, MC34063AML1	, MC34063AML2	, MC34063AMR1
MC34063AMR2	, MC34063AP1	, MC34063BD	, MC34063BDR2
MC34064D-005	, MC34064D-5R2	, MC34064DM-5R2	, MC34064P-005
MC34064P-5RA	, MC34064P-5RM	, MC34064P-5RP	, MC34065DW-H
MC34065DW-L	, MC34065P-H	, MC34065P-L	, MC34071AD
MC34071ADR2	, MC34071AP	, MC34071D	, MC34071DR2
MC34071JOR2	, MC34071P	, MC34072AD	, MC34072ADR2
MC34072AP	, MC34072D	, MC34072DR2	, MC34072JOR2
MC34072P	, MC34072VD	, MC34072VDR2	, MC34072VP
MC34160DW	, MC34160DWR2	, MC34160P	, MC34163DW
MC34163DWR2	, MC34163P	, MC34164D-003	, MC34164D-005
MC34164D-3R2	, MC34164D-5R2	, MC34164DM-3R2	, MC34164P-003
MC34164P-005	, MC34164P-3RP	, MC34164P-5RA	, MC34164P-5RP
MC34166D2T	, MC34166D2TR4	, MC34166T	, MC34166TH
MC34166TV	, MC34167D2T	, MC34167T	, MC34167TH
MC34167TV	, MC3423D	, MC3423DR2	, MC3423P1
MC3425P1	, MC3456P	, MC3458D	, MC3458DR2
MC3458P1	, MC3476P1	, MC3479P	, MC3488AD
MC3488ADR2	, MC3488AP1	, MC44602P2	, MC4558CD
MC4558CDR2	, MC4558CP1	, MC4558VD	, MC4558VDR2
MC4741CD	, MC4741CDR2	, MC4741CP	, MC78T05ABT
MC78T05ACT	, MC78T05BT	, MC78T05CT	, MC78T08CT
MC78T12ACT	, MC78T12BT	, MC78T12CT	, MC78T15ABT
MC78T15ACT	, MC78T15CT	, MC7905.2CT	, MC79L05ABD
MC79L05ABDR2	, MC79L05ABP	, MC79L05ABPRA	, MC79L05ACD
MC79L05ACDR2	, MC79L05ACP	, MC79L05ACPRA	, MC79L05ACPRP
MC79L05CP	, MC79L12ABD	, MC79L12ABDR2	, MC79L12ABP
MC79L12ACD	, MC79L12ACDR2	, MC79L12ACP	, MC79L12ACPRA
MC79L12ACPRP	, MC79L15ABD	, MC79L15ABDR2	, MC79L15ABP



\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 08-Mar-2000

NOTIFICATION #:10147

EFFECTIVE DATE: 09-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC79L15ABPRP	, MC79L15ACD	, MC79L15ACDR2	, MC79L15ACP
MC79L15ACPRA	, MC79L15ACPRP	, MC79L18ACP	, MC79L24ABP
MC79L24ACP	, MC79L24ACPRM	, MC79L24ACPRP	, MC79M05BDT
MC79M05BDTRK	, MC79M05BT	, MC79M05CDT	, MC79M05CDTRK
MC79M05CT	, MC79M12BDT	, MC79M12BDTRK	, MC79M12BT
MC79M12CDT	, MC79M12CDTRK	, MC79M12CT	, MC79M15BDT
MC79M15BDTRK	, MC79M15BT	, MC79M15CDT	, MC79M15CDTRK
MC79M15CT	, MCW1403	, MCW1436C	, MCW1455
MCW1488C	, MCW1723C	, MCW1741C	, MCW33035
MCW33039	, MCW33171	, MCW33172	, MCW33174
MCW34071	, MCW34072	, MCW34164-005	, MCW79L05AC
MCW79L05C	, MCW79L12AC	, SA317MDTRK	, SG3525AN
SG3526N	, TDA1085C		
TL494BDR2	, TL494CD	, TL494CDR2	, TL494CN
TL494IN	, TL594CD	, TL594CDR2	, TL594CN
TLW594C	, TYA1496DR2	, TYA2803A	, TYA33164D-5R2
TYA33164P-5RP	, TYA33272ADR2	, UA78S40PC	, UA78S40PV
UAA2016D	, UAA2016P	, UC2842AD	, UC2842ADR2
UC2842AN	, UC2843AD	, UC2843ADR2	, UC2843AN
UC2844D	, UC2844DR2	, UC2844N	, UC2845D
UC2845DR2	, UC2845N	, UC3842AD	, UC3842ADR2
UC3842AN	, UC3842AN1	, UC3842AN2	, UC3843AD
UC3843AD2R2	, UC3843ADR2	, UC3843AN	, UC3843AN2
UC3844D	, UC3844DR2	, UC3844N	, UC3845D
UC3845DR2	, UC3845N	, ULN2803A	, ULN2804A
ULNW2803			