



---

**PRODUCT BULLETIN # 20314**Generic Copy

---

**Issue Date:** 16-Dec-2013**TITLE:** LC89075WA Datasheet Update**PROPOSED FIRST SHIP DATE:** 16-Dec-2013**AFFECTED CHANGE CATEGORY(S):** Datasheet Only**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**

Contact your local ON Semiconductor sales office or Yuji Sakai &lt;Yuji.Sakai@onsemi.com&gt;

**NOTIFICATION TYPE:**

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact &lt;quality@onsemi.com&gt;.

**DESCRIPTION AND PURPOSE:**

The LC89075WA datasheet Rev.0 has an error.

Error correction is made with the publication of the Rev.1 of the LC89075WA datasheet.

- Contents of an error:
  - Page of an error: 20-page, Figure 9.2 Internal PGA Analog Input Configuration Diagram
  - Issue: The polarity of the external capacitor C1 is reverse. The plus polarity of the external capacitor C1 is on the resistor R1 side.
- Correction of an error:
  - The plus polarity of the external capacitor C1 needs to be the LC89075WA side.

**List of affected General Parts:**

LC89075WA-H