



PCN# : P634AAB  
Issue Date : Mar. 10, 2016

### Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

### Implementation of change:

Description of Change (From) :

Figure 1, Typical Application Drawing (Page 2), HV Pin is connected to bulk:




Figure 1. Typical Application

Description of Change (To) :

Figure 1, Typical Application Drawing (Page 2), HV Pin is connected to AC Line:




Figure 1. Typical Application

Reason for Change:  
Datasheet change only.

Fairchild is correcting the error found with application drawing on HV pin to correct to proper level and is changing to suitable application drawing. This new configuration will avoid entering latch-off protection when on/off testing is performed.

---

**Affected Product(s):**

FAN6921MLMY		
-------------	--	--