



PRODUCT DISCONTINUANCE # 20120Y

Issue Date: 26-Jul-2013

TITLE: Product Discontinuance Notice

LAST BUY DATE: 26-Jan-2014

LAST SHIP DATE: 26-Jul-2014

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or Theresa McCarley
<theresa.mccarley@onsemi.com>, Lea Bonita <lea.bonita@onsemi.com>.

NOTIFICATION TYPE:

Customers must notify ON Semiconductor (<quality@onsemi.com>) in writing within 30 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

DESCRIPTION AND PURPOSE:

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. ON Semiconductor continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable). For questions or concerns regarding this notification, please contact your local sales office or customer service representative.



PRODUCT DISCONTINUANCE #20120Y

Additional contacts are:

Americas:

PC Wan (pc.wan@onsemi.com)
602.244.6345
USA

Europe:

Andrej Tomasik (Andrej.tomasik@onsemi.com)
+421 33790 4127
Slovakia

Japan & Asia Pacific:

Stephen Ng (Stephen.ng@onsemi.com)
(852) 2689-0209
China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

End of life buy orders must be placed before 26-Jan-2014
End of life buy orders must be shipped before 26-Jul-2014


PRODUCT DISCONTINUANCE #20120Y
List of affected Parts:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
LA4525-E	NONE	NA
LA4525-V-E	NONE	NA
LA4627HK-E	NONE	NA
LA6358NS-E	NONE	NA
LA6393MC-AH	NONE	NA
LA76931H7FB-E	NONE	NA
LB11988-A-E	NONE	NA
LB11988-E	NONE	NA
LB1205-E	LB1205M—TLM-E	ON Semi(Sanyo)
LB1641L-E	LV8400V-TLM-E	ON Semi(Sanyo)
LB1663-E	LB1868M	ON Semi(Sanyo)
LB1668-E	LB1668M	ON Semi(Sanyo)
LB1731-E	NONE	NA
LB1860-E	LB1860M	ON Semi(Sanyo)
LC72711LW-E	LC72717PW-H	ON Semi(Sanyo)
LC72F3781-E	NONE	NA
LC82162BL-E	LC821621-E	ON Semi(Sanyo)
LC87F0A08AUEB-NH	LC87F0A08AU-EB-TLM-H	ON Semi(Sanyo)
LC87F2832AUFL68TBM-H	NONE	NA
LC87F2924BU-FL64-E	NONE	NA
LC87F2924BUFL64TBM-E	NONE	NA
LC87F2924BUFL64TBM-H	NONE	NA
LC87F2932AVU-QIP-E	NONE	NA
LC898105-TBM-GB-E	LC898113-TBM-H	ON Semi(Sanyo)
LC98500BT-03T-E	NONE	NA
LV3313PM-MPB-E	LV3313PM-TLM-E	ON Semi(Sanyo)
LV3319PM-MPB-E	LV3319PM-TLM-E	ON Semi(Sanyo)
LV51110T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51112T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51114T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51115T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51116LF-TE-F-H	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51116T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51117T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51118T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51119T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51132T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51133T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51134T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51135T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51136T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51137T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51138T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)


PRODUCT DISCONTINUANCE #20120Y

Device to be Discontinued	Recommended Replacement	Supplier
LV51143T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51144T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51146T-TE-F-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV5125T-TLM-E	LV5113/51130/51131	ON Semi(Sanyo)
LV7108E-MPB-E	LV7109E	ON Semi(Sanyo)
LA5693D-E	NONE	NA
LC87F1HC8SAU-SQFP-E	NONE	NA
LC87F57C8AU-QIP-E	NONE	NA
LA6585M-TLM-H	LA6585MC	ON Semi(Sanyo)
LA76931H7N57G9-E	NONE	NA
LA76931J7M5AC0-E	NONE	NA
LA76933G7FB-E	LA76931J7FB-E	ON Semi(Sanyo)
LA76933G7N59H9-E	NONE	NA
LA76933G7N59N2-E	NONE	NA
LC24085BT-XJ5-E	NONE	NA
LC651104N-4M93-E	LC872H08A	ON Semi(Sanyo)
LC651104N-4M94-TRM-E	LC872H08A	ON Semi(Sanyo)
LC66404A-4K28-E	LC875G07B	ON Semi(Sanyo)
LC66404A-4L88-E	LC875G07B	ON Semi(Sanyo)
LC786922E-UM-E	NONE	NA
LC865508A-5K74-E	LC875G07B	ON Semi(Sanyo)
LC865508B-5V88-E	LC875G07B	ON Semi(Sanyo)
LC98700DQ-10J-H	NONE	NA
LV0200-TLM-E	NONE	NA
LV761102C5AV4-MPB-E	NONE	NA
LV761102C5AV9-MPB-E	NONE	NA
LV761112C5AN4-MPB-E	NONE	NA
LV761122C5AV4-MPB-E	NONE	NA
LV761122C5AV9-MPB-E	NONE	NA
LV761132C5AL0-MPB-E	NONE	NA
LV761132C5AS0-MPB-E	NONE	NA
LV761132C5AV4A-MPB-E	NONE	NA
LV761132C5AV9A-MPB-E	NONE	NA
LV761132F5AS0-MPB-E	NONE	NA
LV761202C5AV8-MPB-E	NONE	NA
LV761202C5BA8-MPB-E	NONE	NA
LV761222C5AV8-MPB-E	NONE	NA
LV761222C5BA8-MPB-E	NONE	NA
LC5851N-1E89-E	LC877917A	ON Semi(Sanyo)
LC587008-1P36-E	LC877648C	ON Semi(Sanyo)
LC587008-1P62-E	LC877648C	ON Semi(Sanyo)
LC5873-1E26-E	LC877648C	ON Semi(Sanyo)
LC5873-1G76-E	LC877648C	ON Semi(Sanyo)
LC587406A-1N93-E	LC877917A	ON Semi(Sanyo)
LC587406A-1P53-E	LC877917A	ON Semi(Sanyo)


PRODUCT DISCONTINUANCE #20120Y

Device to be Discontinued	Recommended Replacement	Supplier
LC587406A-1P72-E	LC877917A	ON Semi(Sanyo)
LC651104F-4G60-TLM-E	LC872H08A	ON Semi(Sanyo)
LC651104F-4M90-TLM-E	LC872H08A	ON Semi(Sanyo)
LC6527C-4C48-E	LC87BK04A	ON Semi(Sanyo)
LC723341E-9D29-E	NONE	NA
LC72366-9C29-E	NONE	NA
LC72366-9C56-E	NONE	NA
LC74735NWH-8A02-E	NONE	NA
LC74735NWH-9889-E	NONE	NA
LC75010W-6105-E	NONE	NA
LC75030WH-6147-E	NONE	NA
LC786960E-12SM-LR-H	NONE	NA
LC786960E-17UM-H	NONE	NA
LC786960E-18UM-H	NONE	NA
LC786960PE-14SM-LR-H	NONE	NA
LC865508A-5S16	LC875G07B	ON Semi(Sanyo)
LC865508B-52S0-E	LC875G07B	ON Semi(Sanyo)
LC865520B-53H1-E	LC875G24A	ON Semi(Sanyo)
LC865520B-53V6-E	LC875G24A	ON Semi(Sanyo)
LC865520B-5M23-E	LC875G24A	ON Semi(Sanyo)
LC865616A-5K14-E	LC87F5M64A	ON Semi(Sanyo)
LC866524A-5V59-E	LC87F6AC8ALU-EJ-H	ON Semi(Sanyo)
LC871HC8A-5BJ7-E	LC871HC8A-5BJ7-WA-2H	ON Semi(Sanyo)
LC871HC8A-5BL1-E	LC871HC8A-5BL1-WA-2H	ON Semi(Sanyo)
LC875755W-56C5-E	NONE	NA
LC875816A-56F1-E	NONE	NA
LC875816A-59P2-E	NONE	NA
LC877812A-59K0-E	LC877917A	ON Semi(Sanyo)
LC877816A-58K7-E	LC877917A	ON Semi(Sanyo)
LC877C24C-56V1-E	LC87F76C8A	ON Semi(Sanyo)
LC877C32C-59B9-E	LC87F76C8A	ON Semi(Sanyo)
LC877C40C-59B8-E	LC87F76C8A	ON Semi(Sanyo)
LC877C64C-58H9-E	LC87F76C8A	ON Semi(Sanyo)
LC8783J2PA-5BL0-E	NONE	NA
LC8783M4PA-5BK9-E	NONE	NA
LC8784P7PB-5BG9-E	NONE	NA
LC87F1HC8SA-F59P7-E	NONE	NA
LC87F1HC8SA-F5AL4-E	NONE	NA
LC87F2G08A5BE5-TLM-E	LC87F2G08AUMU-ZH	ON Semi(Sanyo)
LC87F2G08A5BJ0-TLM-E	LC87F2G08AUMU-ZH	ON Semi(Sanyo)
LC87F2G08A5BK0-TLM-E	LC87F2G08AUMU-ZH	ON Semi(Sanyo)
LC87F2G08AV5BM6TLM-E	LC87F2G08AV5BM6MJ-AH	ON Semi(Sanyo)
LC87F7CC8A-F56A1-E	LC87F76C8A	ON Semi(Sanyo)