

ON Semiconductor
Formerly a Division of Motorola



Subject: ON Semiconductor PRODUCT BULLETIN 10052

TITLE: DELETING LCX TOSHIBA DIE FROM FINISH GOODS BILL OF MATERIAL

EFFECTIVE DATE: 26-OCT-99

AFFECTED CHANGE CATEGORIES

AFFECTED PRODUCT DIVISIONS
LOGIC DIV

ADDITIONAL RELIABILITY DATA: None

Ref:

SAMPLES: No

Ref:

For any questions concerning this notification:

REFERENCE:DARYL ROBERTS

PHONE: 602-244-5059

DISCLAIMER:

ON SEMICONDUCTOR CONSIDERS THIS CHANGE APPROVED UNLESS SPECIFIC
CONDITIONS OF ACCEPTANCE ARE PROVIDED IN WRITING. TO DO SO, CONTACT
YOUR LOCAL ON SEMICONDUCTOR SALES OFFICE.

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.



PRODUCT BULLETIN

ISSUE DATE: 25-Oct-1999

NOTIFICATION #:10052

EFFECTIVE DATE: 26-Oct-1999

ISSUING DIVISION:PHX-GPPD

DESCRIPTION AND PURPOSE

This bulletin is to alert our customers that ON Semiconductor, formerly a division of Motorola will not produce the attached listed LCX parts from Toshiba. Some parts were listed in PCNs 3887 and 4159, distributed in August and October of 1998. Wafer production on these 16 parts will continue at Charter Semiconductor Manufacturing, in Singapore.

List of LCX die solely manufactured at Charter Semiconductor:

- LCX00
- LCX02
- LCX08
- LCX32
- LCX86
- LCX125
- LCX240
- LCX244
- LCX245
- LVX3245
- LVXC4245
- LCX16240
- LCX16244
- LCX16245
- LCX16373
- LCX16374

This move is part of ON Semiconductor's manufacturing restructuring strategy, and by no means reflects on the quality or performance of the die manufactured in Toshiba's wafer foundry. ON Semiconductor will maintain in the interim some LCX production on the remaining portfolio.

FILE FORMAT: ASCII TEXT
FONT - Courier
SIZE - 12 Point
LINE - 70 characters/line
PAGE - 55 lines/page
PAGEBREAK CHARACTER - ^L (Control L)



AFFECTED DEVICE LIST (WITHOUT SPECIALS)

MC74LCX00D	, MC74LCX00DR2	, MC74LCX00DT	, MC74LCX00DTEL
MC74LCX00DTR2	, MC74LCX00M	, MC74LCX00MEL	, MC74LCX02D
MC74LCX02DR2	, MC74LCX02DT	, MC74LCX02DTEL	, MC74LCX02DTR2
MC74LCX02M	, MC74LCX02MEL	, MC74LCX04D	, MC74LCX04DR2
MC74LCX04DT	, MC74LCX04DTEL	, MC74LCX04DTR2	, MC74LCX04M
MC74LCX04MEL	, MC74LCX08D	, MC74LCX08DR2	, MC74LCX08DT
MC74LCX08DTEL	, MC74LCX08DTR2	, MC74LCX08M	, MC74LCX08MEL
MC74LCX125D	, MC74LCX125DR2	, MC74LCX125DT	, MC74LCX125DTEL
MC74LCX125DTR2	, MC74LCX125M	, MC74LCX125MEL	, MC74LCX138D
MC74LCX138DR2	, MC74LCX138DT	, MC74LCX138DTR2	, MC74LCX138M
MC74LCX138MEL	, MC74LCX157D	, MC74LCX157DR2	, MC74LCX157DT
MC74LCX157DTR2	, MC74LCX157M	, MC74LCX157MEL	, MC74LCX157ML1
MC74LCX157ML2	, MC74LCX16240ADT	, MC74LCX16240ADTR	, MC74LCX16240DT
MC74LCX16240DTR2	, MC74LCX16244DT	, MC74LCX16244DTR2	, MC74LCX16245DT
MC74LCX16245DTR2	, MC74LCX16373DT	, MC74LCX16373DTR2	, MC74LCX16374DT
MC74LCX16374DTR2	, MC74LCX16501DT	, MC74LCX16501DTR2	, MC74LCX16543ADT
MC74LCX16543ADTR	, MC74LCX240DT	, MC74LCX240DTR2	, MC74LCX240DW
MC74LCX240DWR2	, MC74LCX240M	, MC74LCX240MEL	, MC74LCX244DT
MC74LCX244DTEL	, MC74LCX244DTR2	, MC74LCX244DW	, MC74LCX244DWR2
MC74LCX244M	, MC74LCX244MEL	, MC74LCX245DT	, MC74LCX245DTEL
MC74LCX245DTR2	, MC74LCX245DW	, MC74LCX245DWR2	, MC74LCX245M
MC74LCX245MEL	, MC74LCX257D	, MC74LCX257DR2	, MC74LCX257DT
MC74LCX257DTR2	, MC74LCX2952DT	, MC74LCX2952DW	, MC74LCX32D
MC74LCX32DR2	, MC74LCX32DT	, MC74LCX32DTEL	, MC74LCX32DTR2
MC74LCX32M	, MC74LCX32MEL	, MC74LCX373DT	, MC74LCX373DTR2
MC74LCX373DW	, MC74LCX373DWR2	, MC74LCX373M	, MC74LCX374DT
MC74LCX374DTR2	, MC74LCX374DW	, MC74LCX374DWR2	, MC74LCX374M
MC74LCX374MEL	, MC74LCX540DT	, MC74LCX540DW	, MC74LCX540DWR2
MC74LCX540M	, MC74LCX540MEL	, MC74LCX541DT	, MC74LCX541DTEL
MC74LCX541DTR2	, MC74LCX541DW	, MC74LCX541DWR2	, MC74LCX541M
MC74LCX541MEL	, MC74LCX573DT	, MC74LCX573DTR2	, MC74LCX573DW
MC74LCX573DWR2	, MC74LCX574DT	, MC74LCX574DTEL	, MC74LCX574DTR2
MC74LCX574DW	, MC74LCX574DWR2	, MC74LCX574M	, MC74LCX646DT
MC74LCX646DW	, MC74LCX646DWR2	, MC74LCX652DT	, MC74LCX652DTR2
MC74LCX652DW	, MC74LCX652DWR2	, MC74LCX74D	, MC74LCX74DR2
MC74LCX74DT	, MC74LCX74DTR2	, MC74LCX74M	, MC74LCX74MEL
MC74LCX74ML1	, MC74LCX74ML2	, MC74LCX86D	, MC74LCX86DR2
MC74LCX86DT	, MC74LCX86DTR2	, MC74LVX4245DT	, MC74LVX4245DTR2
MC74LVX4245DW	, MC74LVX4245DWR2	, MC74LVXC3245DT	, MC74LVXC3245DTR2
MC74LVXC3245DW	, MC74LVXC3245DWR2	, PC74LCX373BDW	, PC74LCX373BDWR2
PC74LVX4245DT	, PC74LVX4245DW	, PC74LVXC3245DT	, PC74LVXC3245DW
TSC74LCX244DTR2			