

**ON Semiconductor**  
Formerly a Division of Motorola



Subject: Motorola PRODUCT DISCONTINUANCE 4323

TITLE: EOL FOR VARIOUS ANALOG DEVICES

LAST BUY DATE: 08-FEB-2000

LAST SHIP DATE: 08-AUG-2000

AFFECTED CHANGE CATEGORIES

AFFECTED PRODUCT DIVISIONS  
GENERAL PURPOSE PRO

ADDITIONAL RELIABILITY DATA: None

Ref:

SAMPLES: No

Ref:

For any questions concerning this notification:

REFERENCE: BILL ROMAN

PHONE: 602-413-3824

DISCLAIMER:

CUSTOMERS MUST NOTIFY MOTOROLA IN WRITING WITHIN 90 DAYS OF RECEIPT  
OF THIS NOTIFICATION IF THEY CONSIDER THE DISCONTINUED PRODUCT TO BE  
"SOLE SOURCE." MOTOROLA AND THE CUSTOMER MAY NEGOTIATE AN  
APPROPRIATE END-OF-LIFE

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.

\*\*\*\*\*

PRODUCT DISCONTINUANCE

\*\*\*\*\*

ISSUE DATE: 08-Feb-1999

NOTIFICATION #:4323

LAST BUY DATE: 08-Feb-2000

LAST SHIP DATE: 08-Aug-2000

DESCRIPTION AND PURPOSE

-----

The attached information refers to certain products purchased by your company, which Motorola intends to discontinue manufacturing. The decision to discontinue these devices is part of overall Product Portfolio renewal process. Although this may cause some short term inconveniences, which we regret, we believe we will be able to serve you better in the long term. Motorola continues to make substantial investments in both new technologies and improved manufacturing capabilities to provide you the highest quality and reliable semiconductors in the industry. We believe these actions will also improve our ability to serve you in the future.

End of Life buy orders have to be placed before January 20, 2000 and will be shipped before July 20, 2000

NOTE: SUBSEQUENT TO PUBLISHING A DISCONTINUANCE NOTICE, MOTOROLA WILL ALLOW TWELVE (12) MONTHS FROM THE ANNOUNCEMENT DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS.

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER EIGHTEEN (18) MONTHS BEYOND THE ANNOUNCEMENT DATE.

POSSIBLE REPLACEMENT PARTS

-----

DEVICE	REPLACEMENT
AM26LS30PC	NONE
BM6S2BFEL	NONE
JBL1026MEL	NONE
LM2931ACD2T	NONE, TRY LM2931CT
LM2931ACT	NONE, TRY LM2931CT
LM2931ACTH	NONE, TRY LM2931CT
LM2931ACTV	NONE, TRY LM2931CT
LM2931ADT-1-5.0	NONE, TRY LM2931ADT-5
LM2931CTV	NONE, TRY LM2931CT
LM2935TH	LM2935T
LM2935TV	LM2935T
LM308AD	NONE
LM308ADR2	NONE
LM308AN	NONE
LM317MDT-001	LM317MDT
LMT2901D	LM2901D
LMT2901DR2	LM2901DR2
LMT2901N	LM2901N
LMT2902DR2	LM2902DR2
LMT2903DR2	LM2903DR2
LMT2903N	LM2903N
LMT2904DR2	LM2904DR2
LMT2904N	LM2904N

\*\*\*\*\*

PRODUCT DISCONTINUANCE

\*\*\*\*\*

ISSUE DATE: 08-Feb-1999

NOTIFICATION #:4323

ISSUING DIVISION:PHX-GPPD

LMT324D	LM324D
LMT324DR2	LM324DR2
LMT324N	LM324N
LMT339D	LM339D
LMT339DR2	LM339DR2
LMT339N	LM339N
LMT358DR2	LM358DR2
LMT358N	LM358N
LMT393DR2	LM393DR2
LMT393N	LM393N
LMW308A	NONE
LP2950CDT-5.0RK	LP2950CDT-5.0
LP2950CP-005	LP2950CZ-5.0
LP2951ACD-005	LP2951ACD
LP2951ACD-5R2	LP2951ACDR2
LP2951CD-005	LP2951CD
LP2951CD-5R2	LP2951CDR2
LSC1142P	MC34074P
MC13304T3A	NONE
MC13500T2	NONE
MC13562SP	NONE
MC13573ASP	NONE
MC1436CD	NONE, TRY MC1741CD
MC1436CP1	NONE, TRY MC1741CP1
MC1436P1	NONE, TRY MC1741CP1
MC1496BD	MC1496D
MC1496BDR2	MC1496D
MC1496M	MC1496D
MC14C89BP	NONE
MC33065DW	MC33065DW-H
MC33065P	MC33065P-H
MC33154D	NONE
MC33154DR2	NONE
MC33154P	NONE
MC33202JO	NONE
MC33202JOR2	NONE
MC33347DR2	MC33347ADR2
MC33347DTB	MC33347ADTB
MC33463H-30KT1	RH5R1301B-T1
MC33463H-33KT1	RH5R1331B-T1
MC33463H-33LT1	RH5R1302B-T1
MC33463H-50KT1	RH5R1501B-T1
MC33463H-50LT1	RH5R1502B-T1
MC33464H-09AT1	RH5VT09AA-T1
MC33464H-09CT1	RH5VT09CA-T1
MC33464H-20CT1	RH5VT20CA-T1
MC33464H-27AT1	RH5VT20CA-T1
MC33464H-30AT1	RH5VT30AA-T1

\*\*\*\*\*

PRODUCT DISCONTINUANCE

\*\*\*\*\*

ISSUE DATE: 08-Feb-1999

NOTIFICATION #:4323

ISSUING DIVISION:PHX-GPPD

MC33464H-30CT1	RH5VT30CA-T1
MC33464H-45CT1	RH5VT45CA-T1
MC33466H-30JT1	RH5RH301A-T1
MC33466H-30LT1	RH5RH302B-T1
MC33466H-33JT1	RH5RH331A-T1
MC33466H-33LT1	RH5RH332B-T1
MC33466H-50JT1	RH5RH501A-T1
MC34001BP	TL081ACP
MC34065DW	MC33065DW-H
MC34065DW-LR2	MC33065DW-LR2
MC34065P	MC33065P-H
MC34065P-H	MC33065P-H
MC34066DW	MC33066DW
MC34085BDW	NONE
MC34261D	MC33261D
MC3476P1	NONE, TRY MC1741CP1
MC7806CD2TR4	MC7806BD2TR4
MCT7808CT	MC7808CT
MC78FC28HT1	RH5RE28AA-T1
MC78FC40HT1	RH5RE40AA-T1
MC78L05CP	MC78L05ACP
MC78L08CP	MC78L08ACP
MC78L15CP	MC78L15ACP
MC78M05BDT-001	MC78M05BDT
MC78M05CDT-001	MC78M05CDT
MC78M12CDT-001	MC78M12CDT
MC78M15CDT-001	MC78M15CDT
MC7915ACD2TR4	MC7915ACD2T
MC79L12CP	MC79L12ACP
MC79M05CDT-001	MC79M05CDT
MC79M15BDT-001	MC79M15BDT
MC79M15CDT-001	MC79M15CDT
MCCS142237DW	NONE
MCT1413BP	MC1413BP
MCT1413P	MC1413P
MCT1458CD	MC1458CD
MCT1458CP1	MC1458CP1
MCT1458D	MC1458D
MCT1458DR2	MC1458DR2
MCT1458P1	MC1458P1
MCT4558CD	MC4558CD
MCT7805CD2T	MC7805CD2T
MCT7805CT	MC7805CT
MCT7809BT	MC7809BT
MCT7812CT	MC7812CT
MCT7815CT	MC7815CT
NE555N	MC1455P1
NE556D	MC3456P

\*\*\*\*\*

PRODUCT DISCONTINUANCE

\*\*\*\*\*

ISSUE DATE: 08-Feb-1999

NOTIFICATION #:4323

ISSUING DIVISION:PHX-GPPD

NE556DR2	MC3456P
NE556N	MC3456P
SC111686P	NONE
SC111951ADR2	NONE
SC2951ACDM-3.3	LP2951ACDM-3.3R2
SC34164DM-003	MC34164DM-3R2
SC34164DM-3R2	MC34164CM-3R2
SC371072FEL	NONE
SC74730D1R2	LM201AD
SC74761D1R2	LM358DR2
SC77682PK	LM324N
SC78L05ACDR2	MC78L05ACDR2
SC78M09HT	MC78M09CT
SC79021P	LM2931AZ-5.0
SC79021P-001	LM2931AZ-5.0
SC79055P	MC33063AP1
SC79058P	NONE
SC79123DR2	MC33178DR2
SC79141DR2	NONE
SC79219P	UC3845N
SC79804-3DR2	MC3303DR2
SC901012T	NONE
SDC5100R1	SDC5100R2
SCT78108P5	MC7805CT
TL071ACP	TL081ACP
TL071CD	TL081CD
TL071CDR2	TL081CDR2
TY30486	NONE
TY30508	LM2904
TY30542R2	LM339AD

FILE FORMAT: ASCII TEXT

FONT - Courier

SIZE - 12 Point

LINE - 70 characters/line

PAGE - 55 lines/page

PAGEBREAK CHARACTER - ^L (Control L)

AFCTD DEVICE (W/O SPECIALS) ,FORMAT: PN, REPL MOT PN, NON MOT INFO

-----  
AM26LS30PC , ,  
BM6S2BFEL , ,  
JBL1026MEL , ,  
LM2931ACD2T , ,  
LM2931ACT , ,  
LM2931ACTH , ,  
LM2931ACTV , ,  
LM2931ADT-1-5.0 , ,  
LM2931CTV , ,  
LM2935TH , ,  
LM2935TV , ,  
LM308AD , ,  
LM308ADR2 , ,  
LM308AN , ,  
LM317MDT-001 , ,  
LMT2901D , ,  
LMT2901DR2 , ,  
LMT2901N , ,  
LMT2902DR2 , ,  
LMT2903DR2 , ,  
LMT2903N , ,  
LMT2904DR2 , ,  
LMT2904N , ,  
LMT324D , ,  
LMT324DR2 , ,  
LMT324N , ,  
LMT339D , ,  
LMT339DR2 , ,  
LMT339N , ,  
LMT358DR2 , ,  
LMT358N , ,  
LMT393DR2 , ,  
LMT393N , ,  
LMW308A , ,  
LP2951CD-005 , ,  
LP2951CD-5R2 , ,  
MC13304T3A , ,  
MC13500T2 , ,  
MC13562SP , ,  
MC13573ASP , ,  
MC1436CD , ,  
MC1436CP1 , ,  
MC1436P1 , ,  
MC1496BD , ,  
MC1496BDR2 , ,  
MC1496M , ,  
MC14C89BP , ,  
MC33065DW , ,  
MC33065P , ,  
MC33154D , ,  
MC33154DR2 , ,  
MC33154P , ,  
MC33202JO , ,  
MC33202JOR2 , ,  
MC33347DR2 , ,

\*\*\*\*\*

PRODUCT DISCONTINUANCE

\*\*\*\*\*

ISSUE DATE: 08-Feb-1999

NOTIFICATION #:4323

ISSUING DIVISION:PHX-GPPD

MC33347DTB	,	,
MC33463H-30KT1	,	,
MC33463H-33KT1	,	,
MC33463H-33LT1	,	,
MC33463H-50KT1	,	,
MC33463H-50LT1	,	,
MC33464H-09AT1	,	,
MC33464H-09CT1	,	,
MC33464H-20CT1	,	,
MC33464H-27AT1	,	,
MC33464H-30AT1	,	,
MC33464H-30CT1	,	,
MC33464H-45CT1	,	,
MC33466H-30JT1	,	,
MC33466H-30LT1	,	,
MC33466H-33JT1	,	,
MC33466H-33LT1	,	,
MC33466H-50JT1	,	,
MC34001BP	,	,
MC34065DW	,	,
MC34065DW-LR2	,	,
MC34065P	,	,
MC34065P-H	,	,
MC34066DW	,	,
MC34085BDW	,	,
MC34261D	,	,
MC3476P1	,	,
MC7806CD2TR4	,	,
MC78FC28HT1	,	,
MC78FC40HT1	,	,
MC78L05CP	,	,
MC78L08CP	,	,
MC78L15CP	,	,
MC78M05BDT-001	,	,
MC78M05CDT-001	,	,
MC78M12CDT-001	,	,
MC78M15CDT-001	,	,
MC7915ACD2TR4	,	,
MC79L12CP	,	,
MC79M05CDT-001	,	,
MC79M15BDT-001	,	,
MC79M15CDT-001	,	,
MCCS142237DW	,	,
MCT1413BP	,	,
MCT1413P	,	,
MCT1458CD	,	,
MCT1458CP1	,	,
MCT1458D	,	,

\*\*\*\*\*

PRODUCT DISCONTINUANCE

\*\*\*\*\*

ISSUE DATE: 08-Feb-1999  
ISSUING DIVISION:PHX-GPPD

NOTIFICATION #:4323

MCT1458DR2	,	,
MCT1458P1	,	,
MCT4558CD	,	,
MCT7805CD2T	,	,
MCT7805CT	,	,
MCT7808CT	,	,
MCT7809BT	,	,
MCT7812CT	,	,
MCT7815CT	,	,
NE555N	,	,
NE556D	,	,
NE556DR2	,	,
NE556N	,	,
SC111951ADR2	,	,
SC34164DM-3R2	,	,
SC371072FEL	,	,
SC78L05ACDR2	,	,
SC78M09HT	,	,
SC79804-3DR2	,	,
SC901012T	,	,
TL071ACP	,	,
TL071CD	,	,
TL071CDR2	,	,
TY30486	,	,
TY30542R2	,	,
TY30542R2	,	,