



UPDATE CHANGE NOTIFICATION # 16546

Generic Copy

Issue Date: 19-Nov-2010

TITLE: Assembly Location Correction to FPCN #16390

PROPOSED FIRST SHIP DATE: 21-Apr-2010

AFFECTED CHANGE CATEGORY(S): Subcontractor Assembly and Test site

ADDITIONAL RELIABILITY DATA: N/A

SAMPLES: Contact your local ON Semiconductor Sales Office

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:


Contact your local ON Semiconductor Sales Office or Scott Brow <Scott.Brow@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

This is to notify customers of an error in FPCN #16390. The assembly location code for Unisem Batam should be 5 and not C as was listed in the original PCN.



A = 5 (Unisem Batam, Indonesia)



UPDATE CHANGE NOTIFICATION #16546

List of affected General Parts:

MC33262DG
MC33262DR2G
UC2842BD1G
UC2842BD1R2G
UC2843BD1G
UC2843BD1R2G
UC2844BD1R2G
UC2845BD1G
UC2845BD1R2G
UC3842BD1G
UC3842BD1R2G
UC3843BD1G
UC3843BD1R2G
UC3843BVD1G
UC3843BVD1R2G
UC3844BD1G
UC3844BD1R2G
UC3845BD1G
UC3845BD1R2G
UC3845BVD1G
UC3845BVD1R2G