



UPDATE CHANGE NOTIFICATION # 16789

Generic Copy

Issue Date: 09-Mar-2012

TITLE: Update Notification to Previous Issued FPCN16789 (Announcement of alternative product delivery associated with SSTH - Sanyo Semiconductor Thailand flood damage)

PROPOSED FIRST SHIP DATE: 30-Apr-2012 (or earlier with customer approval)

AFFECTED CHANGE CATEGORY(S): Updating Contact Names

ADDITIONAL RELIABILITY DATA: Not Applicable (see original FPCN16789)

SAMPLES: Contact your local ON Semiconductor Sales Office

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION: Contact your local ON Semiconductor Sales Office.

For affected devices below in Group A thru Group H (see original FPCN16789), contact Tetsuya.Ishizuka@onsemi.com

For affected devices in Group I and Group J (see original FPCN16789), contact Toshikazu.Hirai@onsemi.com.

SAMPLES: Contact your local ON Semiconductor Sales Office or Akira.Yoneyama@onsemi.com

ADDITIONAL RELIABILITY DATA: Contact your local ON Semiconductor Sales Office.

For affected devices below in Group A thru Group H (see original FPCN16789), contact Shoji.Suematsu@onsemi.com

For affected devices in Group I and Group J (see original FPCN16789), contact Osamu.Ishihara@onsemi.com

DESCRIPTION AND PURPOSE:

The purpose of this Update Notification is to just correct a contact email name and address.

Wrong/Incorrect: Tetsuo.Ishizuka@onsemi.com (identified on the original FPCN16789)

Correct: Tetsuya.Ishizuka@onsemi.com

All other information and data remains the same as originally issued in FPCN16789.



UPDATE CHANGE NOTIFICATION #16789

List of affected General Parts:

Group A (Parts transferring from SSTH – Sanyo Semiconductor Thailand to KSS – Kanto Sanyo Semiconductor)

CHANGED PART IDENTIFICATION: Identified by marking lot number

LB8649W-MPB-E	LV5609LP-E	LC75852W-TLM-E
LB8649W-TBM-E	LV5609LP-TE-L-E	LC75853NW-E
LV8018W-MPB-E	LV8402GP-TE-L-H	LC75853NW-TLM-E
LC08900PW-A-TLM-E	LB1938T-TLM-E	LC75854WHS-USV-TLM-E
LV24100LP-TLM-E	LB1938T-TLM-H	LC75854W-TLM-E
LV8044LP-MPB-E	LC75841PEH-UGN-TFM-H	LC75857W-E
LA6581T-TE-L-E	LC75841PEHUGN-TH	LC75412EH-E
LA6585T-TLM-E	LC75834JEHS-USL-E	LC75412E-UHK-E
LA6595T-TLM-E	LC75834W-E	LC75725E-E
LB1941T-TLM-E	LC75834WHS-TLM-E	LC75725EHS-E
LV8075LP-TE-L-E	LC75836WH-E	LC75725E-TLA-E
LV8080LP-TE-L-E	C75854WHS-USV-LE	LC75821E-E
LV8413GP-E	LC75824W-E	LC75822E-E
LV8413GP-TE-L-E	LC75832WS-E	LC75822EHS-T-E
LV8413GP-TE-L-H	LC75852W-E	

Group B (Parts transferring from SSTH – Sanyo Semiconductor Thailand to SSMP – Sanyo Semiconductor Manufacturing Philippines)

CHANGED PART IDENTIFICATION: Identified by marking lot number

LC75832E-E

Group C (Parts transferring from SSTH – Sanyo Semiconductor Thailand to SSMP – Sanyo Semiconductor Manufacturing Philippines (Including materials))

CHANGED PART IDENTIFICATION: Identified by marking lot number

LB1836M-MPB-E
LB1836M-TLM-E

Group D (Parts transferring from SSTH – Sanyo Semiconductor Thailand to Amkor Technology)

CHANGED PART IDENTIFICATION: Identified by marking Part number

Current Part Number	NEW Part Number
LV8747T-TLM-E	LV8747TA-AE



UPDATE CHANGE NOTIFICATION #16789

Group E (Parts transferring from SSTH – Sanyo Semiconductor Thailand to Aoi Electronics)

CHANGED PART IDENTIFICATION: Identified by marking Part number

Current Part Number	NEW Part Number
LC72131KM-TLM-E	LC72131KMA-AE

Group F (Parts transferring from SSTH – Sanyo Semiconductor Thailand to J-Devices Corporation)

CHANGED PART IDENTIFICATION: Identified by marking Part number

Current Part Number	NEW Part Number
LA1844M-TLM-E	LA1844MC-AH
LC72121M-TLM-E	LC72121MA-AH

Group G (Parts transferring from SSTH – Sanyo Semiconductor Thailand to OSPI – ON Semiconductor, Philippines)

CHANGED PART IDENTIFICATION: Identified by marking Part number

Current Part Number	NEW Part Number
LA5735M-TLM-E	LA5735MC-AH
LA4537M-TE-L-E	LA4537MC-BH
LB1638M-TLM-E	LB1638MC-AH
LB1830M-TLM-E	LB1830MC-AH
LB1848M-TE-R-E	LB1848MC-GH
LB1848M-TLM-E	LB1848MC-AH
LB1848M-TRM-H	LB1848MC-FH
LB1909M-TE-L-E	LB1909MC-BH
LB1930M-TLM-E	LB1930MC-AH
LB1962M-TLM-E	LB1962MC-AH
LV8548M-TLM-H	LV8548MC-AH
LV8549M-TLM-H	LV8549MC-AH
ICC3-TLM-E	ICC3-FP-AH
LA1178M-TLM-E	LA1178MC-SHR-AH
LA1235M-TLM-E	LA1235MC-SHR-AH
LA3335M-TLM-E	LA3335MC-SHR-AH
LA1225M-TLM-E	LA1225MC-AH

Group H (Parts transferring from SSTH – Sanyo Semiconductor Thailand to Taihei Electronics Co., Ltd.)

CHANGED PART IDENTIFICATION: Identified by marking Part number

Current Part Number	NEW Part Number
LB1846M-TLM-E	LB1846MC-AH
LB1862M-TLM-E	LB1862MC-AH
LB1948M-TE-L-E	LB1948MC-BH



UPDATE CHANGE NOTIFICATION #16789

Group I (Parts transferring from SSTH – Sanyo Semiconductor Thailand to SP Semiconductor & Communication Co., Ltd.)

CHANGED PART IDENTIFICATION:

As a mean of the identification, we will add the suffix “-1EX”.

Current Part Number	NEW Part Number (adding suffix -1EX)
2SA2099	2SA2099-1EX
2SC5888	2SC5888-1EX
2SC6082	2SC6082-1EX
2SJ652	2SJ652-1EX
2SJ656	2SJ656-1EX
2SK3703	2SK3703-1EX
2SK3704	2SK3704-1EX
2SK3745LS	2SK3745LS-1EX
2SK3746	2SK3746-1EX
2SK3747-MG8	2SK3747-1EX
2SK3748	2SK3748-1EX
2SK4085LS	2SK4085LS-1EX
2SK4124	2SK4124-1EX
2SK4125	2SK4125-1EX
2SK4177-DL-E	2SK4177-DL-1EX
2SK4210	2SK4210-1EX
BBS3002-DL-E	BBS3002-DL-1EX
SBA120-18J	SBA120-18JS-1EX
SBR100-10J	SBR100-10JS-1EX
SBR100-16JS	SBR100-16JS-1EX
SBR160-10J	SBR160-10JS-1EX
SBR200-16JS	SBR200-16JS-1EX
SBT100-16JS	SBT100-16JS-1EX
SBT150-04J	SBT150-04JS-1EX
SBT150-06J	SBT150-06JS-1EX
SBT250-04J	SBT250-04JS-1EX
SBT250-06J	SBT250-06JS-1EX
SBT350-06J	SBT350-06JS-1EX
SBT80-04J	SBT80-04JS-1EX
SBT80-06LS	SBT80-06JS-1EX
SBT80-10LS	SBT80-10JS-1EX

Group J (Parts transferring from SSTH – Sanyo Semiconductor Thailand to GEM Electronics, Shanghai, Co., Ltd.)

CHANGED PART IDENTIFICATION:

As a mean of the identification, we will add the suffix -2HX.

Current Part Number	NEW Part Number (adding suffix -2HX)
TND027SW-TL-E	TND027SW-TL-2HX