ABSOCIATION CONNECTING ELECTRONICS INDUSTRIES® INCLUSTRIES®	C. Bannockb	ourn. Illinois. A	ll rights reserved u ntions.	nder both	This docum level parts, t	ent is a declaratio the declaration en	n of the substand compasses all lo	es within the manufactur wer level materials for w	rer listed it hich the m	tem. Note: if nanufacturer	the item is an as has engineering	sembly with lower responsibility.	
				Form Type Distribute	e * Declaration Class * Class 6 - RoHS Yes/No, Homogeneous Materials and Mfg Information					on			
Supplier Information													
Company name* Company			unique ID			Unique ID Authority				Response Date*			
onsemi						l l				2024-05-18			
Contact Name Title - Contact			ct			Phone - Contact*			Email - Contact*				
Product-Env-Stewards Product Envir			viro Compliance			NA			Product-Env-Stewards@onsemi.com				
Authorized Representative* Title - Repre			esentative			Phone - Representative*			Email - Representative*				
Product-Env-Stewards Product			duct Enviro Compliance			NA			Product-Env-Stewards@onsemi.com				
Requester Item Number	Mfr Item Number		Mfr Item Name			Effective Date	Version	Manufacturing Site		Weight*	UOM	Unit Type	
	FZT790A	FZT790A 40V 3A PNP LOV		W SAT BJT		2024-05-18 MY1		-	118.432	mg	Each		
Manufacturing Proccess Informat	ion												
Terminal Plating / Grid Array Ma	Terminal Plating / Grid Array Material Terminal Base Allo		Alloy J	-STD-020 MSL	Rating	Peak Proces	s Body Tempera	ture Max Time at Peak	Temperat	ure Numbe	er of Reflow Cyc	les	
Matte Tin (Sn) - annealed CU Alloy			1	l		260	С	30	secon	ds 3			
Comments													
evel 1 - maximum time at peak temperatu	re during sol	dering is 10-3	0 seconds										
for more information regarding material	composition	please refer to	page 3										

RoHS Material Composition Declaration				Declaration Type *	Detailed						
Directive 2015/863/EU amending RoHS Directive 2011/65/EU	RoHS Definition: Quantity limit of 0.01% by mass (100 PPM) in homogeneous material for Cadmium and quantity limit of 0.1% by mass (1000 PPM) in homogeneous material for: Lead (Pb), Mercury (Hg), Hexavalent Chromium (Cr6+), Polybrominated Biphenyls (PBB), Polybrominated Diphenyl Ethers (PBDE), and Bis(2-ethylhexyl) phthalate (DEHP), Benzyl-butyl phthalate (BBP), Dibutyl phthalate (DBP), Disobutyl phthalate (DIBP).										
cadmium, hexavalentchromium, polybrominate contains a RoHS restricted substance inexcess encompass all such components. Supplier certif as of the date that Supplier completes this form Company acknowledges that Supplier may hav independently verified information provided by certification in this paragraph. If the Company a	ed biphenyls and/or polybrominated dip of an applicable quantity limit, please ir ies that it gathered the information it pro- .Supplier acknowledges that Company e relied on informationprovided by othe v others, Supplier agrees that, at a minin and the Supplier enter into a written agre pource of the Supplier's liability and the	henyl ethers (each a " ndicate below which, i ovides in this form us will rely on this certifiers in completing this num, itssuppliers have eement with respect to Company's remedies	RoHS restricted substance") in exce if any, RoHS exemption you believe ing appropriate methods to ensure if ication in determining the complian form, and that Supplier may not have e provided certifications regarding the to the identified part, the terms and co for issues that arise regarding inform	ce of its products with European Union membe	ove. If a homogeneous material within the part er level components, the declaration shall l correct to the best of its knowledge and belief, r state laws that implement the RoHS Directive. wever, in situations where Supplier has not tions are at least as comprehensive as the anty rights and/or remedies provided as part of						
RoHS Declaration * 1 - Item(s)	does not contain RoHS restricted substa	on above	Supplier Acceptance	* Accepted							
Exemption: If the declared item does not con applicable exemptions.	ntain RoHS restricted substances per	the definition above	except for defined RoHS exempti	ons, then select the corresponding response i	n the RoHS Declaration above and choose all						
Exemption List Version	EL-2011/534/EU										
Declaration Signature											
Instructions: Complete all of the required fin Requester) and click on Submit Form to have	elds on all pages of this form. Select the form returned to the Requester	he "Accepted" on th	e Supplier Acceptance drop-down	. This will display the signature area. Digital	lly sign the declaration (if required by the						
Supplier Digital Signature Ra	stislav Drska	Le									

## Homogeneous Material Composition Declaration for Electronic Products

SubItem Instructions: The presence of any JIG Level A or B substances must be declared. [1] indicate the subpart in which the substance is located, [2] provide a description of the homogeneous material [3], enter the weight of the homogeneous material.

signa range of distribution diffess otherwise noted).									
Homogeneous Material	Weight	Unit of Measure	Level	Substance	CAS	Exempt	Weight	Unit of Measure	
Die	1.54	mg	Supplier	Silicon (Si)	7440-21-3		1.54	mg	
Lead Frame	66.944	mg	Supplier	Silver (Ag)	7440-22-4		0.234	mg	
			Supplier	Zinc (Zn)	7440-66-6		0.08	mg	
			Supplier	Iron (Fe)	7439-89-6		1.61	mg	
			Supplier	Copper (Cu)	7440-50-8		65	mg	
			Supplier	Phosphorus (P)	7723-14-0		0.02	mg	
Mold Compound-Black	41.108	mg	В	Brominated Bisphenol A Diglycidyl Ether	40039-93-8		0.4111	mg	
			Supplier	Ortho Cresol Novolac Resin	29690-82-2		6.1662	mg	
			В	Antimony Trioxide (Sb2O3)	1309-64-4		1.0277	mg	
			Supplier	Fused Silica (SiO2)	60676-86-0		30.0088	mg	
			Supplier	Silica (SiO2)	14464-46-1		0.2055	mg	
			Supplier	Phenolic Resin (Novolac)	9003-35-4		3.0831	mg	
			Supplier	Silica Crystalline (SiO2)	14808-60-7		0.2055	mg	
Plating	8.29	mg	Supplier	Tin (Sn)	7440-31-5		8.29	mg	
Wire Bond - Au	0.55	mg	Supplier	Gold (Au)	7440-57-5		0.55	mg	

Substance Instructions: [A] select the Level (JIG A, JIG B, Requester or Supplier) [B] select the substance category (JIG or Requester) or enter a value (Supplier). [C] select the substance (JIG) or enter the substance and CAS (Other). [D] select a RoHS exemption, if applicable [E] enter the weight of the substance or the PPM concentration [F] Optionally enter the positive (+) and negative (-) tolerance in percent (Note: percent tolerance values are expected to cover a 3 sigma range of distribution unless otherwise noted).