ON Semiconductor



PRODUCT BULLETIN Generic Copy

12-MAY-2005

SUBJECT: ON Semiconductor Product Bulletin #14077

TITLE: NCP582 and NCP583 Change the Suffix from "T1" to "T2" for SOT563 Package

EFFECTIVE DATE: 12-May-2005

AFFECTED PRODUCT DIVISION: Analog Products

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor sales office or Beatriz Lofts <FFBGFX@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact your local ON Semiconductor sales office.

DESCRIPTION AND PURPOSE:

ON Semiconductor has identified a mis-match issue with the actual product tape and reel suffix versus the product tape specification (BRD8011) for the SOT563 package of NCP582 and NCP583 devices. A different suffix "T2" should be used instead of "T1" in order to match the actual tape orientation and the tape & reel specification. We apologize for any inconvenience that this has caused.

AFFECTED DEVICE LIST(WITHOUT SPECIALS):

PART NCP582DXV15T1G NCP582DXV18T1G NCP582DXV25T1G NCP582DXV28T1G NCP582DXV29T1G NCP582DXV30T1G NCP582DXV30T1G NCP582DXV33T1G NCP582LXV15T1G NCP582LXV18T1G NCP582LXV25T1G NCP582LXV28T1G NCP582LXV29T1G

Issue Date: 12 May, 2005

ON Semiconductor



Product Bulletin #14077

NCP582LXV30T1G NCP582LXV33T1G NCP583XV15T1G NCP583XV18T1G NCP583XV25T1G NCP583XV28T1G NCP583XV29T1G NCP583XV29T1G NCP583XV30T1G NCP583XV33T1G