

**ON Semiconductor**  
Formerly a Division of Motorola



Subject: Motorola PRODUCT BULLETIN 4595

TITLE: SECTOR MATERIALS ORGANIZATION (SMO) CLOSURE (PART 7 OF 8)

EFFECTIVE DATE: 05-APR-99

AFFECTED CHANGE CATEGORIES

AFFECTED PRODUCT DIVISIONS

GENERAL PURPOSE PRO POWER PRODUCTS DIV OPTO SIGNAL DIV

ADDITIONAL RELIABILITY DATA: None

Ref:

SAMPLES: No

Ref:

For any questions concerning this notification:

REFERENCE:ED BRZEZINSKI

PHONE: 602-244-4575

DISCLAIMER:

MOTOROLA CONSIDERS THIS CHANGE APPROVED UNLESS SPECIFIC CONDITIONS OF ACCEPTANCE ARE PROVIDED IN WRITING. TO DO SO, CONTACT YOUR LOCAL MOTOROLA SALES OFFICE.

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.

\*\*\*\*\*

PRODUCT BULLETIN

\*\*\*\*\*

ISSUE DATE: 10-Apr-1999

NOTIFICATION #:4595

EFFECTIVE DATE: 05-Apr-1999

ISSUING DIVISION:PHX-PPD

DESCRIPTION AND PURPOSE

-----

\*\*\*\*\*ATTENTION\*\*\*\*\*

This Product Bulletin (PB) is part of eight PBs covering the Sector Materials Organization Closure. This was originally intended to be released on one PB, but due to size limitations, it had to be divided by technology codes. Some customers may receive what appears to be the same PB multiple times, but the device list will be different on each PB: 4575, 4590, 4591, 4592, 4593, 4594, 4595 and 4596.

Motorola Semiconductor Products Sector is currently going through realignment of its manufacturing resources. The Silicon Materials Organization (SMO) in Phoenix, Arizona, originally opened in 1958, and is currently scheduled to be closed by the end of June 1999. Silicon wafers currently provided by this facility will transfer to previously qualified sources or to Mitsubishi Silicon America's (MSA) production facility at its headquarters in Salem, Oregon. MSA, one of the top six global silicon materials suppliers, was chosen for its global technological and logistic capabilities. MSA has been an approved silicon supplier to Motorola for over 5 years. The transfer will occur after significant technology transfer and Motorola internal evaluation and qualification. This qualification process has been designed to help make the transfer seamless to our customers.

FILE FORMAT: ASCII TEXT

FONT - Courier

SIZE - 12 Point

LINE - 70 characters/line

PAGE - 55 lines/page

PAGEBREAK CHARACTER - ^L (Control L)

AFFECTED DEVICE LIST (WITHOUT SPECIALS)

-----

1.5SMC10AT3	, 1.5SMC12AT3	, 1.5SMC13AT3	, 1.5SMC15AT3
1.5SMC16AT3	, 1.5SMC18AT3	, 1.5SMC20AT3	, 1.5SMC22AT3
1.5SMC24AT3	, 1.5SMC27AT3	, 1.5SMC30AT3	, 1.5SMC33AT3
1.5SMC36AT3	, 1.5SMC39AT3	, 1.5SMC43AT3	, 1.5SMC47AT3
1.5SMC51AT3	, 1.5SMC56AT3	, 1.5SMC6.8AT3	, 1.5SMC62AT3
1.5SMC68AT3	, 1.5SMC7.5AT3	, 1.5SMC75AT3	, 1.5SMC8.2AT3
1.5SMC82AT3	, 1.5SMC91AT3	, 1N4728A	, 1N4728ARL
1N4728ATA	, 1N4729A	, 1N4729ARL	, 1N4730A
1N4730ARL	, 1N4730ATA	, 1N4731A	, 1N4731ARL
1N4732A	, 1N4732ARL	, 1N4732ATA	, 1N4733A
1N4733ARL	, 1N4733ATA	, 1N4733ATA2	, 1N4733CRL
1N4733DRL	, 1N4734A	, 1N4734ARL	, 1N4734C
1N4734DRL	, 1N4735A	, 1N4735ARL	, 1N4735ATA
1N4736A	, 1N4736ARL	, 1N4736ATA	, 1N4737A
1N4737ARL	, 1N4737ATA	, 1N4737CRL	, 1N4737D
1N4738A	, 1N4738ARL	, 1N4738ATA	, 1N4739A
1N4739ARL	, 1N4739ATA	, 1N4739C	, 1N4740A
1N4740ARL	, 1N4740ATA	, 1N4740CRL	, 1N4740D
1N4741A	, 1N4741ARL	, 1N4741ATA	, 1N4742A
1N4742ARL	, 1N4742ATA	, 1N4742CRL	, 1N4742D
1N4743A	, 1N4743ARL	, 1N4743ATA	, 1N4743CRL
1N4743DRL	, 1N4744A	, 1N4744ARL	, 1N4744ATA
1N4744C	, 1N4744D	, 1N4745A	, 1N4745ARL
1N4745ATA	, 1N4745C	, 1N4745CRL	, 1N4746A
1N4746ARL	, 1N4746ATA	, 1N4747A	, 1N4747ARL
1N4747ATA	, 1N4748A	, 1N4748ARL	, 1N4748ATA
1N4748C	, 1N4749A	, 1N4749ARL	, 1N4749ATA
1N4750A	, 1N4750ARL	, 1N4750ATA	, 1N4751A
1N4751ARL	, 1N4751ATA	, 1N4752A	, 1N4752ARL
1N4753A	, 1N4753ARL	, 1N4753ATA	, 1N4754A
1N4754ARL	, 1N4754ATA	, 1N4755A	, 1N4755ARL
1N4755ATA	, 1N4756A	, 1N4756ARL	, 1N4757A
1N4757ARL	, 1N4758A	, 1N4758ARL	, 1N4759A
1N4759ARL	, 1N4760A	, 1N4760ARL	, 1N4760ATA
1N4761A	, 1N4761ARL	, 1N4762A	, 1N4762ARL
1N4763A	, 1N4763ARL	, 1N4764A	, 1N4764ARL
1N5913B	, 1N5913BRL	, 1N5917B	, 1N5917BRL
1N5919B	, 1N5919BRL	, 1N5920B	, 1N5920BRL
1N5921B	, 1N5921BRL	, 1N5923B	, 1N5923BRL
1N5924B	, 1N5924BRL	, 1N5925B	, 1N5925BRL
1N5926B	, 1N5927B	, 1N5927BRL	, 1N5929B
1N5929BRL	, 1N5930B	, 1N5930BRL	, 1N5931B
1N5931BRL	, 1N5932B	, 1N5932BRL	, 1N5933B
1N5934B	, 1N5934BRL	, 1N5935B	, 1N5936B
1N5936BRL	, 1N5937B	, 1N5937BRL	, 1N5938B
1N5940BRL	, 1N5941B	, 1N5941BRL	, 1N5942BRL
1N5943B	, 1N5943BRL	, 1N5944B	, 1N5944BRL
1N5945B	, 1N5946B	, 1N5946BRL	, 1N5947BRL
1N5948B	, 1N5948BRL	, 1N5950B	, 1N5950BRL
1N5951B	, 1N5951BRL	, 1N5952BRL	, 1N5953B
1N5953BRL	, 1N5954BRL	, 1N5955B	, 1N5955BRL
1N5956B	, 1N5956BRL	, 1SMB100AT3	, 1SMB10AT3
1SMB110AT3	, 1SMB11AT3	, 1SMB120AT3	, 1SMB12AT3
1SMB130AT3	, 1SMB13AT3	, 1SMB14AT3	, 1SMB150AT3
1SMB15AT3	, 1SMB16AT3	, 1SMB170AT3	, 1SMB17AT3
1SMB18AT3	, 1SMB20AT3	, 1SMB22AT3	, 1SMB24AT3
1SMB26AT3	, 1SMB28AT3	, 1SMB30AT3	, 1SMB33AT3
1SMB36AT3	, 1SMB40AT3	, 1SMB43AT3	, 1SMB45AT3

\*\*\*\*\*

PRODUCT BULLETIN

\*\*\*\*\*

ISSUE DATE: 10-Apr-1999

NOTIFICATION #:4595

EFFECTIVE DATE: 05-Apr-1999

ISSUING DIVISION:PHX-PPD

1SMB48AT3	, 1SMB5.0AT3	, 1SMB51AT3	, 1SMB54AT3
1SMB58AT3	, 1SMB5913BT3	, 1SMB5914BT3	, 1SMB5915BT3
1SMB5916BT3	, 1SMB5917BT3	, 1SMB5918BT3	, 1SMB5919AT3
1SMB5919BT3	, 1SMB5920BT3	, 1SMB5921BT3	, 1SMB5922BT3
1SMB5923BT3	, 1SMB5924BT3	, 1SMB5925BT3	, 1SMB5926BT3
1SMB5927BT3	, 1SMB5928BT3	, 1SMB5929BT3	, 1SMB5930BT3
1SMB5931BT3	, 1SMB5932BT3	, 1SMB5933BT3	, 1SMB5934BT3
1SMB5935BT3	, 1SMB5936BT3	, 1SMB5937BT3	, 1SMB5938BT3
1SMB5939BT3	, 1SMB5940BT3	, 1SMB5941BT3	, 1SMB5942BT3
1SMB5943BT3	, 1SMB5944BT3	, 1SMB5945BT3	, 1SMB5946BT3
1SMB5947BT3	, 1SMB5948BT3	, 1SMB5949BT3	, 1SMB5950BT3
1SMB5951BT3	, 1SMB5952BT3	, 1SMB5953BT3	, 1SMB5954BT3
1SMB5955BT3	, 1SMB5956BT3	, 1SMB6.0AT3	, 1SMB6.5AT3
1SMB60AT3	, 1SMB64AT3	, 1SMB7.0AT3	, 1SMB7.5AT3
1SMB70AT3	, 1SMB75AT3	, 1SMB8.0AT3	, 1SMB8.5AT3
1SMB85AT3	, 1SMB9.0AT3	, 1SMB90AT3	, 1SMC10AT3
1SMC12AT3	, 1SMC13AT3	, 1SMC14AT3	, 1SMC15AT3
1SMC16AT3	, 1SMC17AT3	, 1SMC18AT3	, 1SMC20AT3
1SMC22AT3	, 1SMC24AT3	, 1SMC26AT3	, 1SMC28AT3
1SMC30AT3	, 1SMC33AT3	, 1SMC36AT3	, 1SMC40AT3
1SMC43AT3	, 1SMC45AT3	, 1SMC48AT3	, 1SMC5.0AT3
1SMC51AT3	, 1SMC54AT3	, 1SMC58AT3	, 1SMC6.0AT3
1SMC6.5AT3	, 1SMC60AT3	, 1SMC64AT3	, 1SMC7.0AT3
1SMC7.5AT3	, 1SMC70AT3	, 1SMC75AT3	, 1SMC78AT3
1SMC8.0AT3	, 1SMC8.5AT3	, 1SMC9.0AT3	, 3EZ10D5
3EZ13D5	, 3EZ15D5RL	, 3EZ16D5RL	, 3EZ18D5
3EZ220D5RL	, 3EZ240D5	, 3EZ240D5RL	, 3EZ24D5
3EZ24D5RL	, 3EZ330D5	, 3EZ360D5	, 3EZ36D5RL
3EZ39D5	, 3EZ4.3D5RL	, 3EZ400D5RL	, 3EZ6.2D5RL
3EZ8.2D5	, 3EZ8.2D5RL	, BZX85B33RL	, BZX85C100RL
BZX85C10RL	, BZX85C12RL	, BZX85C13RL	, BZX85C15RL
BZX85C16RL	, BZX85C18RL	, BZX85C22RL	, BZX85C24RL
BZX85C27RL	, BZX85C30RL	, BZX85C33RL	, BZX85C36RL
BZX85C3V3RL	, BZX85C3V6RL	, BZX85C3V9RL	, BZX85C43RL
BZX85C47RL	, BZX85C4V3RL	, BZX85C4V7RL	, BZX85C56RL
BZX85C5V1RL	, BZX85C5V6RL	, BZX85C62RL	, BZX85C6V2RL
BZX85C6V8RL	, BZX85C75RL	, BZX85C7V5RL	, BZX85C82RL
BZX85C8V2RL	, BZX85C9V1RL	, MMQA12VT1	, MMQA13VT1
MMQA13VT3	, MMQA15VT1	, MMQA18VT1	, MMQA20VT1
MMQA20VT3	, MMQA21VT1	, MMQA22VT1	, MMQA24VT1
MMQA27VT1	, MMQA30VT1	, MMQA33VT1	, MMQA5V6T1
MMQA6V2T1	, MMQA6V2T3	, MMQA6V8T1	, MMSZ10T1
MMSZ11T1	, MMSZ12T1	, MMSZ13T1	, MMSZ15T1
MMSZ16T1	, MMSZ18T1	, MMSZ20T1	, MMSZ22T1
MMSZ24T1	, MMSZ27T1	, MMSZ2V4T1	, MMSZ2V7T1
MMSZ30T1	, MMSZ33T1	, MMSZ36T1	, MMSZ39T1
MMSZ3V0T1	, MMSZ3V0T3	, MMSZ3V3T1	, MMSZ3V3T3
MMSZ3V6T1	, MMSZ3V9T1	, MMSZ43T1	, MMSZ4678T1
MMSZ4679T1	, MMSZ4680T1	, MMSZ4681T1	, MMSZ4681T3
MMSZ4682T1	, MMSZ4683T1	, MMSZ4684T1	, MMSZ4684T3
MMSZ4685T1	, MMSZ4686T1	, MMSZ4687T1	, MMSZ4688T1

\*\*\*\*\*

PRODUCT BULLETIN

\*\*\*\*\*

ISSUE DATE: 10-Apr-1999

NOTIFICATION #:4595

EFFECTIVE DATE: 05-Apr-1999

ISSUING DIVISION:PHX-PPD

MMSZ4688T3	, MMSZ4689T1	, MMSZ4689T3	, MMSZ4690T1
MMSZ4690T3	, MMSZ4691T1	, MMSZ4692T1	, MMSZ4693T1
MMSZ4694T1	, MMSZ4695T1	, MMSZ4696T1	, MMSZ4697T1
MMSZ4698T1	, MMSZ4699T1	, MMSZ4700T1	, MMSZ4701T1
MMSZ4702T1	, MMSZ4703T1	, MMSZ4703T3	, MMSZ4704T1
MMSZ4705T1	, MMSZ4706T1	, MMSZ4707T1	, MMSZ4708T1
MMSZ4709T1	, MMSZ4710T1	, MMSZ4711T1	, MMSZ4711T3
MMSZ4712T1	, MMSZ4713T1	, MMSZ4714T1	, MMSZ4715T1
MMSZ4716T1	, MMSZ4717T1	, MMSZ47T1	, MMSZ4V3T1
MMSZ4V7T1	, MMSZ4V7T3	, MMSZ51T1	, MMSZ5221BT1
MMSZ5222BT1	, MMSZ5223BT1	, MMSZ5224BT1	, MMSZ5225BT1
MMSZ5226BT1	, MMSZ5227BT1	, MMSZ5228BT1	, MMSZ5228BT3
MMSZ5229BT1	, MMSZ5229BT3	, MMSZ5230BT1	, MMSZ5230BT3
MMSZ5231BT1	, MMSZ5231BT3	, MMSZ5232BT1	, MMSZ5233BT1
MMSZ5233BT3	, MMSZ5234BT1	, MMSZ5234BT3	, MMSZ5235BT1
MMSZ5235BT3	, MMSZ5236BT1	, MMSZ5236BT3	, MMSZ5237BT1
MMSZ5237BT3	, MMSZ5238BT1	, MMSZ5239BT1	, MMSZ5239BT3
MMSZ5240BT1	, MMSZ5240BT3	, MMSZ5241BT1	, MMSZ5242BT1
MMSZ5242BT3	, MMSZ5243BT1	, MMSZ5243BT3	, MMSZ5244BT1
MMSZ5245BT1	, MMSZ5245BT3	, MMSZ5246BT1	, MMSZ5246BT3
MMSZ5247BT1	, MMSZ5248BT1	, MMSZ5249BT1	, MMSZ5249BT3
MMSZ5250BT1	, MMSZ5251BT1	, MMSZ5252BT1	, MMSZ5252BT3
MMSZ5253BT1	, MMSZ5254BT1	, MMSZ5255BT1	, MMSZ5255BT3
MMSZ5256BT1	, MMSZ5256BT3	, MMSZ5257BT1	, MMSZ5257BT3
MMSZ5258BT1	, MMSZ5258BT3	, MMSZ5259BT1	, MMSZ5260BT1
MMSZ5261BT1	, MMSZ5261BT3	, MMSZ5262BT1	, MMSZ5263BT1
MMSZ5264BT1	, MMSZ5264BT3	, MMSZ5265BT1	, MMSZ5266BT1
MMSZ5266BT3	, MMSZ5267BT1	, MMSZ5267BT3	, MMSZ5268BT1
MMSZ5269BT1	, MMSZ5270BT1	, MMSZ5272BT3	, MMSZ56T1
MMSZ56T3	, MMSZ5V1T1	, MMSZ5V1T3	, MMSZ5V6T1
MMSZ5V6T3	, MMSZ6026T1	, MMSZ6026T3	, MMSZ6V2T1
MMSZ6V2T3	, MMSZ6V8T1	, MMSZ7V5T1	, MMSZ8V2T1
MMSZ9V1T1	, MZP4729A	, MZP4729ARL	, MZP4734ARL
MZP4735ARL	, MZP4736ATA	, MZP4737ARL	, MZP4738ARL
MZP4740ARL	, MZP4741A	, MZP4741ARL	, MZP4744A
MZP4744ARL	, MZP4745ARL	, MZP4746ARL	, MZP4746ATA
MZP4749ARL	, MZP4749ATA	, MZP4750ARL	, MZP4751ARL
MZP4752ARL	, MZP4753A	, P6SMB100AT3	, P6SMB10AT3
P6SMB110AT3	, P6SMB11AT3	, P6SMB120AT3	, P6SMB12AT3
P6SMB130AT3	, P6SMB13AT3	, P6SMB150AT3	, P6SMB15AT3
P6SMB160AT3	, P6SMB16AT3	, P6SMB180AT3	, P6SMB18AT3
P6SMB200AT3	, P6SMB20AT3	, P6SMB22AT3	, P6SMB24AT3
P6SMB27AT3	, P6SMB30AT3	, P6SMB33AT3	, P6SMB36AT3
P6SMB39AT3	, P6SMB43AT3	, P6SMB47AT3	, P6SMB51AT3
P6SMB56AT3	, P6SMB6.8AT3	, P6SMB62AT3	, P6SMB68AT3
P6SMB7.5AT3	, P6SMB75AT3	, P6SMB8.2AT3	, P6SMB82AT3
P6SMB9.1AT3	, P6SMB91AT3	, SA12CA	, SA12CARL
SA13CA	, SA13CARL	, SA14CA	, SA14CARL
SA150CA	, SA15CA	, SA15CARL	, SA18CA
SA18CARL	, SA20CA	, SA20CARL	, SA24CA
SA24CARL	, SA28CA	, SA30CA	, SA33CARL

\*\*\*\*\*

PRODUCT BULLETIN

\*\*\*\*\*

ISSUE DATE: 10-Apr-1999

NOTIFICATION #:4595

EFFECTIVE DATE: 05-Apr-1999

ISSUING DIVISION:PHX-PPD

SA36CA	,	SA43CA	,	SA43CARL	,	SA45CARL
SA48CA	,	SA48CARL	,	SA6.0CA	,	SA6.0CARL
SA6.5C	,	SA6.5CA	,	SA6.5CARL	,	SA60CARL
SA64CA	,	SA7.0CA	,	SA7.5CA	,	SA7.5CARL
SA78CA	,	SA8.5CARL	,	SA85CA	,	SMQA1001T1
SMQA1002T1	,	SZG40175RL				