

ON Semiconductor
Formerly a Division of Motorola



Subject: Motorola PRODUCT BULLETIN 4794

TITLE: ALTERNATE COVER TAPE SUPPLIER FOR D-PAK TAPE/REEL DEVICES

EFFECTIVE DATE: 09-JUN-99

AFFECTED CHANGE CATEGORIES

AFFECTED PRODUCT DIVISIONS
OPTO SIGNAL DIV

ADDITIONAL RELIABILITY DATA: None

Ref:

SAMPLES: No

Ref:

For any questions concerning this notification:

REFERENCE: MARK WASILEWSKI PHONE: 602-244-5114

DISCLAIMER:

MOTOROLA CONSIDERS THIS CHANGE APPROVED UNLESS SPECIFIC CONDITIONS
OF ACCEPTANCE ARE PROVIDED IN WRITING. TO DO SO, CONTACT YOUR LOCAL
MOTOROLA SALES OFFICE.

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.

PRODUCT BULLETIN

ISSUE DATE: 08-Jun-1999

NOTIFICATION #:4794

EFFECTIVE DATE: 09-Jun-1999

ISSUING DIVISION:PHX-OSPD

DESCRIPTION AND PURPOSE

Motorola SCG will add an alternate supplier of cover tape for D-Pak tape/reel devices.

Reason for alternate supplier is to minimize or eliminate delivery issues to customers due to unavailability of material from our supplier.

This bulletin affects only the cover tape of D-Pak packages supplied on tape/reel, not the pocket tape or reel components.

Motorola has completed aging tests verified with peel strength measurements, peel strength Cpk's, material properties, drop tests, and interchangeability tests and confirmed no significant differences.

Customer should encounter no issues with machine capabilities, however, the appearance of the tape is different, lighter in color.

FILE FORMAT: ASCII TEXT

FONT - Courier

SIZE - 12 Point

LINE - 70 characters/line

PAGE - 55 lines/page

PAGEBREAK CHARACTER - ^L (Control L)

AFFECTED DEVICE LIST (WITHOUT SPECIALS)

BUD42D	, BUD42D-001	, BUD43B	, BUD43B-001
BUD43D2	, BUD43D2-001	, BUD43D2T4	, BUD44D2-001
JDX3001T4	, JDX3002T4	, JDX3003	, JDX3003T4
JDX5011T4	, MAC4DCM-001	, MAC4DCMT4	, MAC4DCN-001
MAC4DCNT4	, MAC4DHM-001	, MAC4DHMT4	, MAC4DLM-001
MAC4DLMT4	, MAC4DSM-001	, MAC4DSMT4	, MAC4DSN-001
MAC4DSNT4	, MBRD1035CTL	, MBRD1035CTLT4	, MBRD320
MBRD320RL	, MBRD320T4	, MBRD330	, MBRD330RL
MBRD330T4	, MBRD340RL	, MBRD340T4	, MBRD350
MBRD350RL	, MBRD350T4	, MBRD360	, MBRD360-001
MBRD360RL	, MBRD360T4	, MBRD620CTT4	, MBRD630CTT4
MBRD640CT	, MBRD640CTT4	, MBRD650CT	, MBRD650CT1
MBRD650CTT4	, MBRD660CT	, MBRD660CT1	, MBRD660CTRL
MBRD660CTT4	, MBRD835L	, MBRD835LT4	, MCR12DCMT4
MCR12DCNT4	, MCR12DSMT4	, MCR12DSNT4	, MCR703ARL
MCR703AT4	, MCR704ARL	, MCR704AT4	, MCR706ARL
MCR706AT4	, MCR708A	, MCR708A1	, MCR708AT4
MCR716T4	, MCR718RL	, MCR718T4	, MCR8DCMT4
MCR8DCNT4	, MCR8DSMT4	, MCR8DSNT4	, MJD112
MJD112-001	, MJD112RL	, MJD112T4	, MJD117
MJD117-001	, MJD117T4	, MJD122	, MJD122T4
MJD127	, MJD127T4	, MJD128T4	, MJD148T4
MJD18002D2T4	, MJD200	, MJD200-001	, MJD200RL
MJD200T4	, MJD210	, MJD210RL	, MJD210T4
MJD243	, MJD243T4	, MJD253T4	, MJD2955
MJD2955-001	, MJD2955T4	, MJD3055	, MJD3055T4
MJD31C	, MJD31C1	, MJD31CRL	, MJD31CT4
MJD31T4	, MJD32C	, MJD32C1	, MJD32CRL
MJD32CT4	, MJD32RL	, MJD32T4	, MJD340
MJD340RL	, MJD340T4	, MJD350	, MJD350T4
MJD41C1	, MJD41CRL	, MJD41CT4	, MJD42C
MJD42C1	, MJD42CRL	, MJD42CT4	, MJD44E3T4
MJD44H11	, MJD44H11-001	, MJD44H11RL	, MJD44H11T4
MJD45H11	, MJD45H11-001	, MJD45H11RL	, MJD45H11T4
MJD47	, MJD47T4	, MJD50	, MJD50-001
MJD50T4	, MJD5731T4	, MJD6039T4	, MLD1N06CLT4
MLD2N06CL	, MLD2N06CLT4	, MSRD620CT	, MSRD620CTT4
MTD10N05E1	, MTD10N05ET4	, MTD10N10EL	, MTD10N10ELT4
MTD12N06EZL	, MTD12N06EZLT4	, MTD1302	, MTD1302-001
MTD1302T4	, MTD1312T4	, MTD14N10E	, MTD14N10E1
MTD14N10ET4	, MTD15N06V	, MTD15N06V1	, MTD15N06VL
MTD15N06VL1	, MTD15N06VLT4	, MTD15N06VT4	, MTD1N50E
MTD1N50E1	, MTD1N50ET4	, MTD1N60E	, MTD1N60E1
MTD1N60ET4	, MTD1N80E	, MTD1N80E1	, MTD1N80ET4
MTD1P40E	, MTD1P40E1	, MTD1P40ET4	, MTD20N03HDL
MTD20N03HDL1	, MTD20N03HDLT4	, MTD20N06HD	, MTD20N06HD1
MTD20N06HDL	, MTD20N06HDL1	, MTD20N06HDLT4	, MTD20N06HDT4
MTD20N06V	, MTD20N06VT4	, MTD20P03HDL	, MTD20P03HDL1
MTD20P03HDLT4	, MTD20P06HDL	, MTD20P06HDL1	, MTD20P06HDLT4
MTD2955ET4	, MTD2955V	, MTD2955V1	, MTD2955VT4
MTD2N40E	, MTD2N40ET4	, MTD2N50E	, MTD2N50E1
MTD2N50ET4	, MTD3055V	, MTD3055V1	, MTD3055VL
MTD3055VL1	, MTD3055VLT4	, MTD3055VT4	, MTD3302T4
MTD3N25E1	, MTD4N20E	, MTD4N20E1	, MTD4N20ET4
MTD5N25E	, MTD5N25E1	, MTD5N25ET4	, MTD5P06ET4
MTD5P06V	, MTD5P06V1	, MTD5P06VT4	, MTD6N10E
MTD6N10E1	, MTD6N10ET4	, MTD6N15	, MTD6N15T4
MTD6N20E	, MTD6N20E1	, MTD6N20ET4	, MTD6P10E

PRODUCT BULLETIN

ISSUE DATE: 08-Jun-1999

NOTIFICATION #:4794

EFFECTIVE DATE: 09-Jun-1999

ISSUING DIVISION:PHX-OSPD

MTD6P10ET4	,	MTD9N10E	,	MTD9N10E1	,	MTD9N10ET4
MURD305RL	,	MURD310T4	,	MURD315T4	,	MURD320T4
MURD610CTT4	,	MURD615CTT4	,	MURD620CT	,	MURD620CT1
MURD620CTT4	,	STD2N50ET4	,	STD3055VL	,	STD3055VL1
STD3055VLT4	,	STD3055VT4	,	STD5P06VT4	,	XBRD3100