

Title of Change:	Update to PD24582 series – To correct the Replacement Supplier
Last Time Buy Date:	Same date to the originally announced in PD24582 series
Last Ship Date:	Same date to the originally announced in PD24582 series
Contact information:	Contact your local onsemi Sales Office or Esther.Lau@onsemi.com
Type of notification:	Customers must notify onsemi (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

This update notice is provided to correct the replacement supplier for the device listed below. There are no other changes to the original PD24582 series. The last time buy date and last ship date remains the same as originally announced.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 6880 1771

Japan

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Device to be Discontinued	Replacement part	Supplier
MID400WV	MID400TVM	onsemi
MID400V	MID400VM	onsemi
MID400SV	MID400SVM	onsemi
MID400SDV	MID400SDVM	onsemi
MID400SD	MID400SDM	onsemi
MID400S	MID400SM	onsemi
MID400	MID400M	onsemi
HCPL3700V	HCPL3700VM	onsemi
HCPL3700SV	HCPL3700SVM	onsemi
HCPL3700SDV	HCPL3700SDVM	onsemi
HCPL3700SD	HCPL3700SDM	onsemi
HCPL3700S	HCPL3700SM	onsemi

HCPL3700	HCPL3700M	onsemi
HCPL2731V	HCPL2731VM	onsemi
HCPL2731SD	HCPL271SDM	onsemi
HCPL2731S	HCPL2731SM	onsemi
HCPL2731	HCPL2731M	onsemi
HCPL2730SD	HCPL2730SDM	onsemi
HCPL2730S	HCPL2730SM	onsemi
HCPL2730	HCPL2730M	onsemi
HCPL2631WV	HCPL2631TVM	onsemi
HCPL2631V	HCPL2631VM	onsemi
HCPL2631SV	HCPL2631SVM	onsemi
HCPL2631SDV	HCPL2631SDVM	onsemi
HCPL2631SD	HCPL2631SDM	onsemi
HCPL2631S	HCPL2631SM	onsemi
HCPL2631	HCPL2631M	onsemi
HCPL2630V	HCPL2630VM	onsemi
HCPL2630SV	HCPL2630SVM	onsemi
HCPL2630SDV	HCPL2630SDVM	onsemi
HCPL2630SD	HCPL2630SDM	onsemi
HCPL2630S	HCPL2630SM	onsemi
HCPL2630	HCPL2630M	onsemi
HCPL2611V	HCPL2611VM	onsemi
HCPL2611SV	HCPL2611SVM	onsemi
HCPL2611S	HCPL2611SM	onsemi
HCPL2611	HCPL2611M	onsemi
HCPL2601WV	HCPL2601TVM	onsemi
HCPL2601V	HCPL2601VM	onsemi
HCPL2601SD	HCPL2601SDM	onsemi
HCPL2601S	HCPL2601SM	onsemi
HCPL2601	HCPL2601M	onsemi
HCPL2531WV	HCPL2531TVM	onsemi
HCPL2531V	HCPL2531VM	onsemi
HCPL2531SDV	HCPL2531SDVM	onsemi
HCPL2531SD	HCPL2531SDM	onsemi
HCPL2531S	HCPL2531SM	onsemi
HCPL2531	HCPL2531M	onsemi
HCPL2530SD	HCPL2530SDM	onsemi



Product Discontinuance

Document #:PD24582X1

Issue Date:28 Apr 2022

HCPL2530S	HCPL2530SM	onsemi
HCPL2530	HCPL2530M	onsemi
6N137SD	6N137SDM	onsemi
6N137	6N137M	onsemi