



---

**UPDATE CHANGE NOTIFICATION #16606**

Generic Copy

---

**Issue Date:** 26-Apr-2011

**TITLE:** Retraction of Leaded Device list from PD16606

**PROPOSED FIRST SHIP DATE:** 26-Apr-2011

**AFFECTED CHANGE CATEGORY(S):** EOL

**ADDITIONAL RELIABILITY DATA:** N/A

**SAMPLES:** Contact your local ON Semiconductor Sales Office

**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**

Contact your local ON Semiconductor Sales Office or <[lea.bonita@onsemi.com](mailto:lea.bonita@onsemi.com)>

**NOTIFICATION TYPE:**

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <[quality@onsemi.com](mailto:quality@onsemi.com)>.

**DESCRIPTION AND PURPOSE:**

This notice is to retract the leaded devices listed below that were inadvertently included in the 1st Quarter 2011 Product Discontinuance Notice issued on 09Apr2011.


**UPDATE CHANGE NOTIFICATION #16606**
**List of affected Parts:**

| <b>Parts</b>    |                  |
|-----------------|------------------|
| MC100E016FNR2   | MC10E416FNR2     |
| MC100E104FNR2   | MC10E431FNR2     |
| MC100E107FNR2   | MC10E451FNR2     |
| MC100E131FNR2   | MC10E452FNR2     |
| MC100E137FNR2   | MC10E457FNR2     |
| MC100E143FNR2   | MC10SX1189D      |
| MC100E151FNR2   | MC14490DWR2      |
| MC100E195FNR2   | MC14526BDWR2     |
| MC100E211FNR2   | MC34071D         |
| MC100E404FNR2   | MC74AC02DR2      |
| MC100E446FNR2   | MC74AC574DWR2    |
| MC100E452FNR2   | MC74ACT00D       |
| MC100E457FNR2   | MC74HC175ADR2    |
| MC100LVE210FNR2 | MC74HC574ADWR2   |
| MC100LVEL38DW   | MC74VHC138DR2    |
| MC10E016FNR2    | MC74VHC157DR2    |
| MC10E101FNR2    | MC74VHC32DR2     |
| MC10E104FNR2    | MC74VHC574DWR2   |
| MC10E107FNR2    | MC74VHCT541ADWR2 |
| MC10E116FNR2    | NLV74HC4052ADR2  |
| MC10E157FNR2    | NLV74HC595ADR2   |
| MC10E158FNR2    | NRVBD660CTT4     |
| MC10E163FNR2    | SZMMSZ5245BT3    |
| MC10E195FNR2    | MC74VHC14DR2     |
| MC10E196FNR2    | SMSZ1600-31T3    |
| MC10E404FNR2    | SURS239T3        |