

**ON Semiconductor**  
Formerly a Division of Motorola



Subject: ON Semiconductor UPDATE NOTIFICATION 10111

TITLE: TRACIABILITY CODE CORRECTION FOR PB 10100

EFFECTIVE DATE: 01-APR-00

AFFECTED CHANGE CATEGORIES  
Marking Process

AFFECTED PRODUCT DIVISIONS  
ANALOG DIV  
GENERAL PURPOSE PRODUCTS

LOGIC DIV  
MOS POWER PRODUCTS DIV

ADDITIONAL RELIABILITY DATA: None

Ref:

SAMPLES: No

Ref:

For any questions concerning this notification:

REFERENCE: JUN HASUNUMA

PHONE: 81-241-27-2231

DISCLAIMER:

ON SEMICONDUCTOR WILL CONSIDER THIS CHANGE APPROVED UNLESS SPECIFIC  
CONDITIONS OF ACCEPTANCE ARE PROVIDED IN WRITING WITHIN 30 DAYS OF  
RECEIPT OF THIS NOTICE. TO DO SO, CONTACT YOUR LOCAL ON  
SEMICONDUCTOR SALES OFFICE.

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

DESCRIPTION AND PURPOSE

-----

ON Semiconductor is announcing the correction to the Product Bulletin 10100 Date Code Format Change for MFP (SO EIAJ T2). We would like to correct description for existing marking and new marking.

Traceability code marking will be changed as follows.

	Existing	New
8 lead MFP	-----	-----
Line1	XXXX	XXXX
Line2	YWWL	ALYW
14 lead MFP		
Line1	XXXXXXXX	XXXXXXXX
Line2	(M)YWWAA	(M)ALYW
16 lead MFP		
Line1	XXXXXXXX	XXXXXXXX
Line2	(M)YWWAA	(M)ALYW
20 lead MFP		
Line1	XXXXXXXX	XXXXXXXX
Line2	(M)YWWAA	(M)AWLYWW

- A-Assembly site code
- AA-Lot code
- L or WL-Lot or wafer code
- Y-Year
- WW-Work week
- YW-Year/Work week
- XXXX-Part number
- (M)-Logo

FILE FORMAT: ASCII TEXT  
FONT - Courier  
SIZE - 12 Point  
LINE - 70 characters/line  
PAGE - 55 lines/page  
PAGEBREAK CHARACTER - ^L (Control L)

AFFECTED DEVICE LIST (WITHOUT SPECIALS)

-----

JLC1132F	, JLC1146FEL	, JLC34538AF	, MC10H100M
MC10H100ML1	, MC10H101M	, MC10H101MEL	, MC10H101ML1
MC10H101ML2	, MC10H101MR1	, MC10H102M	, MC10H102MEL
MC10H102ML1	, MC10H102ML2	, MC10H102MR1	, MC10H102MR2
MC10H103M	, MC10H103MEL	, MC10H103ML1	, MC10H103ML2
MC10H104M	, MC10H104MEL	, MC10H104ML1	, MC10H104ML2
MC10H104MR1	, MC10H104MR2	, MC10H105M	, MC10H105MEL
MC10H105ML1	, MC10H105ML2	, MC10H105MR1	, MC10H105MR2
MC10H106M	, MC10H106ML1	, MC10H107M	, MC10H107MEL
MC10H107ML1	, MC10H107MR2	, MC10H109M	, MC10H109MEL
MC10H109ML1	, MC10H109ML2	, MC10H113M	, MC10H113MEL
MC10H113ML1	, MC10H115M	, MC10H115MEL	, MC10H115ML1
MC10H115ML2	, MC10H115MR1	, MC10H116M	, MC10H116MEL
MC10H116ML1	, MC10H116ML2	, MC10H116MR1	, MC10H116MR2
MC10H117M	, MC10H117MEL	, MC10H117ML1	, MC10H117ML2
MC10H121M	, MC10H124M	, MC10H124MEL	, MC10H124ML1
MC10H124ML2	, MC10H124MR1	, MC10H125M	, MC10H125MEL
MC10H125ML1	, MC10H125ML2	, MC10H125MR1	, MC10H125MR2
MC10H131M	, MC10H131MEL	, MC10H131ML1	, MC10H131ML2
MC10H131MR1	, MC10H135M	, MC10H158M	, MC10H158MEL
MC10H158ML1	, MC10H158ML2	, MC10H158MR1	, MC10H159M
MC10H159MEL	, MC10H159ML1	, MC10H159ML2	, MC10H160M
MC10H161M	, MC10H161MEL	, MC10H161ML1	, MC10H161ML2
MC10H162M	, MC10H162ML1	, MC10H162ML2	, MC10H164M
MC10H164MEL	, MC10H164ML2	, MC10H173M	, MC10H173ML1
MC10H174M	, MC10H174MEL	, MC10H174ML1	, MC10H174ML2
MC10H175M	, MC10H175ML1	, MC10H176M	, MC10H176MEL
MC10H176ML1	, MC10H176ML2	, MC10H176MR1	, MC10H188M
MC10H188MEL	, MC10H188ML1	, MC10H188ML2	, MC10H189M
MC10H189MEL	, MC10H189ML1	, MC10H189ML2	, MC10H209M
MC10H210M	, MC10H210MEL	, MC10H210ML1	, MC10H211M
MC10H211MEL	, MC10H211ML1	, MC10H350M	, MC10H350MEL
MC10H350ML1	, MC10H351M	, MC10H351MEL	, MC10H351ML1
MC10H351MR1	, MC14001BF	, MC14001BFEL	, MC14001BFL1
MC14001BFL2	, MC14001BFR1	, MC14001BFR2	, MC14002BF
MC14002BFEL	, MC14006BF	, MC14006BFR1	, MC14007UBF
MC14007UBFEL	, MC14007UBFR1	, MC14008BF	, MC14011BF
MC14011BFEL	, MC14011BFL1	, MC14011BFL2	, MC14011BFR1
MC14011BFR2	, MC14012BF	, MC14012BFEL	, MC14012BFL1
MC14013BF	, MC14013BFEL	, MC14013BFL1	, MC14013BFL2
MC14013BFR1	, MC14013BFR2	, MC14014BF	, MC14014BFEL
MC14014BFL1	, MC14014BFL2	, MC14014BFR1	, MC14014BFR2
MC14015BF	, MC14015BFEL	, MC14015BFL1	, MC14015BFL2
MC14015BFR1	, MC14016BF	, MC14016BFEL	, MC14016BFL1
MC14016BFR2	, MC14017BF	, MC14017BFEL	, MC14017BFL2
MC14017BFR2	, MC14018BF	, MC14018BFEL	, MC14018BFL2
MC14018BFR1	, MC14020BF	, MC14020BFEL	, MC14020BFL1
MC14020BFL2	, MC14020BFR1	, MC14020BFR2	, MC14021BF
MC14021BFEL	, MC14021BFL1	, MC14021BFR1	, MC14022BF
MC14023BF	, MC14023BFEL	, MC14023BFL1	, MC14023BFL2
MC14024BF	, MC14024BFEL	, MC14024BFL1	, MC14024BFL2
MC14024BFR1	, MC14024BFR2	, MC14025BF	, MC14025BFEL
MC14025BFL1	, MC14027BF	, MC14027BFEL	, MC14027BFL1
MC14027BFL2	, MC14027BFR1	, MC14028BF	, MC14028BFEL
MC14028BFL1	, MC14028BFL2	, MC14029BF	, MC14029BFEL
MC14040BF	, MC14040BFEL	, MC14040BFL1	, MC14040BFL2
MC14040BFR1	, MC14040BFR2	, MC14042BF	, MC14042BFEL
MC14042BFL2	, MC14043BF	, MC14043BFEL	, MC14043BFL1

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

MC14043BFR1	, MC14046BF	, MC14046BFEL	, MC14046BFL1
MC14046BFL2	, MC14046BFR1	, MC14046BFR2	, MC14049BF
MC14049BFL1	, MC14049UBF	, MC14049UBFEL	, MC14049UBFL1
MC14049UBFL2	, MC14049UBFR1	, MC14050BF	, MC14050BFEL
MC14050BFL1	, MC14050BFL2	, MC14050BFR1	, MC14050BFR2
MC14051BF	, MC14051BFEL	, MC14051BFL1	, MC14051BFL2
MC14051BFR1	, MC14051BFR2	, MC14052BF	, MC14052BFEL
MC14052BFL1	, MC14052BFL2	, MC14052BFR1	, MC14052BFR2
MC14053BF	, MC14053BFEL	, MC14053BFL1	, MC14053BFL2
MC14053BFR1	, MC14053BFR2	, MC14060BF	, MC14060BFEL
MC14060BFL1	, MC14060BFR2	, MC14066BF	, MC14066BFEL
MC14066BFL1	, MC14066BFL2	, MC14066BFR1	, MC14066BFR2
MC14068BF	, MC14068BFEL	, MC14069UBF	, MC14069UBFEL
MC14069UBFL1	, MC14069UBFL2	, MC14069UBFR1	, MC14069UBFR2
MC14070BF	, MC14070BFEL	, MC14070BFL1	, MC14070BFL2
MC14070BFR1	, MC14070BFR2	, MC14071BF	, MC14071BFEL
MC14071BFL1	, MC14071BFL2	, MC14071BFR2	, MC14072BF
MC14072BFEL	, MC14072BFL1	, MC14073BF	, MC14073BFEL
MC14073BFL1	, MC14073BFR1	, MC14075BF	, MC14075BFEL
MC14075BFL1	, MC14075BFR1	, MC14075BFR2	, MC14077BF
MC14077BFEL	, MC14078BF	, MC14078BFEL	, MC14078BFL1
MC14081BF	, MC14081BFEL	, MC14081BFL1	, MC14081BFL2
MC14081BFR1	, MC14081BFR2	, MC14082BF	, MC14082BFR2
MC14093BF	, MC14093BFEL	, MC14093BFL1	, MC14093BFR1
MC14093BFR2	, MC14094BF	, MC14094BFEL	, MC14094BFL1
MC14094BFL2	, MC14094BFR1	, MC14094BFR2	, MC14099BF
MC14099BFEL	, MC14099BFL1	, MC14099BFL2	, MC14174BF
MC14174BFEL	, MC14175BF	, MC14175BFEL	, MC14175BFL1
MC14175BFR2	, MC14490F	, MC14490FEL	, MC14490FL1
MC14490FR1	, MC14503BF	, MC14503BFEL	, MC14503BFL2
MC14503BFR1	, MC14504BF	, MC14504BFEL	, MC14504BFL1
MC14504BFR1	, MC14504BFR2	, MC14510BF	, MC14510BFEL
MC14510BFR1	, MC14511BF	, MC14511BFEL	, MC14511BFR1
MC14512BF	, MC14512BFEL	, MC14512BFL1	, MC14516BF
MC14516BFEL	, MC14516BFL1	, MC14516BFR1	, MC14518BF
MC14518BFEL	, MC14518BFL1	, MC14518BFR2	, MC14519BF
MC14519BFR1	, MC14520BF	, MC14520BFEL	, MC14520BFL1
MC14520BFL2	, MC14520BFR1	, MC14520BFR2	, MC14521BF
MC14521BFEL	, MC14521BFL1	, MC14526BF	, MC14526BFL1
MC14526BFR1	, MC14528BF	, MC14528BFEL	, MC14528BFL2
MC14528BFR1	, MC14532BF	, MC14532BFEL	, MC14532BFL1
MC14532BFR2	, MC14536BF	, MC14536BFL1	, MC14536BFL2
MC14538BF	, MC14538BFEL	, MC14538BFL1	, MC14538BFL2
MC14538BFR1	, MC14538BFR2	, MC14539BF	, MC14539BFEL
MC14539BFR1	, MC14541BF	, MC14541BFEL	, MC14541BFL1
MC14541BFL2	, MC14541BFR1	, MC14541BFR2	, MC14543BF
MC14543BFEL	, MC14543BFL1	, MC14551BF	, MC14551BFL2
MC14555BF	, MC14555BFEL	, MC14555BFL1	, MC14556BF
MC14556BFEL	, MC14556BFR1	, MC14557BF	, MC14557BFEL
MC14557BFL1	, MC14566BF	, MC14566BFR1	, MC14568BF
MC14572UBF	, MC14572UBFEL	, MC14584BF	, MC14584BFEL

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

MC14584BFL1	,	MC14584BFL2	,	MC14584BFR1	,	MC14584BFR2
MC14585BF	,	MC14585BFR1	,	MC1488M	,	MC1488MEL
MC1488ML1	,	MC1488MR1	,	MC1489AM	,	MC1489AMEL
MC1489AML1	,	MC1489AML2	,	MC1489AMR1	,	MC1489AMR2
MC1489M	,	MC1489ML1	,	MC1489MR1	,	MC1496M
MC1496ML2	,	MC1648M	,	MC1648ML1	,	MC1648ML2
MC1658M	,	MC1658ML1	,	MC33078ML1	,	MC33079MR1
MC34063AM	,	MC34063AMEL	,	MC34063AML1	,	MC34063AML2
MC34063AMR1	,	MC34063AMR2	,	MC34182M	,	MC34184M
MC4044M	,	MC74AC00M	,	MC74AC00MEL	,	MC74AC00ML1
MC74AC00MR1	,	MC74AC02M	,	MC74AC02MEL	,	MC74AC02MR1
MC74AC04M	,	MC74AC04MEL	,	MC74AC04ML1	,	MC74AC04ML2
MC74AC04MR1	,	MC74AC05M	,	MC74AC08M	,	MC74AC08MEL
MC74AC08ML1	,	MC74AC08MR1	,	MC74AC10M	,	MC74AC10MEL
MC74AC11M	,	MC74AC11MEL	,	MC74AC11ML1	,	MC74AC125M
MC74AC125MEL	,	MC74AC132M	,	MC74AC138M	,	MC74AC138MEL
MC74AC138ML1	,	MC74AC138MR1	,	MC74AC138MR2	,	MC74AC139M
MC74AC139MEL	,	MC74AC139ML1	,	MC74AC14M	,	MC74AC14MEL
MC74AC14ML1	,	MC74AC14MR1	,	MC74AC151M	,	MC74AC153M
MC74AC157M	,	MC74AC157MEL	,	MC74AC157ML1	,	MC74AC157MR1
MC74AC161M	,	MC74AC161MEL	,	MC74AC161MR2	,	MC74AC162M
MC74AC163M	,	MC74AC163MEL	,	MC74AC163ML1	,	MC74AC174M
MC74AC174MEL	,	MC74AC174ML1	,	MC74AC175M	,	MC74AC175ML1
MC74AC20M	,	MC74AC240M	,	MC74AC240MEL	,	MC74AC240ML1
MC74AC241M	,	MC74AC241MEL	,	MC74AC244M	,	MC74AC244MEL
MC74AC244ML1	,	MC74AC245M	,	MC74AC245MEL	,	MC74AC245ML1
MC74AC245MR1	,	MC74AC257M	,	MC74AC259M	,	MC74AC259ML1
MC74AC273M	,	MC74AC273MEL	,	MC74AC273ML1	,	MC74AC32M
MC74AC32MEL	,	MC74AC32ML1	,	MC74AC32MR1	,	MC74AC373M
MC74AC373MEL	,	MC74AC373ML1	,	MC74AC374M	,	MC74AC374MEL
MC74AC374ML1	,	MC74AC377M	,	MC74AC377MEL	,	MC74AC4040M
MC74AC533M	,	MC74AC534M	,	MC74AC540M	,	MC74AC540MEL
MC74AC541M	,	MC74AC541MEL	,	MC74AC541ML1	,	MC74AC541MR1
MC74AC573M	,	MC74AC573MEL	,	MC74AC573ML1	,	MC74AC574M
MC74AC574MEL	,	MC74AC574ML1	,	MC74AC574MR1	,	MC74AC74M
MC74AC74MEL	,	MC74AC74ML1	,	MC74AC74MR1	,	MC74AC86M
MC74AC86MEL	,	MC74ACT00M	,	MC74ACT00MEL	,	MC74ACT00ML1
MC74ACT02M	,	MC74ACT02MEL	,	MC74ACT02ML1	,	MC74ACT04M
MC74ACT04MEL	,	MC74ACT04ML1	,	MC74ACT04MR1	,	MC74ACT05M
MC74ACT05MEL	,	MC74ACT05ML1	,	MC74ACT08M	,	MC74ACT08MEL
MC74ACT08ML1	,	MC74ACT109M	,	MC74ACT10M	,	MC74ACT10MEL
MC74ACT10ML1	,	MC74ACT11M	,	MC74ACT11MEL	,	MC74ACT11ML1
MC74ACT125M	,	MC74ACT125MEL	,	MC74ACT125ML1	,	MC74ACT125ML2
MC74ACT126ML1	,	MC74ACT132M	,	MC74ACT138M	,	MC74ACT138MEL
MC74ACT138ML1	,	MC74ACT139M	,	MC74ACT139MEL	,	MC74ACT139ML1
MC74ACT14M	,	MC74ACT14MEL	,	MC74ACT14ML1	,	MC74ACT14MR1
MC74ACT151M	,	MC74ACT151ML1	,	MC74ACT153M	,	MC74ACT153MEL
MC74ACT153ML1	,	MC74ACT157M	,	MC74ACT157MEL	,	MC74ACT157ML1
MC74ACT158M	,	MC74ACT161M	,	MC74ACT161MEL	,	MC74ACT161ML1
MC74ACT163M	,	MC74ACT174M	,	MC74ACT174MEL	,	MC74ACT174ML1
MC74ACT20M	,	MC74ACT20MEL	,	MC74ACT20ML1	,	MC74ACT240M

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

MC74ACT240MEL	, MC74ACT240ML1	, MC74ACT240MR1	, MC74ACT240MR2
MC74ACT241M	, MC74ACT244M	, MC74ACT244MEL	, MC74ACT244ML1
MC74ACT244MR2	, MC74ACT245M	, MC74ACT245MEL	, MC74ACT245ML1
MC74ACT245MR1	, MC74ACT257M	, MC74ACT273M	, MC74ACT273MEL
MC74ACT273ML1	, MC74ACT273MR2	, MC74ACT323M	, MC74ACT32M
MC74ACT32MEL	, MC74ACT32ML1	, MC74ACT32ML2	, MC74ACT373M
MC74ACT373MEL	, MC74ACT373ML1	, MC74ACT373MR2	, MC74ACT374M
MC74ACT374MEL	, MC74ACT374ML1	, MC74ACT377M	, MC74ACT377ML1
MC74ACT521M	, MC74ACT521MEL	, MC74ACT540M	, MC74ACT540MEL
MC74ACT540ML1	, MC74ACT540MR1	, MC74ACT541M	, MC74ACT541MEL
MC74ACT541ML1	, MC74ACT541MR1	, MC74ACT541MR2	, MC74ACT573M
MC74ACT573MEL	, MC74ACT574M	, MC74ACT574MEL	, MC74ACT574ML1
MC74ACT574MR1	, MC74ACT623M	, MC74ACT640M	, MC74ACT640ML1
MC74ACT74M	, MC74ACT74MEL	, MC74ACT74ML1	, MC74ACT74MR1
MC74ACT86M	, MC74ACT86ML1	, MC74HC00AF	, MC74HC00AFEL
MC74HC00AFL1	, MC74HC00AFL2	, MC74HC00AFR1	, MC74HC00AFR2
MC74HC02AF	, MC74HC02AFEL	, MC74HC02AFL1	, MC74HC02AFL2
MC74HC02AFR1	, MC74HC02AFR2	, MC74HC03AF	, MC74HC03AFEL
MC74HC03AFL1	, MC74HC03AFL2	, MC74HC03AFR1	, MC74HC03AFR2
MC74HC04AF	, MC74HC04AFEL	, MC74HC04AFL1	, MC74HC04AFL2
MC74HC04AFR1	, MC74HC04AFR2	, MC74HC08AF	, MC74HC08AFEL
MC74HC08AFL1	, MC74HC08AFL2	, MC74HC08AFR1	, MC74HC08AFR2
MC74HC107F	, MC74HC107FEL	, MC74HC107FL1	, MC74HC107FL2
MC74HC107FR2	, MC74HC10F	, MC74HC10FEL	, MC74HC10FL1
MC74HC10FL2	, MC74HC10FR1	, MC74HC10FR2	, MC74HC112F
MC74HC112FR2	, MC74HC11F	, MC74HC11FEL	, MC74HC11FL1
MC74HC11FL2	, MC74HC11FR1	, MC74HC11FR2	, MC74HC125AF
MC74HC125AFEL	, MC74HC125AFL1	, MC74HC125AFL2	, MC74HC125AFR1
MC74HC125AFR2	, MC74HC126AF	, MC74HC126AFEL	, MC74HC126AFL1
MC74HC126AFL2	, MC74HC126AFR1	, MC74HC126AFR2	, MC74HC132AF
MC74HC132AFEL	, MC74HC132AFL1	, MC74HC132AFL2	, MC74HC132AFR1
MC74HC132AFR2	, MC74HC133F	, MC74HC133FEL	, MC74HC133FL1
MC74HC137F	, MC74HC137FR2	, MC74HC138AF	, MC74HC138AFEL
MC74HC138AFL1	, MC74HC138AFL2	, MC74HC138AFR1	, MC74HC138AFR2
MC74HC139AF	, MC74HC139AFEL	, MC74HC139AFL1	, MC74HC139AFL2
MC74HC139AFR1	, MC74HC139AFR2	, MC74HC147F	, MC74HC147FEL
MC74HC147FL1	, MC74HC14AF	, MC74HC14AFEL	, MC74HC14AFL1
MC74HC14AFL2	, MC74HC14AFR1	, MC74HC14AFR2	, MC74HC151F
MC74HC151FEL	, MC74HC151FL1	, MC74HC151FL2	, MC74HC151FR1
MC74HC151FR2	, MC74HC153F	, MC74HC153FEL	, MC74HC153FL1
MC74HC153FR1	, MC74HC153FR2	, MC74HC157AF	, MC74HC157AFEL
MC74HC157AFL1	, MC74HC157AFL2	, MC74HC157AFR1	, MC74HC157AFR2
MC74HC158AF	, MC74HC158AFEL	, MC74HC160AF	, MC74HC160AFEL
MC74HC160AFL1	, MC74HC160AFR1	, MC74HC160AFR2	, MC74HC160F
MC74HC160FEL	, MC74HC161AF	, MC74HC161AFEL	, MC74HC161AFL1
MC74HC161AFL2	, MC74HC161AFR1	, MC74HC161AFR2	, MC74HC162AF
MC74HC162AFEL	, MC74HC162AFL1	, MC74HC162AFR1	, MC74HC162F
MC74HC163AF	, MC74HC163AFEL	, MC74HC163AFL1	, MC74HC163AFL2
MC74HC163AFR1	, MC74HC163AFR2	, MC74HC164AF	, MC74HC164AFEL
MC74HC164AFL1	, MC74HC164AFL2	, MC74HC164AFR1	, MC74HC164AFR2
MC74HC164FR1	, MC74HC165AF	, MC74HC165AFEL	, MC74HC165AFL1

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

MC74HC165AFL2	, MC74HC165F	, MC74HC165FEL	, MC74HC165FL1
MC74HC165FR1	, MC74HC165FR2	, MC74HC173F	, MC74HC173FEL
MC74HC173FL1	, MC74HC173FR2	, MC74HC174AF	, MC74HC174AFEL
MC74HC174AFL1	, MC74HC174AFL2	, MC74HC174AFR1	, MC74HC174AFR2
MC74HC175F	, MC74HC175FEL	, MC74HC175FL1	, MC74HC175FL2
MC74HC175FR1	, MC74HC175FR2	, MC74HC195F	, MC74HC195FEL
MC74HC195FL1	, MC74HC20F	, MC74HC20FEL	, MC74HC20FL1
MC74HC20FR1	, MC74HC20FR2	, MC74HC237F	, MC74HC237FEL
MC74HC237FL1	, MC74HC237FL2	, MC74HC237FR1	, MC74HC237FR2
MC74HC240AF	, MC74HC240AFEL	, MC74HC240AFL1	, MC74HC240AFL2
MC74HC240AFR1	, MC74HC240AFR2	, MC74HC241AF	, MC74HC241AFEL
MC74HC241AFL2	, MC74HC241AFR1	, MC74HC242F	, MC74HC242FEL
MC74HC244AF	, MC74HC244AFEL	, MC74HC244AFL1	, MC74HC244AFL2
MC74HC244AFR1	, MC74HC244AFR2	, MC74HC245AF	, MC74HC245AFEL
MC74HC245AFL1	, MC74HC245AFL2	, MC74HC245AFR1	, MC74HC245AFR2
MC74HC251F	, MC74HC251FEL	, MC74HC251FL1	, MC74HC253F
MC74HC253FL1	, MC74HC253FR2	, MC74HC257F	, MC74HC257FEL
MC74HC257FL1	, MC74HC257FL2	, MC74HC257FR1	, MC74HC257FR2
MC74HC259F	, MC74HC259FEL	, MC74HC259FL1	, MC74HC273AF
MC74HC273AFEL	, MC74HC273AFL1	, MC74HC273AFR1	, MC74HC273AFR2
MC74HC27F	, MC74HC27FEL	, MC74HC27FL1	, MC74HC27FL2
MC74HC27FR1	, MC74HC27FR2	, MC74HC280F	, MC74HC280FEL
MC74HC280FL1	, MC74HC280FR2	, MC74HC299F	, MC74HC299FR2
MC74HC30F	, MC74HC30FEL	, MC74HC30FL1	, MC74HC30FR1
MC74HC30FR2	, MC74HC32AF	, MC74HC32AFEL	, MC74HC32AFL1
MC74HC32AFL2	, MC74HC32AFR1	, MC74HC32AFR2	, MC74HC365AF
MC74HC365AFL1	, MC74HC365AFR1	, MC74HC365AFR2	, MC74HC365FEL
MC74HC365FL1	, MC74HC365FL2	, MC74HC365FR1	, MC74HC365FR2
MC74HC367AF	, MC74HC367AFEL	, MC74HC367AFL1	, MC74HC367AFR1
MC74HC367AFR2	, MC74HC367FEL	, MC74HC367FL1	, MC74HC367FL2
MC74HC367FR1	, MC74HC367FR2	, MC74HC368F	, MC74HC373AF
MC74HC373AFEL	, MC74HC373AFL1	, MC74HC373AFR1	, MC74HC373AFR2
MC74HC374AF	, MC74HC374AFEL	, MC74HC374AFL1	, MC74HC374AFL2
MC74HC374AFR1	, MC74HC374AFR2	, MC74HC390F	, MC74HC390FEL
MC74HC390FL1	, MC74HC390FL2	, MC74HC390FR1	, MC74HC390FR2
MC74HC393F	, MC74HC393FEL	, MC74HC393FL1	, MC74HC393FL2
MC74HC393FR1	, MC74HC393FR2	, MC74HC4002F	, MC74HC4002FEL
MC74HC4002FL1	, MC74HC4017F	, MC74HC4017FEL	, MC74HC4017FL1
MC74HC4017FR2	, MC74HC4020AF	, MC74HC4020AFEL	, MC74HC4020AFL1
MC74HC4020AFL2	, MC74HC4020AFR1	, MC74HC4020AFR2	, MC74HC4024F
MC74HC4024FEL	, MC74HC4024FL1	, MC74HC4024FR1	, MC74HC4040AF
MC74HC4040AFEL	, MC74HC4040AFL1	, MC74HC4040AFR1	, MC74HC4040AFR2
MC74HC4040F	, MC74HC4046AF	, MC74HC4046AFEL	, MC74HC4046AFL1
MC74HC4046AFL2	, MC74HC4046AFR1	, MC74HC4046AFR2	, MC74HC4049F
MC74HC4049FEL	, MC74HC4049FL1	, MC74HC4049FR2	, MC74HC4050F
MC74HC4050FEL	, MC74HC4050FL1	, MC74HC4050FR1	, MC74HC4050FR2
MC74HC4051F	, MC74HC4051FEL	, MC74HC4051FL1	, MC74HC4051FL2
MC74HC4051FR1	, MC74HC4051FR2	, MC74HC4052F	, MC74HC4052FEL
MC74HC4052FL1	, MC74HC4052FL2	, MC74HC4052FR1	, MC74HC4052FR2
MC74HC4053F	, MC74HC4053FEL	, MC74HC4053FL1	, MC74HC4053FL2
MC74HC4053FR1	, MC74HC4053FR2	, MC74HC4060AF	, MC74HC4060AFEL

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

MC74HC4060AFL1	, MC74HC4066F	, MC74HC4066FEL	, MC74HC4066FL1
MC74HC4066FL2	, MC74HC4066FR1	, MC74HC4066FR2	, MC74HC4075F
MC74HC4075FEL	, MC74HC4075FL1	, MC74HC4075FL2	, MC74HC4075FR1
MC74HC4075FR2	, MC74HC4078F	, MC74HC4078FEL	, MC74HC4078FL1
MC74HC42F	, MC74HC42FEL	, MC74HC42FL2	, MC74HC42FR1
MC74HC4316F	, MC74HC4316FEL	, MC74HC4316FL1	, MC74HC4316FR1
MC74HC4351F	, MC74HC4351FEL	, MC74HC4351FL1	, MC74HC4511F
MC74HC4511FEL	, MC74HC4538AF	, MC74HC4538AFEL	, MC74HC4538AFL1
MC74HC4538AFL2	, MC74HC4538AFR1	, MC74HC4538AFR2	, MC74HC4851AF
MC74HC4851AFEL	, MC74HC4851AFL1	, MC74HC4851AFL2	, MC74HC4851AFR1
MC74HC4851AFR2	, MC74HC4852AF	, MC74HC4852AFEL	, MC74HC4852AFL1
MC74HC4852AFL2	, MC74HC4852AFR1	, MC74HC4852AFR2	, MC74HC51F
MC74HC533AF	, MC74HC533AFL1	, MC74HC533AFR2	, MC74HC534AF
MC74HC534AFEL	, MC74HC534AFL1	, MC74HC540AF	, MC74HC540AFEL
MC74HC540AFL1	, MC74HC540AFR1	, MC74HC540AFR2	, MC74HC541AF
MC74HC541AFEL	, MC74HC541AFL1	, MC74HC541AFR1	, MC74HC541AFR2
MC74HC563AF	, MC74HC563AFEL	, MC74HC563AFL1	, MC74HC563AFL2
MC74HC564AF	, MC74HC564AFEL	, MC74HC564AFL2	, MC74HC573AF
MC74HC573AFEL	, MC74HC573AFL1	, MC74HC573AFL2	, MC74HC573AFR1
MC74HC574AF	, MC74HC574AFEL	, MC74HC574AFL1	, MC74HC574AFR1
MC74HC574AFR2	, MC74HC589AF	, MC74HC589AFEL	, MC74HC589AFL1
MC74HC589AFL2	, MC74HC589F	, MC74HC589FL2	, MC74HC58FEL
MC74HC595AF	, MC74HC595AFEL	, MC74HC595AFL1	, MC74HC595AFL2
MC74HC595AFR1	, MC74HC595AFR2	, MC74HC597AF	, MC74HC597AFEL
MC74HC597AFL2	, MC74HC597F	, MC74HC640AF	, MC74HC640AFEL
MC74HC688F	, MC74HC688FEL	, MC74HC688FL1	, MC74HC688FR1
MC74HC688FR2	, MC74HC7266AF	, MC74HC7266AFEL	, MC74HC7266AFR1
MC74HC73F	, MC74HC74AF	, MC74HC74AFEL	, MC74HC74AFL1
MC74HC74AFL2	, MC74HC74AFR1	, MC74HC74AFR2	, MC74HC75F
MC74HC75FEL	, MC74HC75FL1	, MC74HC75FL2	, MC74HC85F
MC74HC85FEL	, MC74HC85FL1	, MC74HC85FR1	, MC74HC86AF
MC74HC86AFEL	, MC74HC86AFL1	, MC74HC86AFL2	, MC74HC86AFR1
MC74HC86AFR2	, MC74HC86F	, MC74HC86FEL	, MC74HC86FR2
MC74HCT00AF	, MC74HCT04AF	, MC74HCT04AFEL	, MC74HCT04AFL1
MC74HCT138AF	, MC74HCT138AFL1	, MC74HCT14AF	, MC74HCT14AFEL
MC74HCT14AFL1	, MC74HCT14AFL2	, MC74HCT14AFR1	, MC74HCT14AFR2
MC74HCT240AF	, MC74HCT240AFL1	, MC74HCT241AF	, MC74HCT241AFEL
MC74HCT244AF	, MC74HCT244AFEL	, MC74HCT244AFL1	, MC74HCT244AFR2
MC74HCT245AF	, MC74HCT245AFEL	, MC74HCT245AFL1	, MC74HCT373AF
MC74HCT373AFL1	, MC74HCT374AF	, MC74HCT374AFEL	, MC74HCT374AFL1
MC74HCT541AF	, MC74HCT541AFEL	, MC74HCT541AFL1	, MC74HCT573AF
MC74HCT573AFEL	, MC74HCT573AFL1	, MC74HCT573AFL2	, MC74HCT573AFR1
MC74HCT573AFR2	, MC74HCT574AF	, MC74HCT574AFEL	, MC74HCU04AF
MC74HCU04AFEL	, MC74HCU04AFL1	, MC74HCU04AFL2	, MC74HCU04AFR1
MC74HCU04AFR2	, MC74HCU04F	, MC74HCU04FL1	, MC74HCU04FL2
MC74LCX00M	, MC74LCX00MEL	, MC74LCX02M	, MC74LCX02MEL
MC74LCX04M	, MC74LCX04MEL	, MC74LCX08M	, MC74LCX08MEL
MC74LCX125M	, MC74LCX125MEL	, MC74LCX138M	, MC74LCX138MEL
MC74LCX157M	, MC74LCX157MEL	, MC74LCX157ML1	, MC74LCX157ML2
MC74LCX240M	, MC74LCX240MEL	, MC74LCX244M	, MC74LCX244MEL
MC74LCX245M	, MC74LCX245MEL	, MC74LCX32M	, MC74LCX32MEL



\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

MC74LCX373M	, MC74LCX374M	, MC74LCX374MEL	, MC74LCX540M
MC74LCX540MEL	, MC74LCX541M	, MC74LCX541MEL	, MC74LCX574M
MC74LCX74M	, MC74LCX74MEL	, MC74LCX74ML1	, MC74LCX74ML2
MC74VHC00M	, MC74VHC00MEL	, MC74VHC00ML1	, MC74VHC00ML2
MC74VHC02M	, MC74VHC02MEL	, MC74VHC02ML1	, MC74VHC02ML2
MC74VHC04M	, MC74VHC04MEL	, MC74VHC04ML1	, MC74VHC04ML2
MC74VHC08M	, MC74VHC08MEL	, MC74VHC08ML1	, MC74VHC08ML2
MC74VHC125M	, MC74VHC125MEL	, MC74VHC125ML1	, MC74VHC125ML2
MC74VHC126M	, MC74VHC126MEL	, MC74VHC126ML1	, MC74VHC126ML2
MC74VHC132M	, MC74VHC132MEL	, MC74VHC132ML1	, MC74VHC132ML2
MC74VHC138M	, MC74VHC138MEL	, MC74VHC138ML1	, MC74VHC138ML2
MC74VHC139M	, MC74VHC139MEL	, MC74VHC139ML1	, MC74VHC139ML2
MC74VHC14M	, MC74VHC14MEL	, MC74VHC14ML1	, MC74VHC14ML2
MC74VHC157M	, MC74VHC157MEL	, MC74VHC157ML1	, MC74VHC157ML2
MC74VHC240M	, MC74VHC240MEL	, MC74VHC240ML1	, MC74VHC240ML2
MC74VHC244M	, MC74VHC244MEL	, MC74VHC244ML1	, MC74VHC244ML2
MC74VHC245M	, MC74VHC245MEL	, MC74VHC245ML1	, MC74VHC245ML2
MC74VHC32M	, MC74VHC32MEL	, MC74VHC32ML1	, MC74VHC32ML2
MC74VHC373M	, MC74VHC373MEL	, MC74VHC373ML1	, MC74VHC373ML2
MC74VHC374M	, MC74VHC374MEL	, MC74VHC374ML1	, MC74VHC374ML2
MC74VHC393M	, MC74VHC393MEL	, MC74VHC393ML1	, MC74VHC393ML2
MC74VHC540M	, MC74VHC540MEL	, MC74VHC540ML1	, MC74VHC540ML2
MC74VHC541M	, MC74VHC541MEL	, MC74VHC541ML1	, MC74VHC541ML2
MC74VHC573M	, MC74VHC573MEL	, MC74VHC573ML1	, MC74VHC573ML2
MC74VHC574M	, MC74VHC574MEL	, MC74VHC574ML1	, MC74VHC574ML2
MC74VHC595M	, MC74VHC595MEL	, MC74VHC595ML1	, MC74VHC595ML2
MC74VHC74M	, MC74VHC74MEL	, MC74VHC74ML1	, MC74VHC74ML2
MC74VHC86M	, MC74VHC86MEL	, MC74VHC86ML1	, MC74VHC86ML2
MC74VHCT00AM	, MC74VHCT00AMEL	, MC74VHCT00AML1	, MC74VHCT00AML2
MC74VHCT04AM	, MC74VHCT04AMEL	, MC74VHCT04AML1	, MC74VHCT04AML2
MC74VHCT138AM	, MC74VHCT138AMEL	, MC74VHCT138AML1	, MC74VHCT138AML2
MC74VHCT240AM	, MC74VHCT240AMEL	, MC74VHCT240AML1	, MC74VHCT240AML2
MC74VHCT244AM	, MC74VHCT244AMEL	, MC74VHCT244AML1	, MC74VHCT244AML2
MC74VHCT245AM	, MC74VHCT245AMEL	, MC74VHCT245AML1	, MC74VHCT245AML2
MC74VHCT373AM	, MC74VHCT373AMEL	, MC74VHCT373AML1	, MC74VHCT373AML2
MC74VHCT374AM	, MC74VHCT374AMEL	, MC74VHCT374AML1	, MC74VHCT374AML2
MC74VHCT541AM	, MC74VHCT541AMEL	, MC74VHCT541AML1	, MC74VHCT541AML2
MC74VHCT573AM	, MC74VHCT573AMEL	, MC74VHCT573AML1	, MC74VHCT573AML2
MC74VHCT574AM	, MC74VHCT574AMEL	, MC74VHCT574AML1	, MC74VHCT574AML2
MC74VHCU04M	, MC74VHCU04MEL	, MC74VHCU04ML1	, MC74VHCU04ML2
MMQF2N06VLEL	, SC00214051BFL2	, SC009HC139F	, SC012HC14AFEL
SC012HC541AFEL	, SC014HC02AN	, SC014MG011BM	, SC014MG011BMR2
SC027MG051BF	, SC111003AM	, SC111003AMEL	, SC111019MEL
SC371013FEL	, SC371071FEL	, SC371072FEL	, SN74LS00M
SN74LS00MEL	, SN74LS00ML1	, SN74LS00MR1	, SN74LS02M
SN74LS02MEL	, SN74LS02ML1	, SN74LS02MR1	, SN74LS03M
SN74LS03MEL	, SN74LS04M	, SN74LS04MEL	, SN74LS04ML1
SN74LS04MR1	, SN74LS05M	, SN74LS05MEL	, SN74LS05ML1
SN74LS05MR1	, SN74LS08M	, SN74LS08MEL	, SN74LS08ML1
SN74LS08MR1	, SN74LS109AM	, SN74LS109AMEL	, SN74LS10M
SN74LS10MEL	, SN74LS10ML1	, SN74LS112AMEL	, SN74LS11M

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

SN74LS11MEL	, SN74LS11ML1	, SN74LS11MR1	, SN74LS123M
SN74LS123MEL	, SN74LS123ML1	, SN74LS123MR1	, SN74LS125AM
SN74LS125AMEL	, SN74LS125AML1	, SN74LS125AMR1	, SN74LS126AM
SN74LS126AML1	, SN74LS132M	, SN74LS132ML1	, SN74LS132MR1
SN74LS133ML1	, SN74LS138M	, SN74LS138MEL	, SN74LS138ML1
SN74LS138MR1	, SN74LS139M	, SN74LS139MEL	, SN74LS139ML1
SN74LS139MR1	, SN74LS145M	, SN74LS145ML1	, SN74LS148M
SN74LS148MEL	, SN74LS148ML1	, SN74LS14M	, SN74LS14MEL
SN74LS14ML1	, SN74LS14MR1	, SN74LS151M	, SN74LS151MEL
SN74LS151ML1	, SN74LS151MR1	, SN74LS153M	, SN74LS153MEL
SN74LS153ML1	, SN74LS153MR1	, SN74LS155M	, SN74LS155MEL
SN74LS155ML1	, SN74LS157M	, SN74LS157MEL	, SN74LS157ML1
SN74LS157MR1	, SN74LS158M	, SN74LS158MEL	, SN74LS158ML1
SN74LS161AM	, SN74LS161AMEL	, SN74LS161AML1	, SN74LS161AMR1
SN74LS163AM	, SN74LS163AML1	, SN74LS163AMR1	, SN74LS164M
SN74LS164MEL	, SN74LS164ML1	, SN74LS164MR1	, SN74LS165M
SN74LS165MEL	, SN74LS165MR1	, SN74LS166M	, SN74LS166MEL
SN74LS166ML1	, SN74LS174M	, SN74LS174MEL	, SN74LS174ML1
SN74LS174MR1	, SN74LS175M	, SN74LS175MEL	, SN74LS175ML1
SN74LS175MR1	, SN74LS175MR2	, SN74LS193M	, SN74LS193ML1
SN74LS193MR1	, SN74LS20M	, SN74LS20MEL	, SN74LS20ML1
SN74LS20MR1	, SN74LS21M	, SN74LS21MEL	, SN74LS21ML1
SN74LS240M	, SN74LS240MEL	, SN74LS240ML1	, SN74LS240MR1
SN74LS240MR2	, SN74LS241M	, SN74LS241ML1	, SN74LS242M
SN74LS242MEL	, SN74LS244M	, SN74LS244MEL	, SN74LS244ML1
SN74LS244MR1	, SN74LS244MR2	, SN74LS245M	, SN74LS245MEL
SN74LS245ML1	, SN74LS245MR1	, SN74LS245MR2	, SN74LS251M
SN74LS251ML1	, SN74LS251MR1	, SN74LS253M	, SN74LS253ML1
SN74LS257BM	, SN74LS257BMEL	, SN74LS257BMR1	, SN74LS258BMEL
SN74LS258BML1	, SN74LS259M	, SN74LS259ML1	, SN74LS259MR1
SN74LS273M	, SN74LS273MEL	, SN74LS273ML1	, SN74LS273MR1
SN74LS279M	, SN74LS27M	, SN74LS27MEL	, SN74LS27ML1
SN74LS280M	, SN74LS280MEL	, SN74LS283ML1	, SN74LS30M
SN74LS30MEL	, SN74LS30ML1	, SN74LS30MR1	, SN74LS32M
SN74LS32MEL	, SN74LS32ML1	, SN74LS32MR1	, SN74LS367AM
SN74LS367AMEL	, SN74LS367AML1	, SN74LS367AMR1	, SN74LS368AM
SN74LS368AMEL	, SN74LS368AML1	, SN74LS368AMR1	, SN74LS373M
SN74LS373MEL	, SN74LS373ML1	, SN74LS373MR1	, SN74LS374M
SN74LS374MEL	, SN74LS374ML1	, SN74LS374MR1	, SN74LS38M
SN74LS38MEL	, SN74LS38ML1	, SN74LS38MR1	, SN74LS390M
SN74LS393M	, SN74LS393MEL	, SN74LS393ML1	, SN74LS393MR1
SN74LS42M	, SN74LS42MR1	, SN74LS486M	, SN74LS51M
SN74LS51MEL	, SN74LS51ML1	, SN74LS51MR1	, SN74LS540M
SN74LS541M	, SN74LS541MEL	, SN74LS541ML1	, SN74LS541MR1
SN74LS54MR1	, SN74LS640M	, SN74LS640ML1	, SN74LS640MR1
SN74LS641M	, SN74LS684M	, SN74LS684MEL	, SN74LS74AM
SN74LS74AMEL	, SN74LS74AML1	, SN74LS74AMR1	, SN74LS85M
SN74LS85MEL	, SN74LS85ML1	, SN74LS86M	, SN74LS86MEL
SN74LS86ML1	, SN74LS86MR1	, SN74LS92MEL	, SN74LS92ML1
TCA0372DM2	, TCA0372DM2EL	, TCA0372DM2R2	, TSC14051BF
TSC14051BFEL	, TSC14051BFL1	, TSC14051BFL2	, TSC14051BFR1

\*\*\*\*\*

UPDATE NOTIFICATION

\*\*\*\*\*

ISSUE DATE: 10-Jan-2000

NOTIFICATION #:10111

EFFECTIVE DATE: 01-Apr-2000

ISSUING DIVISION:NML-GPPD

TSC14051BFR2	,	TSC14052BF	,	TSC14052BFEL	,	TSC14052BFL1
TSC14052BFL2	,	TSC14052BFR1	,	TSC14052BFR2	,	TSC14053BF
TSC14053BFEL	,	TSC14053BFL1	,	TSC14053BFL2	,	TSC14053BFR1
TSC14053BFR2	,	TSC14066BF	,	TSC14066BFEL	,	TSC14066BFL1
TSC14066BFL2	,	TSC14066BFR1	,	TSC14066BFR2	,	TSC74HC139AF

=====