

ON Semiconductor



Subject: ON Semiconductor UPDATE NOTIFICATION 10152

TITLE: UPDATE NOTIFICATION FOR PCN10130

EFFECTIVE DATE: 16-MAR-00

AFFECTED CHANGE CATEGORIES

AFFECTED PRODUCT DIVISIONS

ANALOG PRODUCTS DIV

LOGIC PRODUCTS DIV

ADDITIONAL RELIABILITY DATA: None

Ref:

SAMPLES: No

Ref:

For any questions concerning this notification:

REFERENCE: JERRY QUAH

PHONE: 602-244-6855

DISCLAIMER:

ON SEMICONDUCTOR WILL CONSIDER THIS CHANGE APPROVED UNLESS SPECIFIC CONDITIONS OF ACCEPTANCE ARE PROVIDED IN WRITING WITHIN 30 DAYS OF RECEIPT OF THIS NOTICE. TO DO SO, CONTACT YOUR LOCAL ON SEMICONDUCTOR SALES OFFICE.

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.

On Semiconductor
Semiconductor Technology Grp

Page:2

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

DESCRIPTION AND PURPOSE

This is the update notice to cancel PCN10130, which announced a conversion to a recently qualified 3-layer (Ni-Pd-Au) leadframe for the SOIC products built in the ON Semiconductor Carmona factory. The current Sn/Pb leadframe will continue to be used. This is due to availability issues with Pd.

FILE FORMAT: ASCII TEXT

FONT - Courier

SIZE - 12 Point

LINE - 70 characters/line

PAGE - 55 lines/page

PAGEBREAK CHARACTER - ^L (Control L)

AFFECTED DEVICE LIST (WITHOUT SPECIALS)

DRM014D	,	DRM014DR2	,	FLM285D-1.2	,	FLM285D-1.2R2
FLM285D-2.5	,	FLM285D-2.5R2	,	FLM2901DR2	,	FLM2903D
FLM2903DR2	,	FLM2903VD	,	FLM2903VDR2	,	FLM2904D
FLM2904DR2	,	FLM2904VD	,	FLM2904VDR2	,	FLM2931AD-5.0
FLM2931AD-5.0R2	,	FLM2931CD	,	FLM2931CDR2	,	FLM2931D-5.0
FLM2931D-5.0R2	,	FLM311D	,	FLM311DR2	,	FLM317LD
FLM317LDR2	,	FLM358D	,	FLM358DR2	,	FLM385BD-2.5
FLM385BD-2.5R2	,	FLM393D	,	FLM393DR2	,	FLM833D
FLM833DR2	,	FLP2951ACD	,	FLP2951ACDR2	,	FMC14013BDR2
FMC1455D	,	FMC1455DR2	,	FMC33063AD	,	FMC33064D-005
FMC33064D-5R2	,	FMC33072AD	,	FMC33072ADR2	,	FMC33072D
FMC33072DR2	,	FMC33074DR2	,	FMC33077D	,	FMC33077DR2
FMC33078D	,	FMC33078DR2	,	FMC33161D	,	FMC33161DR2
FMC33164D-003	,	FMC33164D-005	,	FMC33164D-3R2	,	FMC33164D-5R2
FMC33172D	,	FMC33172DR2	,	FMC33202D	,	FMC33202DR2
FMC33261DR2	,	FMC33269D-3.3	,	FMC33269DR2-3.3	,	FMC33282D
FMC33282DR2	,	FMC34063ADR2	,	FMC34064D-005	,	FMC34064D-5R2
FMC34072D	,	FMC34072DR2	,	FMC34081BD	,	FMC34081BDR2
FMC34261DR2	,	FMC34262DR2	,	FMC74HC138ADR2	,	FMC78L05ABD
FMC78L05ABDR2	,	FMC78L05ACD	,	FMC78L05ACDR2	,	FMC78L08ACD
FMC78L08ACDR2	,	FMC78L12ABD	,	FMC78L12ABDR2	,	FMC78L12ACD
FMC78L12ACDR2	,	FMC79L05ABD	,	FMC79L05ABDR2	,	FMC79L05ACD
FMC79L05ACDR2	,	FMC79L12ABD	,	FMC79L12ABDR2	,	FP14050BD
FP14094BD	,	FSC78L05ABDR2	,	FTL082CD	,	FTL082CDR2
FTL431ACD	,	FTL431ACDR2	,	FTL431AID	,	FTL431AIDR2
FTL431BID	,	FTL431BIDR2	,	FTL431CD	,	FTL431CDR2
FTL431ID	,	FTL431IDR2	,	FUC3843BD1R2	,	FUC3843BVD1
FZ10EL16D	,	FZ10EL16DR2	,	FZ14050BD	,	FZ14050BDR2
FZ14094BD	,	FZ74LS32D	,	L4949D	,	L4949DR2
LF351D	,	LF351DR2	,	LF353D	,	LF353DR2
LF411CD	,	LF411CDR2	,	LF412CD	,	LF412CDR2
LF442CD	,	LF442CDR2	,	LF444CD	,	LF444CDR2
LM201AD	,	LM201ADR2	,	LM211D	,	LM211DR2
LM224D	,	LM224DR2	,	LM239AD	,	LM239ADR2
LM239D	,	LM239DR2	,	LM258D	,	LM258DR2
LM285D-1.2	,	LM285D-1.2R2	,	LM285D-2.5	,	LM285D-2.5R2
LM2901D	,	LM2901DR2	,	LM2901VDR2	,	LM2902D
LM2902DR2	,	LM2902VD	,	LM2902VDR2	,	LM2903D
LM2903DR2	,	LM2903VD	,	LM2903VDR2	,	LM2904D
LM2904DR2	,	LM2904VD	,	LM2904VDR2	,	LM2931ACD
LM2931ACDR2	,	LM2931AD-5.0	,	LM2931AD-5.0R2	,	LM2931CD
LM2931CDR2	,	LM2931D-5.0	,	LM2931D-5.0R2	,	LM293D
LM293DR2	,	LM301AD	,	LM301ADR2	,	LM311D
LM311DR2	,	LM317LBD	,	LM317LBDR2	,	LM317LD
LM317LDR2	,	LM324AD	,	LM324ADR2	,	LM324D
LM324DR2	,	LM339AD	,	LM339ADR2	,	LM339D
LM339DR2	,	LM348D	,	LM348DR2	,	LM358D
LM358DR2	,	LM385BD-1.2	,	LM385BD-1.2R2	,	LM385BD-2.5
LM385BD-2.5R2	,	LM385D-1.2	,	LM385D-1.2R2	,	LM385D-2.5
LM385D-2.5R2	,	LM393D	,	LM393DR2	,	LM833D
LM833DR2	,	LMT2901DR2	,	LMT2902DR2	,	LMT2903DR2
LMT2904DR2	,	LMT324D	,	LMT324DR2	,	LMT339DR2
LMT358DR2	,	LP2951ACD	,	LP2951ACD-3.0	,	LP2951ACD-3.0R2
LP2951ACD-3.3	,	LP2951ACDR2	,	LP2951CD	,	LP2951CD-3.0
LP2951CD-3.0R2	,	LP2951CD-3.3	,	LP2951CD-3.3R2	,	LP2951CDR2
LXM100LVEL12D	,	LXM100LVEL58D	,	LXM100LVELT22D	,	MC100EL01D
MC100EL01DR2	,	MC100EL04D	,	MC100EL04DR2	,	MC100EL05D
MC100EL05DR2	,	MC100EL07D	,	MC100EL07DR2	,	MC100EL11D

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC100EL11DR2	,	MC100EL12D	,	MC100EL12DR2	,	MC100EL15D
MC100EL15DR2	,	MC100EL1648D	,	MC100EL1648DR2	,	MC100EL16D
MC100EL16DR2	,	MC100EL31D	,	MC100EL31DR2	,	MC100EL32D
MC100EL32DR2	,	MC100EL33D	,	MC100EL33DR2	,	MC100EL34D
MC100EL34DR2	,	MC100EL35D	,	MC100EL35DR2	,	MC100EL51D
MC100EL51DR2	,	MC100EL52D	,	MC100EL52DR2	,	MC100EL57D
MC100EL57DR2	,	MC100EL58D	,	MC100EL58DR2	,	MC100ELT20D
MC100ELT20DR2	,	MC100ELT21D	,	MC100ELT21DR2	,	MC100ELT22D
MC100ELT22DR2	,	MC100ELT23D	,	MC100ELT23DR2	,	MC100ELT24D
MC100ELT24DR2	,	MC100ELT25D	,	MC100ELT25DR2	,	MC100ELT28D
MC100ELT28DR2	,	MC100EP11D	,	MC100EP11DR2	,	MC100EPT21D
MC100EPT21DR2	,	MC100EPT22D	,	MC100EPT22DR2	,	MC100EPT23D
MC100EPT23DR2	,	MC100EPT24D	,	MC100EPT24DR2	,	MC100EPT25D
MC100EPT25DR2	,	MC100EPT26D	,	MC100EPT26DR2	,	MC100LVEL01D
MC100LVEL05D	,	MC100LVEL05DR2	,	MC100LVEL11D	,	MC100LVEL11DR2
MC100LVEL12D	,	MC100LVEL12DR2	,	MC100LVEL16D	,	MC100LVEL16DR2
MC100LVEL31D	,	MC100LVEL31DR2	,	MC100LVEL32D	,	MC100LVEL32DR2
MC100LVEL33D	,	MC100LVEL33DR2	,	MC100LVEL51D	,	MC100LVEL51DR2
MC100LVEL58D	,	MC100LVEL58DR2	,	MC100LVELT22D	,	MC100LVELT22DR2
MC100LVELT23D	,	MC100LVELT23DR2	,	MC10EL01D	,	MC10EL01DR2
MC10EL04D	,	MC10EL04DR2	,	MC10EL05D	,	MC10EL05DR2
MC10EL07D	,	MC10EL07DR2	,	MC10EL11D	,	MC10EL11DR2
MC10EL12D	,	MC10EL12DR2	,	MC10EL15D	,	MC10EL15DR2
MC10EL16D	,	MC10EL16DR2	,	MC10EL31D	,	MC10EL31DR2
MC10EL32D	,	MC10EL32DR2	,	MC10EL33D	,	MC10EL33DR2
MC10EL34D	,	MC10EL34DR2	,	MC10EL35D	,	MC10EL35DR2
MC10EL51D	,	MC10EL51DR2	,	MC10EL52D	,	MC10EL52DR2
MC10EL57D	,	MC10EL57DR2	,	MC10EL58D	,	MC10EL58DR2
MC10EL89D	,	MC10EL89DR2	,	MC10ELT20D	,	MC10ELT20DR2
MC10ELT21D	,	MC10ELT21DR2	,	MC10ELT22D	,	MC10ELT22DR2
MC10ELT24D	,	MC10ELT24DR2	,	MC10ELT25D	,	MC10ELT25DR2
MC10ELT28D	,	MC10ELT28DR2	,	MC10EP01D	,	MC10EP01DR2
MC10EP05D	,	MC10EP05DR2	,	MC10EP08D	,	MC10EP08DR2
MC10EP11D	,	MC10EP11DR2	,	MC10EP16D	,	MC10EP16DR2
MC10EP31D	,	MC10EP31DR2	,	MC10EP32D	,	MC10EP32DR2
MC10EP33D	,	MC10EP33DR2	,	MC10EP35D	,	MC10EP35DR2
MC10EP58D	,	MC10EP58DR2	,	MC10EP89D	,	MC10EP89DR2
MC10EPT20D	,	MC10EPT20DR2	,	MC10H116D	,	MC10H116DR2
MC10SX1125AD	,	MC10SX1125ADR2	,	MC10SX1130D	,	MC10SX1130DR2
MC10SX1189D	,	MC10SX1189DR2	,	MC12015D	,	MC12015DR2
MC12016D	,	MC12016DR2	,	MC12017D	,	MC12017DR2
MC12019D	,	MC12019DR2	,	MC12026AD	,	MC12026ADR2
MC12034ADR2	,	MC12038ADR2	,	MC12052AD	,	MC12052ADR2
MC12053AD	,	MC12053ADR2	,	MC12054AD	,	MC12054ADR2
MC12058D	,	MC12058DR2	,	MC12066D	,	MC12066DR2
MC12079D	,	MC12079DR2	,	MC12080D	,	MC12080DR2
MC12089D	,	MC12089DR2	,	MC12093D	,	MC12093DR2
MC12095D	,	MC12095DR2	,	MC12147D	,	MC12147DR2
MC12148D	,	MC12148DR2	,	MC12149D	,	MC12149DR2
MC12179D	,	MC12179DR2	,	MC12181D	,	MC12181DR2
MC12202D	,	MC12202DR2	,	MC12210D	,	MC12210DR2

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC13025D	,	MC13025DR2	,	MC13028AD	,	MC13028ADR2
MC13055D	,	MC13055DR2	,	MC13060D	,	MC13060DR2
MC13142D	,	MC13142DR2	,	MC13143D	,	MC13143DR2
MC13144D	,	MC13144DR2	,	MC13155D	,	MC13155DR2
MC13176D	,	MC13176DR2	,	MC1350D	,	MC1350DR2
MC14001BD	,	MC14001BDR2	,	MC14001UBD	,	MC14001UBDR2
MC14007UBD	,	MC14007UBDR2	,	MC14008BDR2	,	MC14011BD
MC14011BDR2	,	MC14011UBD	,	MC14011UBDR2	,	MC14012BD
MC14012BDR2	,	MC14013BD	,	MC14013BDR2	,	MC14014BD
MC14014BDR2	,	MC14015BD	,	MC14015BDR2	,	MC14016BD
MC14016BDR2	,	MC14017BD	,	MC14017BDR2	,	MC14018BD
MC14018BDR2	,	MC14020BD	,	MC14020BDR2	,	MC14021BD
MC14021BDR2	,	MC14022BD	,	MC14022BDR2	,	MC14023BD
MC14023BDR2	,	MC14024BD	,	MC14024BDR2	,	MC14025BD
MC14025BDR2	,	MC14027BD	,	MC14027BDR2	,	MC14028BD
MC14028BDR2	,	MC14029BD	,	MC14029BDR2	,	MC1403BD
MC1403BDR2	,	MC1403D	,	MC1403DR2	,	MC14040BD
MC14040BDR2	,	MC14042BD	,	MC14042BDR2	,	MC14043BD
MC14043BDR2	,	MC14044BD	,	MC14044BDR2	,	MC14049BD
MC14049BDR2	,	MC14049UBD	,	MC14049UBDR2	,	MC14050BD
MC14050BDR2	,	MC14051BD	,	MC14051BDR2	,	MC14052BD
MC14052BDR2	,	MC14053BD	,	MC14053BDR2	,	MC14060BD
MC14060BDR2	,	MC14066BD	,	MC14066BDR2	,	MC14069UBD
MC14069UBDR2	,	MC14070BD	,	MC14070BDR2	,	MC14071BD
MC14071BDR2	,	MC14073BD	,	MC14073BDR2	,	MC14076BD
MC14076BDR2	,	MC14077BD	,	MC14077BDR2	,	MC14081BD
MC14081BDR2	,	MC14082BD	,	MC14082BDR2	,	MC14093BD
MC14093BDR2	,	MC14094BD	,	MC14094BDR2	,	MC14106BD
MC14106BDR2	,	MC1413BD	,	MC1413BDR2	,	MC1413D
MC1413DR2	,	MC1416BD	,	MC1416BDR2	,	MC1416D
MC1416DR2	,	MC14174BD	,	MC14174BDR2	,	MC14175BD
MC14175BDR2	,	MC1436CDR2	,	MC1436D	,	MC1436DR2
MC145026D	,	MC145026DR2	,	MC14503BD	,	MC14503BDR2
MC14504BD	,	MC14504BDR2	,	MC145053D	,	MC145053DR2
MC145076D	,	MC14511BD	,	MC14512BD	,	MC14512BDR2
MC145162D	,	MC14516D1	,	MC14516D1R2	,	MC14516D2R2
MC14516BD	,	MC14516BDR2	,	MC145170D	,	MC145170D1
MC145170D1R2	,	MC145170D2	,	MC145170D2R2	,	MC145170DR2
MC14521BD	,	MC14521BDR2	,	MC14528BD	,	MC14528BDR2
MC14532BD	,	MC14532BDR2	,	MC14538BD	,	MC14538BDR2
MC14541BD	,	MC14541BDR2	,	MC14543BD	,	MC14543BDR2
MC14551BD	,	MC14551BDR2	,	MC14555BD	,	MC14555BDR2
MC14556BD	,	MC14556BDR2	,	MC1455BD	,	MC1455BDR2
MC1455D	,	MC1455DR2	,	MC14572UBD	,	MC14572UBDR2
MC14573D	,	MC14573DR2	,	MC14574D	,	MC14574DR2
MC14575D	,	MC14575DR2	,	MC14578D	,	MC14584BD
MC14584BDR2	,	MC14585BD	,	MC14585BDR2	,	MC1458CD
MC1458CDR2	,	MC1458D	,	MC1458DR2	,	MC1488D
MC1488DR2	,	MC1489AD	,	MC1489ADR2	,	MC1489D
MC1489DR2	,	MC1495D	,	MC1495DR2	,	MC1496D
MC1496DR2	,	MC14C88BD	,	MC14C88BDR2	,	MC14C89ABD

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC14C89ABDR2	,	MC1723BD	,	MC1723BDR2	,	MC1723CD
MC1723CDR2	,	MC1741CD	,	MC1741CDR2	,	MC1776CD
MC1776CDR2	,	MC26LS30D	,	MC26LS30DR2	,	MC2830D
MC2830DR2	,	MC3302D	,	MC3302DR2	,	MC33039D
MC33039DR2	,	MC3303D	,	MC3303DR2	,	MC33060AD
MC33060ADR2	,	MC33063AD	,	MC33063ADR2	,	MC33063AVD
MC33063AVDR2	,	MC33064D-005	,	MC33064D-5R2	,	MC33071AD
MC33071ADR2	,	MC33071D	,	MC33071DR2	,	MC33072AD
MC33072ADR2	,	MC33072D	,	MC33072DR2	,	MC33074AD
MC33074ADR2	,	MC33074D	,	MC33074DR2	,	MC33076D
MC33076DR2	,	MC33077D	,	MC33077DR2	,	MC33078D
MC33078DR2	,	MC33079D	,	MC33079DR2	,	MC33091AD
MC33091ADR2	,	MC33095D	,	MC33095DR2	,	MC33102D
MC33102DR2	,	MC33110D	,	MC33110DR2	,	MC33111D
MC33111DR2	,	MC33129D	,	MC33129DR2	,	MC33151D
MC33151DR2	,	MC33151VD	,	MC33151VDR2	,	MC33152D
MC33152DR2	,	MC33152VDR2	,	MC33153D	,	MC33153DR2
MC33161D	,	MC33161DR2	,	MC33164D-003	,	MC33164D-005
MC33164D-3.3	,	MC33164D-3.3R2	,	MC33164D-3R2	,	MC33164D-4.6
MC33164D-4.6R2	,	MC33164D-5R2	,	MC33171D	,	MC33171DR2
MC33172D	,	MC33172DR2	,	MC33172VD	,	MC33172VDR2
MC33174D	,	MC33174DR2	,	MC33174VDR2	,	MC33178D
MC33178DR2	,	MC33179D	,	MC33179DR2	,	MC33181D
MC33181DR2	,	MC33182D	,	MC33182DR2	,	MC33184D
MC33184DR2	,	MC33187D	,	MC33187DR2	,	MC33193D
MC33193DR2	,	MC33197AD	,	MC33197ADR2	,	MC33198D
MC33198DR2	,	MC33199D	,	MC33199DR2	,	MC33201D
MC33201DR2	,	MC33201VD	,	MC33202D	,	MC33202DR2
MC33202VD	,	MC33202VDR2	,	MC33204D	,	MC33204DR2
MC33204VD	,	MC33204VDR2	,	MC33206D	,	MC33206DR2
MC33207D	,	MC33207DR2	,	MC33232D	,	MC33232DR2
MC33260D	,	MC33261D	,	MC33261DR2	,	MC33262D
MC33262DR2	,	MC33264D-2.8	,	MC33264D-2.8R2	,	MC33264D-3.0
MC33264D-3.0R2	,	MC33264D-3.3	,	MC33264D-3.3R2	,	MC33264D-3.8
MC33264D-3.8R2	,	MC33264D-4.0	,	MC33264D-4.0R2	,	MC33264D-4.75
MC33264D-4.75R2	,	MC33264D-5.0	,	MC33264D-5.0R2	,	MC33269D
MC33269D-012	,	MC33269D-3.3	,	MC33269D-3.3R2	,	MC33269D-5.0
MC33269DR2	,	MC33269DR2-012	,	MC33269DR2-3.3	,	MC33269DR2-5.0
MC33272AD	,	MC33272ADR2	,	MC33274AD	,	MC33274ADR2
MC33275D-2.5	,	MC33275D-2.5R2	,	MC33275D-3.0	,	MC33275D-3.0R2
MC33275D-3.3	,	MC33275D-3.3R2	,	MC33275D-5.0	,	MC33275D-5.0R2
MC33282D	,	MC33282DR2	,	MC33284D	,	MC33284DR2
MC33285D	,	MC33285DR2	,	MC33290D	,	MC33290DR2
MC33304D	,	MC33304DR2	,	MC33340D	,	MC33340DR2
MC33341D	,	MC33341DR2	,	MC33342D	,	MC33342DR2
MC33347AD	,	MC33347ADR2	,	MC3334D	,	MC3334DR2
MC33364D	,	MC33364D1	,	MC33364D1R2	,	MC33364D2
MC33364D2R2	,	MC33364DR2	,	MC33368D	,	MC33368DR2
MC33375D-2.5	,	MC33375D-2.5R2	,	MC33375D-3.0	,	MC33375D-3.0R2
MC33375D-3.3	,	MC33375D-3.3R2	,	MC33375D-5.0	,	MC33375D-5.0R2
MC33390D	,	MC33390DR2	,	MC3346D	,	MC3346DR2

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC33502D	,	MC33502DR2	,	MC33565D	,	MC33565DR2
MC33567D-001	,	MC33567D-002	,	MC33567D-1R2	,	MC33567D-2R2
MC3358D	,	MC3358DR2	,	MC3361BD	,	MC3361BDR2
MC3361CD	,	MC3361CDR2	,	MC3371D	,	MC3371DR2
MC3372D	,	MC3372DR2	,	MC34001BD	,	MC34001D
MC34001DR2	,	MC34002BD	,	MC34002BDR2	,	MC34002D
MC34002DR2	,	MC34012-2D	,	MC34012-2DR2	,	MC34017-1D
MC34017-1DR2	,	MC34017-2D	,	MC34017-2DR2	,	MC3403D
MC3403DR2	,	MC3405D	,	MC3405DR2	,	MC34060AD
MC34060ADR2	,	MC34063AD	,	MC34063ADR2	,	MC34063BD
MC34063BDR2	,	MC34064D-005	,	MC34064D-5R2	,	MC34071AD
MC34071ADR2	,	MC34071D	,	MC34071DR2	,	MC34072AD
MC34072ADR2	,	MC34072D	,	MC34072DR2	,	MC34072VD
MC34072VDR2	,	MC34074AD	,	MC34074ADR2	,	MC34074D
MC34074DR2	,	MC34074VD	,	MC34074VDR2	,	MC34080BD
MC34080BDR2	,	MC34081BD	,	MC34081BDR2	,	MC34119D
MC34119DR2	,	MC34129D	,	MC34129DR2	,	MC34151D
MC34151DR2	,	MC34152D	,	MC34152DR2	,	MC34161D
MC34161DR2	,	MC34164D-003	,	MC34164D-005	,	MC34164D-3.3
MC34164D-3.3R2	,	MC34164D-3R2	,	MC34164D-4.6	,	MC34164D-4.6R2
MC34164D-5R2	,	MC34181D	,	MC34181DR2	,	MC34182D
MC34182DR2	,	MC34184D	,	MC34184DR2	,	MC34217D
MC34217DR2	,	MC3423D	,	MC3423DR2	,	MC34261DR2
MC34262D	,	MC34262DR2	,	MC34268D	,	MC34268DR2
MC3458D	,	MC3458DR2	,	MC3488AD	,	MC3488ADR2
MC44144D1	,	MC44144D1R2	,	MC44306D	,	MC44306DR2
MC44817SBD	,	MC44817SBDR2	,	MC44817SD	,	MC44817SDR2
MC44818D	,	MC44818DR2	,	MC44829D	,	MC44829DR2
MC4558CD	,	MC4558CDR2	,	MC4558VD	,	MC4558VDR2
MC4741CD	,	MC4741CDR2	,	MC623DR2	,	MC642DR2
MC680DR2	,	MC74AC00D	,	MC74AC00DR2	,	MC74AC02D
MC74AC02DR2	,	MC74AC04D	,	MC74AC04DR2	,	MC74AC05D
MC74AC05DR2	,	MC74AC08D	,	MC74AC08DR2	,	MC74AC109D
MC74AC109DR2	,	MC74AC10D	,	MC74AC10DR2	,	MC74AC11D
MC74AC11DR2	,	MC74AC125D	,	MC74AC125DR2	,	MC74AC132D
MC74AC132DR2	,	MC74AC138D	,	MC74AC138DR2	,	MC74AC139D
MC74AC139DR2	,	MC74AC14D	,	MC74AC14DR2	,	MC74AC151D
MC74AC151DR2	,	MC74AC153D	,	MC74AC153DR2	,	MC74AC157D
MC74AC157DR2	,	MC74AC161D	,	MC74AC161DR2	,	MC74AC163D
MC74AC163DR2	,	MC74AC174D	,	MC74AC174DR2	,	MC74AC175D
MC74AC175DR2	,	MC74AC20D	,	MC74AC20DR2	,	MC74AC253D
MC74AC253DR2	,	MC74AC257D	,	MC74AC257DR2	,	MC74AC259D
MC74AC259DR2	,	MC74AC32D	,	MC74AC32DR2	,	MC74AC352DR2
MC74AC4040D	,	MC74AC4040DR2	,	MC74AC74D	,	MC74AC74DR2
MC74AC86D	,	MC74AC86DR2	,	MC74ACT00D	,	MC74ACT00DR2
MC74ACT02D	,	MC74ACT02DR2	,	MC74ACT04D	,	MC74ACT04DR2
MC74ACT05D	,	MC74ACT05DR2	,	MC74ACT08D	,	MC74ACT08DR2
MC74ACT109D	,	MC74ACT109DR2	,	MC74ACT10D	,	MC74ACT10DR2
MC74ACT11D	,	MC74ACT11DR2	,	MC74ACT125D	,	MC74ACT125DR2
MC74ACT132D	,	MC74ACT132DR2	,	MC74ACT138D	,	MC74ACT138DR2
MC74ACT139D	,	MC74ACT139DR2	,	MC74ACT14D	,	MC74ACT14DR2

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC74ACT151D	,	MC74ACT151DR2	,	MC74ACT153D	,	MC74ACT153DR2
MC74ACT157D	,	MC74ACT157DR2	,	MC74ACT161D	,	MC74ACT161DR2
MC74ACT163D	,	MC74ACT163DR2	,	MC74ACT174D	,	MC74ACT174DR2
MC74ACT175D	,	MC74ACT175DR2	,	MC74ACT20D	,	MC74ACT20DR2
MC74ACT253D	,	MC74ACT253DR2	,	MC74ACT257D	,	MC74ACT257DR2
MC74ACT259D	,	MC74ACT259DR2	,	MC74ACT32D	,	MC74ACT32DR2
MC74ACT74D	,	MC74ACT74DR2	,	MC74ACT86D	,	MC74ACT86DR2
MC74HC00AD	,	MC74HC00ADR2	,	MC74HC02AD	,	MC74HC02ADR2
MC74HC03AD	,	MC74HC03ADR2	,	MC74HC04AD	,	MC74HC04ADR2
MC74HC08AD	,	MC74HC08ADR2	,	MC74HC125AD	,	MC74HC125ADR2
MC74HC126AD	,	MC74HC126ADR2	,	MC74HC132AD	,	MC74HC132ADR2
MC74HC138AD	,	MC74HC138ADR2	,	MC74HC139AD	,	MC74HC139ADR2
MC74HC14AD	,	MC74HC14ADR2	,	MC74HC157AD	,	MC74HC157ADR2
MC74HC161AD	,	MC74HC161ADR2	,	MC74HC163AD	,	MC74HC163ADR2
MC74HC164AD	,	MC74HC164ADR2	,	MC74HC164DR2	,	MC74HC165AD
MC74HC165ADR2	,	MC74HC165D	,	MC74HC165DR2	,	MC74HC174AD
MC74HC174ADR2	,	MC74HC175AD	,	MC74HC175ADR2	,	MC74HC175D
MC74HC175DR2	,	MC74HC32AD	,	MC74HC32ADR2	,	MC74HC390AD
MC74HC390ADR2	,	MC74HC390D	,	MC74HC390DR2	,	MC74HC393AD
MC74HC393ADR2	,	MC74HC393D	,	MC74HC393DR2	,	MC74HC4020AD
MC74HC4020ADR2	,	MC74HC4040AD	,	MC74HC4040ADR2	,	MC74HC4046AD
MC74HC4046ADR2	,	MC74HC4051AD	,	MC74HC4051ADR2	,	MC74HC4051ADWR2
MC74HC4051D	,	MC74HC4051DR2	,	MC74HC4052AD	,	MC74HC4052ADR2
MC74HC4052D	,	MC74HC4052DR2	,	MC74HC4053AD	,	MC74HC4053ADR2
MC74HC4053D	,	MC74HC4053DR2	,	MC74HC4060AD	,	MC74HC4060ADR2
MC74HC4066AD	,	MC74HC4066ADR2	,	MC74HC4066D	,	MC74HC4066DR2
MC74HC4316AD	,	MC74HC4316ADR2	,	MC74HC4316D	,	MC74HC4316DR2
MC74HC4538AD	,	MC74HC4538ADR2	,	MC74HC4851AD	,	MC74HC4851ADR2
MC74HC4852AD	,	MC74HC4852ADR2	,	MC74HC589AD	,	MC74HC589ADR2
MC74HC589DR2	,	MC74HC595AD	,	MC74HC595ADR2	,	MC74HC74AD
MC74HC74ADR2	,	MC74HC86AD	,	MC74HC86ADR2	,	MC74HCT04AD
MC74HCT04ADR2	,	MC74HCT138AD	,	MC74HCT138ADR2	,	MC74HCT14AD
MC74HCT14ADR2	,	MC74HCT74AD	,	MC74HCT74ADR2	,	MC74HCU04AD
MC74HCU04ADR2	,	MC74HCU04D	,	MC74HCU04DR2	,	MC74LCX00D
MC74LCX00DR2	,	MC74LCX02D	,	MC74LCX02DR2	,	MC74LCX04D
MC74LCX04DR2	,	MC74LCX08D	,	MC74LCX08DR2	,	MC74LCX125D
MC74LCX125DR2	,	MC74LCX138D	,	MC74LCX138DR2	,	MC74LCX157D
MC74LCX157DR2	,	MC74LCX257D	,	MC74LCX257DR2	,	MC74LCX32D
MC74LCX32DR2	,	MC74LCX74D	,	MC74LCX74DR2	,	MC74LCX86D
MC74LCX86DR2	,	MC74LVQ04DR2	,	MC74LVQ125DR2	,	MC74LVX00D
MC74LVX00DR2	,	MC74LVX02D	,	MC74LVX02DR2	,	MC74LVX04D
MC74LVX04DR2	,	MC74LVX08D	,	MC74LVX08DR2	,	MC74LVX125D
MC74LVX125DR2	,	MC74LVX126D	,	MC74LVX126DR2	,	MC74LVX132D
MC74LVX132DR2	,	MC74LVX138D	,	MC74LVX138DR2	,	MC74LVX139D
MC74LVX139DR2	,	MC74LVX14D	,	MC74LVX14DR2	,	MC74LVX157D
MC74LVX157DR2	,	MC74LVX32D	,	MC74LVX32DR2	,	MC74LVX390D
MC74LVX393D	,	MC74LVX393DR2	,	MC74LVX4066D	,	MC74LVX4066DR2
MC74LVX595D	,	MC74LVX595DR2	,	MC74LVX74D	,	MC74LVX74DR2
MC74LVX8051D	,	MC74LVX8051DR2	,	MC74LVX8053D	,	MC74LVX8053DR2
MC74LVX86D	,	MC74LVX86DR2	,	MC74LVXT4066D	,	MC74LVXT4066DR2
MC74LVXT8051D	,	MC74LVXT8051DR2	,	MC74LVXT8053D	,	MC74LVXT8053DR2

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

MC74VHC00D	,	MC74VHC00DR2	,	MC74VHC02D	,	MC74VHC02DR2
MC74VHC04D	,	MC74VHC04DR2	,	MC74VHC08D	,	MC74VHC08DR2
MC74VHC125D	,	MC74VHC125DR2	,	MC74VHC126D	,	MC74VHC126DR2
MC74VHC132D	,	MC74VHC132DR2	,	MC74VHC138D	,	MC74VHC138DR2
MC74VHC139D	,	MC74VHC139DR2	,	MC74VHC14D	,	MC74VHC14DR2
MC74VHC157D	,	MC74VHC157DR2	,	MC74VHC32D	,	MC74VHC32DR2
MC74VHC390D	,	MC74VHC393D	,	MC74VHC393DR2	,	MC74VHC4051D
MC74VHC4051DR2	,	MC74VHC4052D	,	MC74VHC4052DR2	,	MC74VHC4053D
MC74VHC4053DR2	,	MC74VHC4066D	,	MC74VHC4066DR2	,	MC74VHC4538D
MC74VHC4538DR2	,	MC74VHC50D	,	MC74VHC50DR2	,	MC74VHC595D
MC74VHC595DR2	,	MC74VHC74D	,	MC74VHC74DR2	,	MC74VHC86D
MC74VHC86DR2	,	MC74VHCT00AD	,	MC74VHCT00ADR2	,	MC74VHCT02AD
MC74VHCT02ADR2	,	MC74VHCT04AD	,	MC74VHCT04ADR2	,	MC74VHCT08AD
MC74VHCT08ADR2	,	MC74VHCT125AD	,	MC74VHCT125ADR2	,	MC74VHCT126AD
MC74VHCT126ADR2	,	MC74VHCT132AD	,	MC74VHCT132ADR2	,	MC74VHCT138AD
MC74VHCT138ADR2	,	MC74VHCT14AD	,	MC74VHCT14ADR2	,	MC74VHCT14ADT
MC74VHCT14ADTR2	,	MC74VHCT32AD	,	MC74VHCT32ADR2	,	MC74VHCT4051D
MC74VHCT4051DR2	,	MC74VHCT4053D	,	MC74VHCT4053DR2	,	MC74VHCT4066D
MC74VHCT4066DR2	,	MC74VHCT50AD	,	MC74VHCT50ADR2	,	MC74VHCT74AD
MC74VHCT74ADR2	,	MC74VHCT86AD	,	MC74VHCT86ADR2	,	MC74VHCU04D
MC74VHCU04DR2	,	MC7660DR2	,	MC78L05ABD	,	MC78L05ABDR2
MC78L05ACD	,	MC78L05ACDR2	,	MC78L08ABD	,	MC78L08ABDR2
MC78L08ACD	,	MC78L08ACDR2	,	MC78L09ABD	,	MC78L09ABDR2
MC78L09ACD	,	MC78L09ACDR2	,	MC78L12ABD	,	MC78L12ABDR2
MC78L12ACD	,	MC78L12ACDR2	,	MC78L15ABD	,	MC78L15ABDR2
MC78L15ACD	,	MC78L15ACDR2	,	MC79L05ABD	,	MC79L05ABDR2
MC79L05ACD	,	MC79L05ACDR2	,	MC79L12ABD	,	MC79L12ABDR2
MC79L12ACD	,	MC79L12ACDR2	,	MC79L15ABD	,	MC79L15ABDR2
MC79L15ACD	,	MC79L15ACDR2	,	MCCS142234D	,	MCH12140D
MCH12140DR2	,	MCK12140D	,	MCK12140DR2	,	MCT1458CD
MCT1458D	,	MCT1458DR2	,	MCT4558CD	,	MCZ1413D
MCZ33091AD	,	MCZ33091ADR2	,	MCZ33095D	,	MCZ33095DR2
MCZ33172D	,	MCZ33174D	,	MCZ33272AD	,	MCZ3403D
MCZ4558CD	,	MCZ4558CDR2	,	MDC3405	,	MDC3405R1
MDC3405R2	,	MMPQ2222A	,	MMPQ2222AR1	,	MMPQ2222AR2
MMPQ2369	,	MMPQ2369R2	,	MMPQ3467	,	MMPQ3725
MMPQ3725R1	,	MMPQ3725R2	,	MMPQ3904	,	MMPQ3906
MMPQ3906R1	,	MMPQ3906R2	,	MMPQ6700	,	MPC905D
MPC905DR2	,	MPIC2117D	,	MPIC2151D	,	MRFIC0903
MRFIC0904	,	MRFIC0914	,	MRFIC0930	,	MRFIC0930R2
MRFIC0931	,	MRFIC1501	,	MRFIC1501R2	,	MRFIC1801
MRFIC1803	,	MRFIC1804	,	MRFIC1806	,	MRFIC1807
MRFIC1807R2	,	MRFIC1808	,	MRFIC2001	,	MRFIC2002
MRFIC2004	,	MRFIC2006	,	MRFIC2006R2	,	MRFIC2101
MRFIC2401	,	MRFIC2404	,	MRFIC2406	,	PC100EL1648D
PC100EL1648DR2	,	PC100EP11D	,	PC100EPT21D	,	PC100EPT22D
PC100EPT23D	,	PC100EPT24D	,	PC100EPT25D	,	PC100EPT26D
PC10EP01D	,	PC10EP05D	,	PC10EP08D	,	PC10EP11D
PC10EP16D	,	PC10EP31D	,	PC10EP32D	,	PC10EP33D
PC10EP35D	,	PC10EP58D	,	PC10EP89D	,	PC10EPT20D
PC10SX1125AD	,	PC10SX1126D	,	PC13141D	,	PC33290D

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

PC33388D	,	PC33390D	,	PC33390DR2	,	PC33480D1
PC33567D-002	,	PC44BC380D	,	PC44BC380DR2	,	PC68151DV
PC905XD	,	PC910801D	,	PCDSID2CD	,	PMC14011BD
PMC14013BD	,	PMC14051BD	,	PMC14052BD	,	PMC14053BD
PMC14066BD	,	PMC14538BD	,	PMC14551BD	,	PMC74HC74AD
PMC74HC74ADR2	,	PSN74LS14D	,	PY40495D	,	PY40495DR2
SA14011BD	,	SA14011BDR2	,	SA14013BD	,	SA14013BDR2
SA14021BD	,	SA14021BDR2	,	SA14023BD	,	SA14023BDR2
SA14040BD	,	SA14040BDR2	,	SA14050BD	,	SA14050BDR2
SA14051BD	,	SA14051BDR2	,	SA14052BD	,	SA14052BDR2
SA14053BD	,	SA14053BDR2	,	SA14060BD	,	SA14060BDR2
SA14066BD	,	SA14066BDR2	,	SA14069UBD	,	SA14069UBDR2
SA14070BD	,	SA14070BDR2	,	SA14073BD	,	SA14073BDR2
SA14081BD	,	SA14081BDR2	,	SA14093BD	,	SA14093BDR2
SA14094BD	,	SA14094BDR2	,	SA14106BD	,	SA14106BDR2
SA1413BD	,	SA1413BDR2	,	SA1413D	,	SA1413DR2
SA14175BD	,	SA14175BDR2	,	SA14503BD	,	SA14503BDR2
SA14504BD	,	SA14504BDR2	,	SA14512BD	,	SA14512BDR2
SA14538BD	,	SA14538BDR2	,	SA14541BD	,	SA14541BDR2
SA14551BD	,	SA14551BDR2	,	SA14584BD	,	SA14584BDR2
SA33072DR2	,	SB33262DR2	,			
SN74LS00D	,	SN74LS00DR2	,	SN74LS04D	,	SN74LS04DR2
SN74LS05D	,	SN74LS05DR2	,	SN74LS08D	,	SN74LS08DR2
SN74LS109AD	,	SN74LS122D	,	SN74LS122DR2	,	SN74LS123D
SN74LS123DR2	,	SN74LS125AD	,	SN74LS125ADR2	,	SN74LS126AD
SN74LS126ADR2	,	SN74LS132D	,	SN74LS132DR2	,	SN74LS138D
SN74LS138DR2	,	SN74LS139D	,	SN74LS139DR2	,	SN74LS145D
SN74LS145DR2	,	SN74LS148D	,	SN74LS148DR2	,	SN74LS14D
SN74LS14DR2	,	SN74LS151D	,	SN74LS151DR2	,	SN74LS153D
SN74LS156D	,	SN74LS156DR2	,	SN74LS157D	,	SN74LS157DR2
SN74LS161AD	,	SN74LS161ADR2	,	SN74LS163AD	,	SN74LS163ADR2
SN74LS164D	,	SN74LS164DR2	,	SN74LS165D	,	SN74LS165DR2
SN74LS166D	,	SN74LS166DR2	,	SN74LS174D	,	SN74LS174DR2
SN74LS175D	,	SN74LS175DR2	,	SN74LS193D	,	SN74LS193DR2
SN74LS194AD	,	SN74LS194ADR2	,	SN74LS195ADR2	,	SN74LS221D
SN74LS221DR2	,	SN74LS247D	,	SN74LS247DR2	,	SN74LS251D
SN74LS251DR2	,	SN74LS253D	,	SN74LS253DR2	,	SN74LS257BD
SN74LS257BDR2	,	SN74LS258BD	,	SN74LS258BDR2	,	SN74LS259D
SN74LS259DR2	,	SN74LS260D	,	SN74LS260DR2	,	SN74LS280D
SN74LS280DR2	,	SN74LS283D	,	SN74LS298D	,	SN74LS298DR2
SN74LS32D	,	SN74LS32DR2	,	SN74LS365AD	,	SN74LS365ADR2

UPDATE NOTIFICATION

ISSUE DATE: 15-Mar-2000

NOTIFICATION #:10152

EFFECTIVE DATE: 16-Mar-2000

ISSUING DIVISION:ON SEMICONDUCTO

SN74LS367AD	,	SN74LS367ADR2	,	SN74LS368AD	,	SN74LS368ADR2
SN74LS38D	,	SN74LS38DR2	,	SN74LS393D	,	SN74LS393DR2
SN74LS395D	,	SN74LS42D	,	SN74LS42DR2	,	SN74LS47D
SN74LS670D	,	SN74LS74AD	,	SN74LS74ADR2	,	SN74LS76AD
SN74LS85D	,	SN74LS85DR2	,	SN74LS86D	,	SN74LS86DR2
SPAKXC68176DV	,	SRFIC11N01	,	SRFIC25E02	,	SRFIC49C06
SRFIC49C07	,	SRFIC49C08	,	SRFIC49C12	,	SRFIC49C13
SRFIC50C06	,	TCF6000D	,	TCF6000DR2	,	TCF7011D
TCF7011DR2	,	TCM2951-3.0VOA	,	TCM2951-3.3VOA	,	TCM2951-5.0VOA
TCM33063AVOA	,	TCM33368VOM	,	TCM4949VOA	,	TL062ACD
TL062ACDR2	,	TL062CD	,	TL062CDR2	,	TL062VD
TL062VDR2	,	TL064ACD	,	TL064ACDR2	,	TL064CD
TL064CDR2	,	TL064VD	,	TL064VDR2	,	TL071ACD
TL072ACD	,	TL072ACDR2	,	TL072CD	,	TL072CDR2
TL081ACD	,	TL081ACDR2	,	TL081CD	,	TL081CDR2
TL082ACD	,	TL082ACDR2	,	TL082CD	,	TL082CDR2
TL431ACD	,	TL431ACDR2	,	TL431AID	,	TL431AIDR2
TL431BCD	,	TL431BCDR2	,	TL431BID	,	TL431BIDR2
TL431BVD	,	TL431CD	,	TL431CDR2	,	TL431ID
TL431IDR2	,	TL494BD	,	TL494BDR2	,	TL494CD
TL494CDR2	,	TL594CD	,	TL594CDR2	,	TLX431AID
TLX431AIDR2	,	TSC14053BD	,	TSC14053BDR2	,	TY30533R2
TY30577DR2	,	TY30578DR2	,	TY38442D	,	TY38442DR2
TY60080D	,	TY60080DR2	,	TY93051AD	,	TY93051ADR2
TY93075ADR2	,	TY94100D	,	TY94100DR2	,	TY94101D
TYA1496DR2	,	TYA33164D-5R2	,	TYA33272ADR2	,	TYB44B17BDR2
UAA2016AD	,	UAA2016D	,	UC2842AD	,	UC2842ADR2
UC2842BD	,	UC2842BD1	,	UC2842BD1R2	,	UC2843AD
UC2843AD2	,	UC2843AD2R2	,	UC2843ADR2	,	UC2843BD
UC2843BD1	,	UC2843BD1R2	,	UC2844BD1R2	,	UC2844BDR2
UC2844D	,	UC2844DR2	,	UC2845BD	,	UC2845BD1
UC2845BD1R2	,	UC2845BDR2	,	UC2845D	,	UC2845DR2
UC3842AD	,	UC3842ADR2	,	UC3842BD	,	UC3842BD1
UC3842BD1R2	,	UC3842BDR2	,	UC3842BVD1	,	UC3842BVD1R2
UC3842BVDR2	,	UC3843AD	,	UC3843AD2	,	UC3843AD2R2
UC3843ADR2	,	UC3843BD	,	UC3843BD1	,	UC3843BD1R2
UC3843BDR2	,	UC3843BVD	,	UC3843BVD1	,	UC3843BVD1R2
UC3843BVDR2	,	UC3844BD	,	UC3844BD1	,	UC3844BD1R2
UC3844BDR2	,	UC3844BVD	,	UC3844BVD1	,	UC3844BVD1R2
UC3844BVDR2	,	UC3844D	,	UC3844DR2	,	UC3845BD
UC3845BD1	,	UC3845BD1R2	,	UC3845BDR2	,	UC3845BVD
UC3845BVD1	,	UC3845BVD1R2	,	UC3845D	,	UC3845DR2
UCX2843AD	,	UCX2843ADR2	,	XC100LVELT23D	,	XC100LVELT23DR2
XC33095D	,	XC33095DR2	,	XC44BC380D	,	XC44BC380DR2
XC68151DV	,	XC68176DV	,	XC68HC55CD	,	XCWF68HC57
XY93091D	,	XY93091DR2	,	XY94100DR2	,	XY94101D