



INITIAL PRODUCT/PROCESS CHANGE NOTIFICATION
Generic Copy

Issue Date
31-Jul-2006

SUBJECT: ON Semiconductor Initial Product/Process Change Notification # 15621

TITLE: Initial Notification of Qualification of OSPI for Assembly/Test of 16/20/24/28 Lead SOIC Wide Body Packages

PROPOSED FIRST SHIP DATE: 30-Nov-2006

AFFECTED CHANGE CATEGORY: ON Semiconductor Assembly & Test Site

AFFECTED PRODUCT DIVISION: **Analog Power Management**
 Standard Components
 Integrated Products

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:
Contact Sales Office or Alan Garlington@onsemi.com>

NOTIFICATION TYPE:

Initial Product/Process Change Notification (IPCN)

First change notification sent to customers. IPCNs are issued at least 120 days prior to implementation of the change. An IPCN is advance notification about an upcoming change and contains general information regarding the change details and devices affected. It also contains the preliminary reliability qualification plan.

The completed qualification and characterization data will be included in the Final Product/Process Change Notification (FPCN).

This IPCN notification will be followed by a Final Product/Process Change Notification (FPCN) at least 60 days prior to implementation of the change.

DESCRIPTION AND PURPOSE:

Initial Process Change Notice to notify customers of the capacity expansion of the ON Semiconductor assembly/test location at Carmona, Philippines (OSPI) for 16/20/24/28 lead Wide body SOIC packages. The devices listed on this IPCN have historically been assembled/tested at the ASE assembly/test facility located in Chung Li, Taiwan. At the expiration of this Initial PCN and subsequent Final PCN, these devices may be processed at either location. This is not a transfer but a capacity expansion.



Initial Product/Process Change Notification # 15621

QUALIFICATION PLAN:

AC/PC 121C, 15psig, 100%RH 96hrs
 TC/PC -65/150C 500cycles
 HTSL 175C 504hrs
 HAST/PC 130C, 85%RH 96hrs
 HTOL 125C 1008hrs
 ELFR 125C for 48hrs or 150C for 24hrs
 Solderability 245C, 8hrs
 WBS Wire Bond Shear Test : Cpk>1.33
 WBP Wire Bond Pull: Cpk>1.33
 PD Physical Dimension Cpk>1.33
 ESD (HBM/MM/CDM) :Test@ R/H

AFFECTED DEVICE LIST:

<u>DEVICE</u>	<u>DEVICE</u>	<u>DEVICE</u>
CS41092DWF16	CS5165AGDWR16	CS92404BDWR16
CS41092DWR16	CS5165AGDWR16G	CS92404BDWR16G
CS41113DWR16	CS61012DW28	LM2574DW-ADJ
CS41129DWR16	CS61012DWR28	LM2574DW-ADJR2
CS41143DWR28	CS61133DWF24	LM2574DW-ADJR2G
CS41154DWR24	CS61133DWR24	MC100EL13DW
CS4121EDWF20	CS61178DWR20	MC100EL13DWG
CS4121EDWF20G	CS68004DW16	MC100EL13DWR2
CS4121EDWFR20	CS68004DWR16	MC100EL13DWR2G
CS4121EDWFR20G	CS68004DWR16G	MC100EL14DW
CS4122XDWF24	CS68059DWR24	MC100EL14DWG
CS4122XDWF24G	CS68110DWR24	MC100EL14DWR2
CS4122XDWFR24	CS68140DWR28	MC100EL14DWR2G
CS4122XDWFR24G	CS69124DWR16	MC100EL17DW
CS4192XDWF16	CS8101YDWF20	MC100EL17DWG
CS4192XDWF16G	CS8101YDWF20G	MC100EL17DWR2
CS4192XDWFR16	CS8101YDWFR20	MC100EL17DWR2G
CS4192XDWFR16G	CS8101YDWFR20G	MC100EL29DW
CS43021DWR16	CS8129YDW16	MC100EL29DWG
CS43079DWR20	CS8129YDW16G	MC100EL29DWR2
CS43141DWR24	CS8129YDWR16	MC100EL29DWR2G
CS43171DWR16	CS8129YDWR16G	MC100EL30DW
CS44114DWR16	CS8151YDWF16	MC100EL30DWG
CS44114DWR16G	CS8151YDWF16G	MC100EL30DWR2
CS45092DWR16	CS8151YDWFR16	MC100EL30DWR2G
CS45093DWF16	CS8151YDWFR16G	MC100EL38DW
CS45093DWR16	CS8183YDWF20	MC100EL38DWG
CS49053DWR16	CS8183YDWF20G	MC100EL38DWR2
CS49053DWR16G	CS8183YDWFR20	MC100EL38DWR2G
CS5101EDW16	CS8183YDWFR20G	MC100EL39DW
CS5101EDW16G	CS8190EDWF20	MC100EL39DWG
CS5101EDWR16	CS8190EDWF20G	MC100EL39DWR2
CS5101EDWR16G	CS8190EDWFR20	MC100EL39DWR2G
CS5112YDWF24	CS8190EDWFR20G	MC100EL56DW
CS5112YDWF24G	CS8361YDWF16	MC100EL56DWG
CS5112YDWFR24	CS8361YDWF16G	MC100EL56DWR2
CS5165AGDW16G	CS92404BDW16	MC100EL59DWG



**Initial Product/Process Change Notification #15621
AFFECTED DEVICE LIST:**

<u>DEVICE</u>	<u>DEVICE</u>	<u>DEVICE</u>
MC100EL90DW	MC100LVEL39DWG	MC14490DWR2
MC100EL90DWG	MC100LVEL39DWR2	MC14490DWR2G
MC100EL90DWR2	MC100LVEL39DWR2G	MC14511BDWR2
MC100EL90DWR2G	MC100LVEL40DW	MC14511BDWR2G
MC100EL91DW	MC100LVEL40DWG	MC14514BDWR2
MC100EL91DWG	MC100LVEL40DWR2	MC14514BDWR2G
MC100EL91DWR2	MC100LVEL40DWR2G	MC14515BDWR2
MC100EL91DWR2G	MC100LVEL56DW	MC14515BDWR2G
MC100EP139DW	MC100LVEL56DWG	MC14517BDW
MC100EP139DWG	MC100LVEL56DWR2	MC14517BDWG
MC100EP139DWR2	MC100LVEL56DWR2G	MC14517BDWR2
MC100EP139DWR2G	MC100LVEL59DW	MC14517BDWR2G
MC100EP17DW	MC100LVEL59DWG	MC14518BDW
MC100EP17DWG	MC100LVEL59DWR2	MC14518BDWG
MC100EP17DWR2	MC100LVEL59DWR2G	MC14518BDWR2
MC100EP17DWR2G	MC100LVEL90DW	MC14518BDWR2G
MC100EP56DW	MC100LVEL90DWG	MC14520BDW
MC100EP56DWG	MC100LVEL90DWR2	MC14520BDWG
MC100EP56DWR2	MC100LVEL90DWR2G	MC14520BDWR2
MC100EP56DWR2G	MC100LVEL91DW	MC14520BDWR2G
MC100LVEL13DW	MC100LVEL91DWG	MC14526BDW
MC100LVEL13DWG	MC100LVEL91DWR2	MC14526BDWG
MC100LVEL13DWR2	MC100LVEL91DWR2G	MC14526BDWR2
MC100LVEL13DWR2G	MC100LVEL92DW	MC14526BDWR2G
MC100LVEL14DW	MC100LVEL92DWG	MC14536BDW
MC100LVEL14DWG	MC100LVEL92DWR2	MC14536BDWG
MC100LVEL14DWR2	MC100LVEL92DWR2G	MC14536BDWR2
MC100LVEL14DWR2G	MC10EP139DW	MC14536BDWR2G
MC100LVEL17DW	MC10EP139DWG	MC14538BDW
MC100LVEL17DWG	MC10EP139DWR2	MC14538BDWG
MC100LVEL17DWR2	MC10EP139DWR2G	MC14538BDWR2
MC100LVEL17DWR2G	MC10EP17DW	MC14538BDWR2G
MC100LVEL29DW	MC10EP17DWG	MC14549BDWR2
MC100LVEL29DWG	MC10EP17DWR2	MC14549BDWR2G
MC100LVEL29DWR2	MC10EP17DWR2G	MC14557BDW
MC100LVEL29DWR2G	MC14046BDW	MC14557BDWG
MC100LVEL30DW	MC14046BDWG	MC14557BDWR2
MC100LVEL30DWG	MC14046BDWR2	MC14557BDWR2G
MC100LVEL30DWR2	MC14046BDWR2G	MC14559BDWR2
MC100LVEL30DWR2G	MC14067BDW	MC14559BDWR2G
MC100LVEL37DW	MC14067BDWG	MC14569BDW
MC100LVEL37DWG	MC14067BDWR2	MC14569BDWG
MC100LVEL37DWR2	MC14067BDWR2G	MC14569BDWR2
MC100LVEL37DWR2G	MC14099BDW	MC14569BDWR2G
MC100LVEL38DW	MC14099BDWG	MC33023DW
MC100LVEL38DWG	MC14099BDWR2	MC33023DWG
MC100LVEL38DWR2	MC14099BDWR2G	MC33023DWR2
MC100LVEL38DWR2G	MC14490DW	MC33023DWR2G
MC100LVEL39DW	MC14490DWG	MC33025DW



**Initial Product/Process Change Notification #15621
AFFECTED DEVICE LIST:**

<u>DEVICE</u>	<u>DEVICE</u>	<u>DEVICE</u>
MC33025DWG	MC34025DWR2	MC74AC540DWR2G
MC33025DWR2	MC34025DWR2G	MC74AC541DW
MC33025DWR2G	MC34067DW	MC74AC541DWG
MC33030DW	MC34067DWG	MC74AC541DWR2
MC33030DWG	MC34067DWR2	MC74AC541DWR2G
MC33030DWR2	MC34067DWR2G	MC74AC573DW
MC33030DWR2G	MC34160DW	MC74AC573DWG
MC33033DW	MC34160DWG	MC74AC573DWR2
MC33033DWG	MC34160DWR2	MC74AC573DWR2G
MC33033DWR2	MC34160DWR2G	MC74AC574DW
MC33033DWR2G	MC34163DW	MC74AC574DWG
MC33035DW	MC34163DWG	MC74AC574DWR2
MC33035DWG	MC34163DWR2	MC74AC574DWR2G
MC33035DWR2	MC34163DWR2G	MC74AC646DW
MC33035DWR2G	MC44603ADW	MC74AC646DWG
MC33067DW	MC44603ADWG	MC74AC646DWR2
MC33067DWG	MC44603ADWR2	MC74AC646DWR2G
MC33067DWR2	MC44603ADWR2G	MC74AC652DWR2
MC33067DWR2G	MC74AC240DW	MC74AC652DWR2G
MC33160DW	MC74AC240DWG	MC74ACT240DW
MC33160DWG	MC74AC240DWR2	MC74ACT240DWG
MC33160DWR2	MC74AC240DWR2G	MC74ACT240DWR2
MC33160DWR2G	MC74AC244DW	MC74ACT240DWR2G
MC33163DW	MC74AC244DWG	MC74ACT241DW
MC33163DWG	MC74AC244DWR2	MC74ACT241DWG
MC33163DWR2	MC74AC244DWR2G	MC74ACT241DWR2
MC33163DWR2G	MC74AC245DW	MC74ACT241DWR2G
MC33362DW	MC74AC245DWG	MC74ACT244DW
MC33362DWG	MC74AC245DWR2	MC74ACT244DWG
MC33362DWR2	MC74AC245DWR2G	MC74ACT244DWR2
MC33362DWR2G	MC74AC273DW	MC74ACT244DWR2G
MC33362XDWR2G	MC74AC273DWG	MC74ACT245DW
MC33363ADW	MC74AC273DWR2	MC74ACT245DWG
MC33363ADWG	MC74AC273DWR2G	MC74ACT245DWR2
MC33363ADWR2	MC74AC373DW	MC74ACT245DWR2G
MC33363ADWR2G	MC74AC373DWG	MC74ACT273DW
MC33363BDW	MC74AC373DWR2	MC74ACT273DWG
MC33363BDWG	MC74AC373DWR2G	MC74ACT273DWR2
MC33363BDWR2	MC74AC374DW	MC74ACT273DWR2G
MC33363BDWR2G	MC74AC374DWG	MC74ACT299DW
MC33470DW	MC74AC374DWR2	MC74ACT299DWG
MC33470DWG	MC74AC374DWR2G	MC74ACT299DWR2
MC33470DWR2	MC74AC377DW	MC74ACT299DWR2G
MC33470DWR2G	MC74AC377DWG	MC74ACT373DW
MC33560DW	MC74AC377DWR2	MC74ACT373DWG
MC33560DWR2	MC74AC377DWR2G	MC74ACT373DWR2
MC33560DWR2G	MC74AC540DW	MC74ACT373DWR2G
MC34025DW	MC74AC540DWG	MC74ACT374DW
MC34025DWG	MC74AC540DWR2	MC74ACT374DWG



**Initial Product/Process Change Notification #15621
AFFECTED DEVICE LIST:**

<u>DEVICE</u>	<u>DEVICE</u>	<u>DEVICE</u>
MC74ACT374DWR2	MC74HC273ADWG	MC74HCT273ADW
MC74ACT374DWR2G	MC74HC273ADWR2	MC74HCT273ADWG
MC74ACT377DW	MC74HC273ADWR2G	MC74HCT273ADWR2
MC74ACT377DWG	MC74HC373ADW	MC74HCT273ADWR2G
MC74ACT377DWR2	MC74HC373ADWG	MC74HCT373ADW
MC74ACT377DWR2G	MC74HC373ADWR2	MC74HCT373ADWG
MC74ACT540DW	MC74HC373ADWR2G	MC74HCT373ADWR2
MC74ACT540DWG	MC74HC374ADW	MC74HCT373ADWR2G
MC74ACT540DWR2	MC74HC374ADWG	MC74HCT374ADW
MC74ACT540DWR2G	MC74HC374ADWR2	MC74HCT374ADWG
MC74ACT541DW	MC74HC374ADWR2G	MC74HCT374ADWR2
MC74ACT541DWG	MC74HC4051ADW	MC74HCT374ADWR2G
MC74ACT541DWR2	MC74HC4051ADWG	MC74HCT541ADW
MC74ACT541DWR2G	MC74HC4051ADWR2	MC74HCT541ADWG
MC74ACT564DWR2	MC74HC4051ADWR2G	MC74HCT541ADWR2
MC74ACT564DWR2G	MC74HC4052ADW	MC74HCT541ADWR2G
MC74ACT573DW	MC74HC4052ADWG	MC74HCT573ADW
MC74ACT573DWG	MC74HC4052ADWR2	MC74HCT573ADWG
MC74ACT573DWR2	MC74HC4052ADWR2G	MC74HCT573ADWR2
MC74ACT573DWR2G	MC74HC4053ADW	MC74HCT573ADWR2G
MC74ACT574DW	MC74HC4053ADWG	MC74HCT574ADW
MC74ACT574DWG	MC74HC4053ADWR2	MC74HCT574ADWG
MC74ACT574DWR2	MC74HC4053ADWR2G	MC74HCT574ADWR2
MC74ACT574DWR2G	MC74HC4851ADWR2	MC74HCT574ADWR2G
MC74ACT640DW	MC74HC4851ADWR2G	MC74LCX240DWR2
MC74ACT640DWG	MC74HC540ADW	MC74LCX240DWR2G
MC74ACT640DWR2	MC74HC540ADWG	MC74LCX244DW
MC74ACT640DWR2G	MC74HC540ADWR2	MC74LCX244DWG
MC74ACT646DW	MC74HC540ADWR2G	MC74LCX244DWR2
MC74ACT646DWG	MC74HC541ADW	MC74LCX244DWR2G
MC74ACT646DWR2	MC74HC541ADWG	MC74LCX245DW
MC74ACT646DWR2G	MC74HC541ADWR2	MC74LCX245DWG
MC74ACT652DW	MC74HC541ADWR2G	MC74LCX245DWR2
MC74ACT652DWG	MC74HC573ADW	MC74LCX245DWR2G
MC74ACT652DWR2	MC74HC573ADWG	MC74LCX373DWR2
MC74ACT652DWR2G	MC74HC573ADWR2	MC74LCX373DWR2G
MC74HC240ADW	MC74HC573ADWR2G	MC74LCX374DWR2
MC74HC240ADWG	MC74HC574ADW	MC74LCX374DWR2G
MC74HC240ADWR2	MC74HC574ADWG	MC74LCX540DWR2
MC74HC240ADWR2G	MC74HC574ADWR2	MC74LCX540DWR2G
MC74HC244ADW	MC74HC574ADWR2G	MC74LCX541DW
MC74HC244ADWG	MC74HCT244ADW	MC74LCX541DWG
MC74HC244ADWR2	MC74HCT244ADWG	MC74LCX541DWR2
MC74HC244ADWR2G	MC74HCT244ADWR2	MC74LCX541DWR2G
MC74HC245ADW	MC74HCT244ADWR2G	MC74LCX573DW
MC74HC245ADWG	MC74HCT245ADW	MC74LCX573DWG
MC74HC245ADWR2	MC74HCT245ADWG	MC74LCX573DWR2
MC74HC245ADWR2G	MC74HCT245ADWR2	MC74LCX573DWR2G
MC74HC273ADW	MC74HCT245ADWR2G	MC74LCX574DWR2



**Initial Product/Process Change Notification #15621
AFFECTED DEVICE LIST:**

<u>DEVICE</u>	<u>DEVICE</u>	<u>DEVICE</u>
MC74LCX574DWR2G	MC74VHCT245ADW	NCV4269DWG
MC74LVX240DWR2	MC74VHCT245ADWG	NCV4269DWR2
MC74LVX240DWR2G	MC74VHCT245ADWR2	NCV4269DWR2G
MC74LVX244DWR2	MC74VHCT245ADWRG	NCV4279BDW
MC74LVX244DWR2G	MC74VHCT373ADWR2	NCV4279BDWG
MC74LVX245DWR2	MC74VHCT373ADWRG	NCV4279BDWR2
MC74LVX245DWR2G	MC74VHCT374ADWR2	NCV4279BDWR2G
MC74LVX373DWR2	MC74VHCT374ADWRG	NCV4949DWR2
MC74LVX373DWR2G	MC74VHCT541ADW	NCV4949DWR2G
MC74LVX374DWR2	MC74VHCT541ADWG	NCV51411PWR2
MC74LVX374DWR2G	MC74VHCT541ADWR2	NCV51411PWR2G
MC74LVX4245DW	MC74VHCT541ADWRG	NCV7001DW
MC74LVX4245DWG	MC74VHCT573ADW	NCV7001DWG
MC74LVX4245DWR2	MC74VHCT573ADWG	NCV7001DWR2
MC74LVX4245DWR2G	MC74VHCT573ADWR2	NCV7001DWR2G
MC74LVX541DW	MC74VHCT573ADWRG	NCV7702BDWG
MC74LVX541DWG	MC74VHCT574ADW	NCV7702BDWR2G
MC74LVX573DWR2	MC74VHCT574ADWG	NCV8501PDW100
MC74LVX573DWR2G	MC74VHCT574ADWR2	NCV8501PDW100G
MC74LVX574DWR2	MC74VHCT574ADWRG	NCV8501PDW100R2
MC74LVX574DWR2G	MC75172BDW	NCV8501PDW100R2G
MC74LVXC3245DWR2	MC75172BDWG	NCV8501PDW25
MC74LVXC3245DWRG	MC75172BDWR2	NCV8501PDW25G
MC74VHC240DWR2	MC75172BDWR2G	NCV8501PDW25R2
MC74VHC240DWR2G	MC75174BDW	NCV8501PDW25R2G
MC74VHC244DWR2	MC75174BDWG	NCV8501PDW33
MC74VHC244DWR2G	MC75174BDWR2	NCV8501PDW33G
MC74VHC245DW	MC75174BDWR2G	NCV8501PDW33R2
MC74VHC245DWG	NB100LVEP91DW	NCV8501PDW33R2G
MC74VHC245DWR2	NB100LVEP91DWG	NCV8501PDW50
MC74VHC245DWR2G	NB100LVEP91DWR2	NCV8501PDW50G
MC74VHC373DWR2	NB100LVEP91DWR2G	NCV8501PDW50R2
MC74VHC373DWR2G	NCP3163BPWG	NCV8501PDW50R2G
MC74VHC374DWR2	NCP3163BPWR2G	NCV8501PDW80
MC74VHC374DWR2G	NCP3163PWG	NCV8501PDW80G
MC74VHC540DWR2	NCP3163PWR2G	NCV8501PDW80R2
MC74VHC540DWR2G	NCP5322ADW	NCV8501PDW80R2G
MC74VHC541DWR2	NCP5322ADWR2	NCV8501PDWADJ
MC74VHC541DWR2G	NCP5332ADW	NCV8501PDWADJG
MC74VHC573DWR2	NCP5332ADWR2	NCV8501PDWADJR2
MC74VHC573DWR2G	NCV2574DW-ADJR2	NCV8501PDWADJR2G
MC74VHC574DW	NCV2574DW-ADJR2G	NCV8502PDW100
MC74VHC574DWG	NCV33033DWR2	NCV8502PDW100G
MC74VHC574DWR2	NCV33033DWR2G	NCV8502PDW100R2
MC74VHC574DWR2G	NCV33035DWR2	NCV8502PDW100R2G
MC74VHCT240ADWR2	NCV33035DWR2G	NCV8502PDW25
MC74VHCT240ADWRG	NCV33163DWR2	NCV8502PDW25G
MC74VHCT244ADWR2	NCV33163DWR2G	NCV8502PDW25R2
MC74VHCT244ADWRG	NCV4269DW	NCV8502PDW25R2G



**Initial Product/Process Change Notification #15621
AFFECTED DEVICE LIST:**

<u>DEVICE</u>	<u>DEVICE</u>	<u>DEVICE</u>
NCV8502PDW33	NCV8508DW50G	NLVHC4051ADWR2
NCV8502PDW33G	NCV8508DW50R2	NLVHC541ADWR2
NCV8502PDW33R2	NCV8508DW50R2G	NLVHC541ADWR2G
NCV8502PDW33R2G	NCV8509PDW18	NLVHCT244ADWR2
NCV8502PDW50	NCV8509PDW18G	NLVHCT244ADWR2G
NCV8502PDW50G	NCV8509PDW18R2	SA571D
NCV8502PDW50R2	NCV8509PDW18R2G	SA571DG
NCV8502PDW50R2G	NCV8509PDW25	SA571DR2
NCV8502PDW80	NCV8509PDW25G	SA571DR2G
NCV8502PDW80G	NCV8509PDW25R2	SA572D
NCV8502PDW80R2	NCV8509PDW25R2G	SA572DG
NCV8502PDW80R2G	NCV8509PDW26	SA572DR2
NCV8502PDWADJ	NCV8509PDW26G	SA572DR2G
NCV8502PDWADJG	NCV8509PDW26R2	SA575D
NCV8502PDWADJR2	NCV8509PDW26R2G	SA575DG
NCV8502PDWADJR2G	NCV8518PWG	SA575DR2
NCV8503PW25	NCV8518PWR2G	SA575DR2G
NCV8503PW25G	NCV8800HDW26	SC100LVEL14DWR2
NCV8503PW25R2	NCV8800HDW26G	SC100LVEL14DWR2G
NCV8503PW25R2G	NCV8800HDW26R2	SC33165ADWR2
NCV8503PW33	NCV8800HDW26R2G	SC33165ADWR2G
NCV8503PW33G	NCV8800HDW33	SC54AC240DWR2
NCV8503PW33R2	NCV8800HDW33G	SC68255DWT373R2
NCV8503PW33R2G	NCV8800HDW33R2	SC68255DWT541R2
NCV8503PW50	NCV8800HDW33R2G	SC79192DWR2
NCV8503PW50G	NCV8800HDW50	SC79229DW
NCV8503PW50R2	NCV8800HDW50G	SC79229DWR2
NCV8503PW50R2G	NCV8800HDW50R2	SC79229DWR2G
NCV8503PWADJ	NCV8800HDW50R2G	SC99572DR2G
NCV8503PWADJG	NCV8800HDW75	SCV33033DWR2
NCV8503PWADJR2	NCV8800HDW75G	SCV33033DWR2G
NCV8503PWADJR2G	NCV8800HDW75R2	SCV6806DWR2
NCV8504PW25	NCV8800HDW75R2G	SCV6902DWR2G
NCV8504PW25G	NCV8800SDW26	SCY99035DWPR2G
NCV8504PW25R2	NCV8800SDW26G	SCY99043DWPR2G
NCV8504PW25R2G	NCV8800SDW26R2	SCY99053DWPR2G
NCV8504PW33	NCV8800SDW26R2G	SCY994407DWR2
NCV8504PW33G	NCV8800SDW33	SCY994409DWR2
NCV8504PW33R2	NCV8800SDW33G	SCY996805DWR2
NCV8504PW33R2G	NCV8800SDW33R2	SCY996806DWR2
NCV8504PW50	NCV8800SDW33R2G	SCY996807DWR2
NCV8504PW50G	NE5532D	SCY996902DR2
NCV8504PW50R2	NE5532DG	SCY996902DR2G
NCV8504PW50R2G	NE5532DR2	SG3525ADW
NCV8504PWADJ	NE5532DR2G	SG3525ADWG
NCV8504PWADJG	NE570D	SG3525ADWR2
NCV8504PWADJR2	NE570DG	SG3525ADWR2G
NCV8504PWADJR2G	NE570DR2	TC74LCX245DW
NCV8508DW50	NE570DR2G	TC74LCX245DWR2



Initial Product/Process Change Notification #15621

AFFECTED DEVICE LIST:

DEVICE

TC74VHC573DWR2
TCA0372BDWR2
TCA0372BDWR2G
TCA0372DW
TCA0372DWG
TCA0372DWR2
TCA0372DWR2G
TY40497DW
TY40497DWR2
TY40497DWR2G
TY40497SDW
TY40497SDWG
TY40497SDWR2
TY40497SDWR2G
TYA33560DW